



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003173
INV Date 15/04/2020
Reference CC6/CTI20002216/Qda3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SLG 4537M
Insured Veh. CB 7576M
Claim No. SNM20D200694C02
Policy No. DMB1SN1517701904
Accident Date 07/02/2020
Inspection Date 18/02/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI20002216/Qda3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 15-04-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 7576M	Veh. Inspected	SLG 4537M
Policy No.	DMB1SN1517701904	Coverage (\$)	0.00
Claim No.	SNM20D200694C02	Excess (\$)	0.00
Assign From		Assign Date	18/02/2020

2. Vehicle Particulars & Condition

Make & Model	SUBARU FORESTER 2.0XT	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JF1SJGK85GG077031	Colour	WHITE
Odometer	51573	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R18	BRIDGESTONE	5 mm
L/H Front Tyre	225/55 R18	BRIDGESTONE	5 mm
R/H Rear Tyre	225/55 R18	BRIDGESTONE	5 mm
L/H Rear Tyre	225/55 R18	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/02/2020	Inspection Date	18/02/2020
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 4537M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	CRUMPLED	800.00	800.00
1	REAR BUMPER RETAINER RH	SERVICEABLE	30.00	-
1	REAR BUMPER RETAINER LH	BROKEN	30.00	30.00
1	REAR BUMPER BRACKET CORNER LH	SERVICEABLE	20.00	-
10	REAR BUMPER CLIP @\$5.00	NECESSARY	50.00	30.00
1	REAR TAILAMP	CRUMPLED	500.00	500.00
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	40.00	-
1	REINFORCEMENT	SERVICEABLE	380.00	-
1	REAR /END PANEL GARNISH	SERVICEABLE	80.00	-
1	END PANEL	SERVICEABLE	380.00	-
	LESS 20% DISCOUNT		-	-272.00
			2,310.00	1,088.00
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
			200.00	-
	<u>LABOUR</u>			
	SPRAY PAINTING REAR BUMPER AND INNER PANEL INCLUDE BLEDDING.		500.00	400.00
	REPAIR AND REPLACE AFFECTED ACCIDENT PARTS.		600.00	250.00
	REMOVE AND REFIT REAR BUMPER REVERSE SENSOR .		80.00	30.00
	APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL.		80.00	30.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			-	-
			-	-
			-	-
			1,290.00	740.00
	GRAND TOTAL		3,800.00	1,828.00



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,450.00
---	--	--	-----------------

Report Ref No. CC6/CTI20002216/Qda3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

