



Automotive Repair Centre Pte Ltd
 CO. Reg. No. : 201312913C
 GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
 #05-18, Singapore 757700
 Tel: 64688834 Fax: 64622278
 E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2002-024
 DATE : 7-Feb-2020
 POLICY NO. : PNPV2019-00014052
 VEHICLE REG. NO. : SLG4537M
 VEHICLE MAKE : SUBARU FORESTER 2.0XT CVT AWD SR

TO Motor Claim Department
 China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper / CRU	1	\$ 800.00	\$ 800.00
2	Rear Bumper Retainer RH X SVC	1	\$ 30.00	\$ 30.00
3	Rear Bumper Retainer LH / BR	1	\$ 30.00	\$ 30.00
4	Rear Bumper Bracket Corner LH X SVC	1	\$ 20.00	\$ 20.00
5	Rear Bumper Clip / Nec	10	\$ 5.00	\$ 50.00
6	Rear Bumper Feltgate LH Tail Amp X CRU	1	\$ 500.00	\$ 500.00
7	Rear Bumper Reflector LH X SVC	1	\$ 40.00	\$ 40.00
8	Reinforcement ? X SVC	1	\$ 380.00	\$ 380.00
9	Rear / End Panel Garnish X SVC	1	\$ 80.00	\$ 80.00
10	End Panel ? X SVC	1	\$ 380.00	\$ 380.00
Total Spare Parts				\$ 2,310.00
SPECIAL NETT				
11	Reverse Sensor X NN	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 200.00
LABOUR				
12	Spray Painting Rear Bumper and Inner Panel include Blending	1	\$ 500.00	\$ 500.00
13	Repair and Replace Affected Accident Parts	1	\$ 600.00	\$ 600.00
14	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
15	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 80.00	\$ 80.00
16	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour			\$ 1,290.00	
Amount Before Excess			\$ 3,800.00	
Add GST @ 7%			266.00	
Total Amount Payable			\$ 4,066.00	

Estimate prepared by: Raymond Tan
 The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

Repair day - 3 days
 Lump Sum Repair
 After paint photo
 Sun Pm (Lkk)
 18/02/2020
 TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P = 1,088
 L = 740
 1,828
 - 20%
 1,462.4
 L/S = \$1,450
 3 days

Oi Sun Pin (LKK Auto)

From: raymond@automotiverepaircentre.com.sg
Sent: Tuesday, 17 March, 2020 10:22 AM
To: Oi Sun Pin (LKK Auto)
Cc: shujuan@automotiverepaircentre.com.sg
Subject: RE: SLG4537M - TP Claim against CB7576M *** LKK REF:CC6/CTI20002216/da3

Follow Up Flag: Follow up
Flag Status: Flagged

Dear Sun Pin,

Noted. Thank you.

Best Regards,
Raymond Tan
Automotive Repair Centre Pte Ltd
38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: +65 64688834
Fax: +65 64622278

From: Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>
Sent: Tuesday, 17 March 2020 10:08 AM
To: raymond@automotiverepaircentre.com.sg
Subject: RE: SLG4537M - TP Claim against CB7576M *** LKK REF:CC6/CTI20002216/da3

Dear Raymond,

Finalize amount is \$1,450.00. Repair day 3 days. (L/S, before gst).

Please ignore the amount \$1,462.40.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: raymond@automotiverepaircentre.com.sg [<mailto:raymond@automotiverepaircentre.com.sg>]
Sent: Tuesday, 17 March, 2020 9:58 AM
To: Oi Sun Pin (LKK Auto)
Cc: shujuan@automotiverepaircentre.com.sg
Subject: RE: SLG4537M - TP Claim against CB7576M *** LKK REF:CC6/CTI20002216/da3

Dear Sun Pin,

Calculation confirmed correct and agreed. (3 repair days)

L/S allow figure at \$1,462.40 or \$1,450.00? Please confirm before we issue our LOD.