



# Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C  
GST Reg. No. : 201312913C

# Estimate

38 Woodlands Industrial Park E1  
#05-18, Singapore 757700  
Tel: 64688834 Fax: 64622278  
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2002-024  
DATE : 7-Feb-2020  
POLICY NO. : PNPV2019-00014052  
VEHICLE REG. NO. : SLG4537M  
VEHICLE MAKE : SUBARU FORESTER 2.0XT CVT AWD SR

TO Motor Claim Department  
China Taiping Insurance (Singapore) Pte. Ltd  
3 Anson Road, #15-00 Springleaf Tower  
Singapore 079909  
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

### ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<b>SPARE PARTS</b>				
1	Rear Bumper / CRU	1	\$ 800.00	\$ 800.00
2	Rear Bumper Retainer RH X Svc	1	\$ 30.00	\$ 30.00
3	Rear Bumper Retainer LH / BR	1	\$ 30.00	\$ 30.00
4	Rear Bumper Bracket Corner LH ?	1	\$ 20.00	\$ 20.00
5	Rear Bumper Clip / Nec	10	\$ 5.00	\$ 50.00
6	Rear Tailgate LH Tailamp X / CRU.	1	\$ 500.00	\$ 500.00
7	Rear Bumper Reflector LH X	1	\$ 40.00	\$ 40.00
8	Reinforcement ?	1	\$ 380.00	\$ 380.00
9	Rear / End Panel Garnish X	1	\$ 80.00	\$ 80.00
10	End Panel ?	1	\$ 380.00	\$ 380.00
<b>Total Spare Parts</b>				\$ 2,310.00
<b>SPECIAL NETT</b>				
11	Reverse Sensor X	1	\$ 200.00	\$ 200.00
<b>Total Special Nett</b>				\$ 200.00
<b>LABOUR</b>				
12	Spray Painting Rear Bumper and Inner Panel include Blending	1	\$ 500.00	\$ 500.00
13	Repair and Replace Affected Accident Parts	1	\$ 600.00	\$ 600.00
14	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
15	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 80.00	\$ 80.00
16	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
<b>Total Labour</b>				\$ 1,290.00
<b>Amount Before Excess</b>				\$ 3,800.00
<b>Add GST @ 7%</b>				266.00
<b>Total Amount Payable</b>				\$ 4,066.00

500  
200  
250  
30  
30  
✓

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

Repair day - 3 days.  
Lump Sum Repair  
Alter part photo  
Sun Pm (LKK)  
18/02/2020  
TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: