

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

04/02/20

VEHICLE NO SH 6008Y

MAKE :

MODEL I-40

CHIANG / CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER <i>crd</i>			\$544.50
1	FRONT BUMPER BRACKET TOP RH <i>X nn</i>			\$22.40
1	FRONT BUMPER BRACKET RH <i>xnn</i>			\$24.60
1	FRONT FENDER RH <i>Bv</i>			\$566.30
1	FRONT FENDER LINING RH <i>xnn</i>			\$74.80
1	FRONT WHEEL HUB CAP <i>crd</i>			\$107.10
1	HEAD LAMP ASSY RH <i>Bv</i>			\$1,388.00
1	HEAD LAMP SUPPORT PANEL <i>xnn</i>			\$907.40
SUB TOTAL				\$3,635.10
LESS 20%				\$727.02
\$2,763.68				
Labour Charge				
Panel Beating				\$700.00 <i>\$560</i>
Spray Painting Charge				<i>\$400</i> \$600.00 <i>\$500</i>
Remove/refix frt lh under carriage				\$90.00 <i>xnn</i>
Tuff Kote				\$80.00 <i>\$50</i>
Check Lighting				\$60.00 <i>\$50</i>
TOTAL LABOUR				\$1,460.00
ESTIMATE TOTAL				\$4,428.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

RAM(LKK)
6/2/2020 1245
ram@lkk.com
88672778
(LIS) (3) @ 9/10/20
ATTACHED photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.