

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

04/02/20

VEHICLE NO SH 6008Y

MAKE :

MODEL I-40

CHIANG / CHINA

| Qty                                | Parts Description/ Labour          | Type | Unit Price | Amount                             |
|------------------------------------|------------------------------------|------|------------|------------------------------------|
| 1                                  | FRONT BUMPER COVER <i>crd</i>      |      |            | \$544.50                           |
| 1                                  | FRONT BUMPER BRACKET TOP RH ?      |      |            | \$22.40                            |
| 1                                  | FRONT BUMPER BRACKET RH <i>xnn</i> |      |            | \$24.60                            |
| 1                                  | FRONT FENDER RH <i>BV</i>          |      |            | \$566.30                           |
| 1                                  | FRONT FENDER LINING RH <i>xnn</i>  |      |            | \$74.80                            |
| 1                                  | FRONT WHEEL HUB CAP <i>crd</i>     |      |            | \$107.10                           |
| 1                                  | HEAD LAMP ASSY RH <i>BV</i>        |      |            | \$1,388.00                         |
| 1                                  | HEAD LAMP SUPPORT PANEL <i>xnn</i> |      |            | \$907.40                           |
| <b>SUB TOTAL</b>                   |                                    |      |            | <b>\$3,635.10</b>                  |
| <b>LESS 20%</b>                    |                                    |      |            | <b>\$727.02</b>                    |
| <b>\$2,763.68</b>                  |                                    |      |            |                                    |
| <b>Labour Charge</b>               |                                    |      |            |                                    |
| Panel Beating                      |                                    |      |            | \$700.00 <i>\$560</i>              |
| Spray Painting Charge              |                                    |      |            | <i>\$400</i> \$600.00 <i>\$500</i> |
| Remove/refix frt lh under carriage |                                    |      |            | \$90.00 <i>xnn</i>                 |
| Tuff Kote                          |                                    |      |            | \$80.00 <i>\$50</i>                |
| Check Lighting                     |                                    |      |            | \$60.00 <i>\$50</i>                |
| <b>TOTAL LABOUR</b>                |                                    |      |            | <b>\$1,460.00</b>                  |
| <b>ESTIMATE TOTAL</b>              |                                    |      |            | <b>\$4,428.68</b>                  |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*RAM (LKK)*  
*6/2/2020 1245*  
*ram@lkk.com*  
*88672778*  
*(LKK) (3) @ 9/10/20*  
*ATTACHED photo*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.