

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20002220/KPA3Q2

Date: 16/07/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MCV0000605_01
Claimant Vehicle No :	SCQ26B	Insured Vehicle No :	GBG3422K
Date of Loss:	06/02/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0000297

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCQ26B	Engine No:	27295231443349
Make & Model:	MERCEDES-BENZ E300, 3.0 (A)	Chassis No:	WDD2120542A161681
Reg. Date:	01/03/2010 (Man. Year: 2009)	Odometer:	148593 km
Colour:	Metallic Maroon		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55Z R16	Rear Tyre Size:	225/55Z R16
Front Left Side:	Michelin 3 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	Michelin 3 mm	Rear Right Side:	Michelin 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,948.30	3,948.30	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	1,200.00	250.00	17.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,398.30	5,148.30	250.00	4.63
Approved Total (Overridden) (S\$)		4,100.00		
	(S\$) 5,398.30	4,100.00	1,298.30	24.05
+ GST 7.00/7.00% (S\$)	377.88	287.00	90.88	24.05
Nett Amount (S\$)	5,776.18	4,387.00	1,389.18	24.05
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		4,715.00		

INSPECTION

Date of Assignment: 07/02/2020

Date Inspected: 10/02/2020 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Apr 2020)
Parts: 143	MERCEDES-BENZ E300 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCQ26B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,698.00 FN	*1,698.00 FN
2	1		*REAR BUMPER REINFORCEMENT	Bent	410.00 FN	*410.00 FN
3	1		*REAR BUMPER LOWER SKIRT	Dented / Cut	245.00 FN	*245.00 FN
4	1		*REAR BUMPER CENTRE MOULDING	Necessary	192.00 FN	*192.00 FN
5	2		*REAR BUMPER SIDE MOULDINGS	Necessary	290.00 FN	*290.00 FN
6	1		*REAR LH REVERSE SENSOR	Shorted	305.00 FN	*305.00 FN
7	1		*REAR BOOT LH REFLECTOR	Cut	466.00 FN	*466.00 FN
8	1		*LH TAILLAMP	Cut	655.00 FN	*655.00 FN
9	1		*LH TAILLAMP LOWER RETAINER	Distorted	62.00 FN	*62.00 FN
10	2		*REAR BUMPER CENTRE LOWER RETAINERS	Missing	64.00 FN	*64.00 FN

F=Franchise part. N=NettItemDisc.

Sub Total (S\$)	4,387.00	4,387.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)	438.70	438.70
Total Parts (S\$)	3,948.30	3,948.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,REFLECTORS ,REVERSE SENSOR ,KNOCK & REPAIR BOOT ,REAR PANEL & REALIGN THE SAME	New	600.00	500.00
2	PUTTY & RESPRAY ON REAR BOOT ,REAR PANEL,REAR BUMPER,REAR LH FENDER	New	850.00	700.00
			Gross Labour Cost (\$)	1,450.00
				1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >