

*Kp*  
*Atan Kenneth*  
**Cheng Hoe Motor Pte Ltd**

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

SCQ 26B  
TP/India

M/S : INDIA INT'L INSURANCE PTE LTD  
64 CECIL STREET  
#04/#05 IOB BUILDING  
SINGAPORE 049711

TEL: 63476100  
ATTN: Motor Claim Department

WS Ref: TP/INDIA

Claim Type: Third Party

Accident Date: 06/02/2020

TP Veh Reg No: GBG3422K

FAX: 62247743

*Not Authorized*  
*11 Reg & 4100L*  
*Returning After 4 days*

Estimate No: ES2090119/YISHUN

Date: 07 Feb 2020

Policy No: 2100194478

Veh Reg No: SCQ26B

Make/Model: MERCEDES E 300

Chassis No: WDD2120542A161681

Engine No: 27295231443349

Reg. Date: 01/03/2010

**Estimate Repair Cost to Vehicle No :SCQ26B**

| Description                                                                                                                   | U/Price  | Quantity             | List Price  | Amount      |
|-------------------------------------------------------------------------------------------------------------------------------|----------|----------------------|-------------|-------------|
|                                                                                                                               |          |                      | SS          | SS          |
| <b>Net Price</b>                                                                                                              |          |                      |             |             |
| 1 REAR BUMPER                                                                                                                 | 1,698.00 | 1 PC                 | 1,698.00    |             |
| 2 REAR BUMPER REINFORCEMENT                                                                                                   | 410.00   | 1 PC                 | 410.00      |             |
| 3 REAR BUMPER LOWER SKIRT                                                                                                     | 245.00   | 1 PC                 | 245.00      |             |
| 4 REAR BUMPER CENTRE MOULDING                                                                                                 | 192.00   | 1 PC                 | 192.00      |             |
| 5 REAR BUMPER SIDE MOULDINGS                                                                                                  | 145.00   | 2 PCS                | 290.00      |             |
| 6 REAR LH REVERSE SENSOR                                                                                                      | 305.00   | 1 PC                 | 305.00      |             |
| 7 REAR BOOT LH REFLECTOR                                                                                                      | 466.00   | 1 PC                 | 466.00      |             |
| 8 LH TAILLAMP                                                                                                                 | 655.00   | 1 PC                 | 655.00      |             |
| 9 LH TAILLAMP LOWER RETAINER                                                                                                  | 62.00    | 1 PC                 | 62.00       |             |
| 10 REAR BUMPER CENTRE LOWER RETAINERS                                                                                         | 32.00    | 2 PCS                | 64.00       |             |
|                                                                                                                               |          |                      | 4,387.00    |             |
|                                                                                                                               |          | Less 10%             | 438.70      | 3,948.30    |
| <b>Labour</b>                                                                                                                 |          |                      |             |             |
| 11 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REFLECTORS, REVERSE SENSOR, KNOCK & REPAIR BOOT, REAR PANEL & REALIGN THE SAME | 600.00   | 1 LA                 | 600.00      |             |
| 12 PUTTY & RESPRAY ON REAR BOOT, REAR PANEL, REAR BUMPER, REAR LH FENDER                                                      | 850.00   | 1 LA                 | 850.00      |             |
|                                                                                                                               |          |                      | 1,450.00    | 1,450.00    |
|                                                                                                                               |          | Total                | SS 5,398.30 |             |
|                                                                                                                               |          | Add GST @ 7%         |             | 377.88      |
|                                                                                                                               |          | Total Amount Payable |             | SS 5,776.18 |

*A 5148.30*

*ys #4100V*

**For Cheng Hoe Motor Pte Ltd**

AUTHORISED SIGNATURE