

A.S. REC. BY:

REF: CS/CT1 20002231/ Kyf3n2 Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

From (Person): Adeline Chng of CT2 Date/Time: 10.2.2020 8.02AM

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKB 54142 Insured: SJY 743P

at Workshop m/s Kun Chw motor Tel: 64536256

of 160 Sh Ming Drive #05-08

Policy No: DMCVSRW00002642002 Claim No: SNM 2012 2006791 SJY 743P / ADRESNG

Sum Insured: Excess:

Make of Veh: D.O.A. 6.2.2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 10.2.2020 9.00AM Person Contacted: mdm Lim H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKB 54142 - X
	SJY 743P - X

ASSIGNED BY

REF: C71

ASSIGNMENT

From:

Date:

10-2-2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKB 5414 R

at Workshop m/s Kum On motor

of 160 Sn mng pnc #05-06

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5-6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

my?

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKB 5414 R

Yr Regn:

06, 11

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Hyundai A Elantra G.C 1591

Colour:

h. white

A/C: Insured / Std / NI / NA

Sp. Reading:

178566

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH01H41Cm14173548

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size:

F: Dayton 225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 6 mm

L/Bal. 7 mm

L/Bal. 6 mm

D.O.A. 6/12/20

D.O.I. 10/2/20

Survey held at

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Est not ready

4s \$3800/- (Red \$3407-04, 47%)

RECEIVED 24 MAR 2020

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

24/3/20 Typist

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS SI

Photos

Other:

TOTAL

220

Report Form:

Lump Sum / O/S / G

\$3800/-

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Feb 2020		10 Feb 2020 09:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

Main Claimant:

LIM KOCK KIM, ID: S7536649C

Vehicle Reg. No.:

SKB5414R

Claim Type:

TP / SNM20D200679C02

Vehicle Reg. No. (Insured):

SJY743P

Date of Loss:

06/02/2020 13:00 - :59

Policy/Cover Note No.:

DMCVSNW00002642002

Policy No. (Claimant):

MS006611

Excess:

S\$450.00

Repairer:

Kum Chew Motor Workshop (160 Sin Ming) (HQ) 160 Sin Ming Drive, #05-08 Sin Ming Autocity, 575722 Sin Ming - Tel: 6456 3715

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]

Claimant's Insurer:

Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/02/2020]

Adj Asg. Remarks:

SURVEY REVERT

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Monday, 10 February, 2020 8:42 AM
To: assignments@lkkauto.com
Cc: kumchew1; Claims Dept of CTI
Subject: FW: OUR REF: SNM20D200679/SJY743P/ADELINE & YOUR REF: SKB5414R - ACCIDENT INVOLVING SKB 5414 R & SJY 743 P ON 06/02/2020.

Without Prejudice

Dear LKK

Please refer to below email and liaise with Third Party workshop accordingly.

Thank you.

Adeline Chng
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

-----Original Message-----

From: kumchew1 [mailto:kumchew1@singnet.com.sg]
Sent: Saturday, 8 February 2020 2:39 PM
To: Adeline Chng <adeline.chng@sg.cntaiping.com>
Subject: RE: OUR REF: SNM20D200679/SJY743P/ADELINE & YOUR REF: SKB5414R - ACCIDENT INVOLVING SKB 5414 R & SJY 743 P ON 06/02/2020.

Hi Ms Adeline,

Kindly appoint Mr. Kenneth Kong to pre-repair inspection our insured vehicle.

Thanks & Best Regards,
Mdm Lim

-----Original Message-----

From: Adeline Chng [mailto:adeline.chng@sg.cntaiping.com]
Sent: Friday, February 07, 2020 5:23 PM
To: Claims Dept of CTI; kumchew1@singnet.com.sg

Subject: RE: OUR REF: SNM20D200679/SJY743P/ADELINE & YOUR REF: SKB5414R - ACCIDENT INVOLVING SKB 5414 R & SJY 743 P ON 06/02/2020.

Without Prejudice

Dear Sirs

We refer to the above matter.

Attached PRS letter for your next action.

Thank you.

Adeline Chng
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

-----Original Message-----

From: Claims Dept of CTI

Sent: Friday, 7 February 2020 2:15 PM

To: Adeline Chng <adeline.chng@sg.cntaiping.com>; kumchew1@singnet.com.sg

Subject: OUR REF: SNM20D200679/SJY743P/ADELINE & YOUR REF: SKB5414R - ACCIDENT INVOLVING SKB 5414 R & SJY 743 P ON 06/02/2020.

Dear Adeline,

Please conduct PRS -SKB5414R soonest possible and our Insured has not filed SAS Report.

Officer in charge-Adeline Chng-DID: 6389 6155.

Dear Mdm Lim,

*** kindly quote our reference number when replying.***

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
Tel: 6389 6116
Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com
Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: kumchew1 <kumchew1@singnet.com.sg>
Sent: Friday, February 7, 2020 10:37 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: ACCIDENT INVOLVING SKB 5414 R & SJY 743 P ON 06/02/2020.

Dear Sir/Madam,

Sorry to inform you typo error and our insured owner is Mr Lim Kok Kim.

Kindly arrange pre-repair inspection for our insured vehicle.

Thanks & Best Regards,
Mdm Lim

-----Original Message-----

From: kumchew1 [mailto:kumchew1@singnet.com.sg]
Sent: Friday, February 07, 2020 9:53 AM
To: 'claimsdept@sg.cntaiping.com'
Subject: FW: ACCIDENT INVOLVING SKB 5414 R & SJY 743 P ON 06/02/2020.

Dear Sir,

We are acting on behalf of Mr Low Thiam Siew, the owner of SKB 5414 R in the above matter.

Kindly arrange for pre-repair with the following details;

Venue : Kum Chew Motor Workshop

160, Sin Ming Drive #05-08

Sin Ming Autocity

Singapore 575722.

Contact No. : 64536256.

Thank & Best Regards,
Mdm Lim

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08

SIN MING AUTOCITY, SINGAPORE 575722.

Tel No. : 64536256/64563715 Fax No. : 64557754

E-Mail : kumchew1@singnet.com.sg

GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3, ANSON ROAD #16-00

SPRINGLEAF TOWER, SINGAPORE 079909.

claimsdept@sg.cntaiping.com

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES004815

Date : 06/03/2020

Vehicle Num. : SKB 5414 R

Make/Model : HYUNDAI ELANTRA-2011

Chassis/Eng# : KMHDH41CMCU173548

Accident Date : 18/02/2020

Claim No. :

Reference : KC/TP5414/2002-02

Policy No. :

*Not Withheld**11 Pny 8380di**Recurring After Paint**6 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|-----|-------|------------------------------|---------|--|
| 1. | 1 PC | LIST ITEMS : | | |
| 2. | 1 PC | REAR LID | 1023.90 | |
| 3. | 1 PC | REAR LID LOCK | | |
| 4. | 1 PC | REAR LID LOWER CATCH | | |
| 5. | 1 PC | REAR LID EMBLEM | | |
| 6. | 1 PC | REAR LID 'HYUNDAI' EMBLEM | | |
| 7. | 1 PC | REAR LID 'ELANTRA' EMBLEM | | |
| 8. | 1 PC | REAR LID 'ELITE' EMBLEM | | |
| 9. | 2 PCS | REAR LID HINGE | | |
| 10. | 1 PC | REAR LID RUBBER | | |
| 11. | 2 PCS | REAR LID REFLECTOR | | |
| 12. | 2 PCS | REAR LAMP | e 362 | |
| 13. | 1 PC | REAR BUMPER | 459.40 | |
| 14. | 8 PCS | REAR BUMPER CLIP | | |
| 15. | 1 PC | REAR BUMPER REINFORCEMENT | 323.70 | |
| 16. | 1 PC | REAR BUMPER SPONGE | | |
| 17. | 2 PCS | REAR BUMPER REFLECTOR | | |
| 18. | 2 PCS | REAR BUMPER SIDE RETAINER | | |
| 19. | 1 PC | REAR END PANEL | 453.80 | |
| 20. | 1 PC | REAR END PANEL GARNISH | | |
| 21. | 5 PCS | REAR END PANEL GARNISH CLIPS | | |

List TotalS\$:

20.00% Discount S\$:

SPECIAL NETT ITEMS :

- | | | | | |
|----|-------|---------------------|--|--|
| 1. | 1 SET | REAR REVERSE SENSOR | | |
|----|-------|---------------------|--|--|

Special Nett Total S\$:

Ad	1,388.40	✓
Ref	191.70	✓
R	24.00	X
Ad	41.00	✓
Ad	49.60	✓
Ad	57.30	✓
Ad	43.70	✓
Ad	274.80	X
Ad/Ad	137.40	✓
Ad/Ad	298.00	508.12
Ad/Ad	362.00	✓
Ad	724.00	✓
Ad	549.40	✓
Ad	101.60	✓
Ad	12.70	✓
Ad	383.80	✓
Ad	149.80	X
Ad/Ad	47.00	✓
Ad/Ad	53.60	X
Ad/Ad	585.40	✓
Ad/Ad	87.10	✓
Ad	9.80	✓
	5,658.80	
	1,131.76	
	4,527.04	

Ad	280.00	200.00
	280.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE / ...

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
 SIN MING AUTOCITY, SINGAPORE 575722.
 Tel No. : 64536256/64563715 Fax No. : 64557754
 E-Mail : kumchew1@singnet.com.sg
 GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3, ANSON ROAD #16-00
 SPRINGLEAF TOWER, SINGAPORE 079909.
 claimsdept@sg.cntaiping.com
 Attention : Motor Claim Department
 Contact : 63896111 Fax No. : 62221033

Estimate : ES004815

Date : 06/03/2020
 Vehicle Num. : SKB 5414 R
 Make/Model : HYUNDAI ELANTRA-2011
 Chassis/Eng# : KMHDH41CMCU173548
 Accident Date : 18/02/2020
 Claim No. :
 Reference : KC/TP5414/2002-02
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

TO PULL, KNOCK ON R/H ACCIDENT PORTION & CHANGE
 THE ABOVE PART.

850.00

TO SPRAY & PAINT ON ACCIDENT PORTION.

1,200.00

TO ANTI-RUST REAR AFFECTED AREAS.

120.00

TO CHECK WIRING FUNCTION.

80.00

TO DISMANTLE & REPLACE 1 SET REVERSE SENSOR.

150.00

Labour Total S\$:

2,400.00

SingDollars : Seven Thousand Two Hundred Seven & Cents Four Only

Total S\$: 7,207.04

=====

KUM CHEW MOTOR WORKSHOP

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002231/KYF3N2

Date: 30/03/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00002642002
Claimant Vehicle No :	SKB5414R	Insured Vehicle No :	SJY743P
Date of Loss:	06/02/2020	Nature of Claim:	TP
		Claim No:	SNM20D200679C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB5414R	Engine No:	G4FGBU237716
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	KMHDH41CMCU173548
Reg. Date:	09/06/2011 (Man. Year: 2011)	Odometer:	178546 km
Colour:	Metallic White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Dayton 7 mm	Rear Left Side:	Dayton 6 mm
Front Right Side:	Dayton 7 mm	Rear Right Side:	Dayton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,807.04	3,717.14	1,089.90	22.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,330.00	1,070.00	44.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,207.04	5,047.14	2,159.90	29.97
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	7,207.04	3,800.00	3,407.04	47.27
+ GST 7.00/7.00% (S\$)	504.49	266.00	238.49	47.27
Nett Amount (S\$)	7,711.53	4,066.00	3,645.53	47.27

INSPECTION

Date of Assignment:	10/02/2020	
Date Inspected:	10/02/2020	Inspected At: Kum Chew Motor Workshop (160 Sin Ming) (HQ) 160 Sin Ming Drive, #05-08 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2020)
Parts: 143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB5414R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LID	Bent	1,388.40 FL	*1,023.90 FL
2	1		*REAR LID LOCK	Dented	191.70 FL	*191.70 FL
3	1		*REAR LID LOWER CATCH	Repair	24.00 FL	*- FL
4	1		*REAR LID EMBLEM	Necessary	41.00 FL	*41.00 FL
5	1		*REAR LID HYUNDAI EMBLEM	Necessary	49.60 FL	*49.60 FL
6	1		*REAR LID ELANTRA EMBLEM	Necessary	57.30 FL	*57.30 FL
7	1		*REAR LID ELITE EMBLEM	Necessary	43.70 FL	*43.70 FL
8	2		*REAR LID HINGE	Repair	274.80 FL	*- FL
9	2		*REAR LID REFLECTOR	Mtg Cracked	596.00 FL	*596.00 FL
10	2		*REAR LAMP	Mtg Cracked	724.00 FL	*724.00 FL
11	1		*REAR BUMPER	Bent	549.40 FL	*459.40 FL
12	8		*REAR BUMPER CLIP	Necessary	101.60 FL	*101.60 FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	383.80 FL	*323.70 FL
14	1		*REAR BUMPER SPONGE	No such part	149.80 FL	*- FL
15	2		*REAR BUMPER REFLECTOR	Mtg Cracked	94.00 FL	*94.00 FL
16	2		*REAR BUMPER SIDE RETAINER	Serviceable	107.20 FL	*- FL
17	1		*REAR END PANEL	Bent	585.40 FL	*453.80 FL
18	1		*REAR END PANEL GARNISH	Mtg Distorted	87.10 FL	*87.10 FL
19	5		*REAR END PANEL GARNISH CLIPS	Necessary	49.00 FL	*49.00 FL
20	1		*REAR LID RUBBER (50%)	Dented/Cut	128.80 FS	*80.50 FS
21	1		*SET REAR REVERSE SENSOR	Dented	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,906.60	4,576.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,099.56	859.16
Total Parts (\$\$)	4,807.04	3,717.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PULL,KNOCK ON R/H ACCIDENT PORTION & CHANGE THE ABOVE PART	New	850.00	600.00
2	TO SPRAY & PAINT ON ACCIDENT PORTION	New	1,200.00	600.00
3	TO ANTI-RUST REAR AFFECTED AREAS	New	120.00	60.00
4	TO CHECK WIRING FUNCTION	New	80.00	20.00
5	TO DISMANTLE & REPLACE 1 SET REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (S\$)			2,400.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >