

ASS. REC. BY:

REF: C71

ASSIGNMENT

From:

Date: 14.2.2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 4857C

at Workshop m/s Xin Hua workshop

of 23 Kaki Burnt Ave 4 #04-01

Insured:

Policy No.

Claims No.

Sum Insured: Excess: \$350.00

(Client's Record)

Make of Veh: 5pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$55K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA (REV) REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

GBH 4857C

Yr Regn:

18 Jun 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

c.c 2982

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

24931

T/Radio: Insured / Std / NI / NA

Eng/No:

ITFAT35Y 20K209795

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/75 R15

R: 155 R12

BSI DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

14-02-20

Survey held at

w/s

5pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/2

Revert via Merimen

18/2

Approval Mandate by Alfred Toh

18/2

Sent email to workshop Authorise.

16/3

PIP \$5346-00 confirm with Eric
(Red \$8135-80, 60%)

RECEIVED 17 MAR 2020

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 6

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2)

17/3/20 Typist

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

220

Rep. Format:

Lump Sum / L.B.I. /

PIP \$5346-00

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 17 Feb 2020

Preliminary Advice

Vehicle No	: GBH4857C	Accident Date	: 06/02/2020
Make	: TOYOTA DYNA 150	Policy No.	: DMCVSN18189219011
Assignment Date	: 10/02/2020	Excess	: S\$350.00
Date of Inspection	: 14/02/2020	Est. Duration of Repair	: 6.00
Inspection At	: XIN HUA WORKSHOP PTE LTD (HQ) 23 KAKI BUKIT AVE 4 #04-01 SINGAPORE 415933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,481.80
Revised Amount	:S\$	4,899.40
Check Items (Estimated)	:S\$	5,219.90
Total	:S\$	10,119.30

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	24,976.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,024.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2020		10 Feb 2020 11:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	M/S HOMAX AIR-CONDITIONING ENTERPRISE PTE LTD, Co. Reg. No.: 200010567C								
Vehicle Reg. No.:	GBH4857C	Date of Loss:	06/02/2020 11:00 - :59						
Claim Type:	OD / SNM20D200665C02	Policy/Cover Note No.:	DMCVSN18189219011 (Comprehensive)						
		Excess:	S\$350.00						
Repairer:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01, 415933 Kaki Bukit - Tel: 68441985 8292 5595								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/02/2020]								
Driver/Custodian:	PUGAZHENTHI BALASUBRAMANIAN (26 / Male) , NRIC: G5443851L, Tel: +6593536360 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All	Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***GBH4857C (SNM20D200665C01/TKL)**

OD

Feb 6 2020 11:00AM

[M/S HOMAX AIR-CONDITIONING ENTERPRISE PTE LTD]

Xin Hua Workshop Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **18/02/2020 12:10 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$\$10119.30) - GBH4857C - Claim Handler: Tan Kah Leong

Approved:10119.30:Please proceed to authorize repairs UP TO \$10,119.30 BEFORE Excess of \$350.00

DOCUMENTS SUMMARY

There are no documents.

Summer Lee (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Monday, 10 February, 2020 11:03 AM
To: xinhuaworkshop@gmail.com; 'assignments'
Subject: RE: OUR REF: SNM20D200665/GBH4857C/TKL & YOUR REF: GBH4857C -OD | Accident involving GBH 4857C and GX 2692E | DOA-06/02/2020

Without Prejudice

Dear LKK,

Please assists to conduct survey for the above matter.

Dear Eric,

Please forward a copy of the estimate quotation for the above.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 7175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Monday, February 10, 2020 10:40 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; xinhuaworkshop@gmail.com
Subject: OUR REF: SNM20D200665/GBH4857C/TKL & YOUR REF: GBH4857C -OD | Accident involving GBH 4857C and GX 2692E | DOA-06/02/2020

Dear Kah Leong,

Please conduct OWN DAMAGED CLAIM -GBH4857C soonest possible

Officer in charge-Kah Leong-DID: 6389 6193.

Dear Eric,

*** kindly quote our reference number when replying.***

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
Tel: 6389 6116
Fax (65) 6224 7175 / 6224 7478
Email : claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Xin Hua <xinhuaworkshop@gmail.com>
Sent: Friday, February 7, 2020 5:02 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: OD | Accident Involving GBH 4857C and GX 2692E | DOA-06/02/2020

Greetings,

We are instructed by our client/your insured **HOMAX AIR-CONDITIONING ENTERPRISE PTE LTD** to notify you that they have authorized us to carry out repair work on their vehicle registration no. **GBH 4857C**.

Before our client/we proceed to repair the damaged vehicle, please let us know whether you would like to conduct a pre-repair survey of the vehicle.

Please note that this case is **OD**.

Thanks & Regards,
Eric
Xin Hua Workshop Pte Ltd

HOTTEST NEW CAR
PROMOTIONS

Honda Shuttle

Downpayment \$3,888! Monthly Instalment \$900!
Private Hirer Loan Available! Ready Stock with VAC
Ready! Contact us for more info!

DON'T MISS OUT!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Small 85 Cooper 2.2L VPS (Quattro) 4x4



Small 85 Cooper 2.2L VPS (Quattro) 4x4

Direct Owner

PRIME MOTOR & LEASING

IMPROVE YOUR CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted

20 results/page

8 vehicles

Toyota Dyna

Advanced Search

	Model	Price	Depreciation	Eng Type	Eng Cap	Mileage	Veh Type	
Search Selection	Toyota Dyna	Any	Any	2018	Any	Any	Any	Available
	Toyota Dyna 150 3.0M	\$55,848	\$6,440 /yr	09-Oct-2018	2,982 cc	-	Truck	Available
Fuel Type: Diesel Still Under Warranty By Borneo Motor, Super Low Mileage, Condition Like New! 3 Day Delivery, Loan Up To 100%, Flexible In House Loan! Super High Trade In! Call Now To View And Test Drive.								
ABWIN Bus Pte Ltd								
Posted: 10-Feb-2020 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna 150 3.0M	\$53,800	\$6,450 /yr	11-Jun-2018	2,982 cc	31,130 km	Truck	Available
Fuel Type: Diesel 3 Months Warranty! As Low As \$714/Month. Flexible Packages With 100% Loan Available! Almost Like New Unit That Equipped With 6 Foot Box To Cater For Maximum Storage Space. Easy Access For Loading/Unloading With Both Side Sliding Doors. Up And Ready To Kic...								
Car (S) Pte Ltd								
Posted: 10-Feb-2020 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna 150 3.0M	\$55,800	\$6,800 /yr	26-Apr-2018	2,982 cc	39,000 km	Truck	Available
Fuel Type: Diesel Confirm Cheapest In Market, No Hidden Costs. Tip Top Condition. New Improve Diesel Engine By Toyota Super Low Fuel Consumption, Most Reliable Model For High Mileage User, Heavy Duty, Viewing By Appointment Only, Please Call For A Friendly No-Obligation Discuss...								
Net Link Partners Pte Ltd								
Posted: 07-Feb-2020 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna 150 3.0M	\$54,800	\$6,440 /yr	15-Aug-2018	2,982 cc	39,000 km	Truck	Available
Fuel Type: Diesel Not Used In Construction! Pristine Condition! Regularly Serviced And Well Maintained By Borneo Motors. Warranty Under Borneo Motors! Workshop/STA Evaluation Welcome. 90% Loan Of The Car Price Available With Lowest Interest Rates From 2.28%. Trade In Welcome...								
Posted: 05-Feb-2020 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Providence Automobile Pte Ltd - Specialist for Toyota Car repair, servicing & maintenance Providence Automobile is specializing in servicing & maintenance for Hybrid cars, a one-stop motoring service for all your vehicles' needs. More info about this shop							
	Toyota Dyna 150 3.0M	\$55,800	\$6,650 /yr	02-Jul-2018	2,982 cc	-	Truck	Available
Fuel Type: Diesel One Owner Only, Low Mileage, Owner Spare Vehicle, Sell Due To Underutilized, High Trade In, High Loan Available, Call Us Now.								
SG Motor Link Pte Ltd								
Posted: 30-Jan-2020 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Toyota Dyna 150 3.0M	\$51,000	\$6,320 /yr	06-Mar-2018	2,982 cc	18,000 km	Truck	Available
Fuel Type: Diesel Genuine Low Mileage! Pristine Condition! Warranty Under Borneo Motors! Workshop/STA Evaluation Welcome. 100% Loan Of The Car Price Available With Lowest Interest Rates From 2.28%. Call Now To Book An Appointment To View This Beauty. Viewing Strictly Appoin...								
Posted: 30-Jan-2020 Tags: 2018 Toyota Dyna, 2018 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota								
	Tc	\$55,800	\$6,670 /yr	20-Jun-2018	2,982 cc	24,749 km	Truck	Available
Fuel T								

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	567C
Vehicle Details	
Vehicle No.:	GBH4857C
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2773479
Chassis No.:	JTFAT35Y20K209795
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	18 Jun 2018
First Registration Date:	18 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jun 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$29,902.00
COE Rebate Amount:	\$24,918.00
Total Rebate Amount:	\$24,918.00

The information contained herein is correct as at 17 Feb 2020

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	567C

Vehicle Details

Vehicle No.:	GBH4857C
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2773479
Chassis No.:	JTFAT35Y20K209795
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	18 Jun 2018
First Registration Date:	18 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$1,355.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	17 Jun 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$29,902.00
COE Rebate Amount:	\$24,976.00
Total Rebate Amount:	\$24,976.00

The information contained herein is correct as at 10 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/02/2020 12:07
Date Of Accident	06/02/2020 11:40
Exact Location Of Accident	SLIP RD PAYA LEBAR RD TWDS PIE (CHANGI)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH4857C
Insured/Policyholder	
Name Of Registered Owner	M/S HOMAX AIR-CONDITIONING ENTERPRISE PTE LTD
Co Reg No	2XXXXX567C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67433143

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 5MT
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1818921901
Cover Note Number	

Driver

Name of Driver	PUGAZHENTHI BALASUBRAMANIAN
NRIC No	GXXXX851L
Date Of Birth	27/08/1993
Occupation	OUTDOOR
Date Of Driving Pass	04/12/2017
Driving Experience	2 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93536360
Fax Number	
Contact Number	OFFICE-93536360
Email Address	NOEMAIL

Address	3025 UBI ROAD 3 #04-137 KAMPONG UBI INDUSTRIAL ESTATE
Postcode	408653
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX2692E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJG9X
-----------------------------	-------

Vehicle Make/Model/Colour:

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

THANGASAMY FRANCIS PRINCE ANAND

NRIC/Passport Number

SXXXX392I

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **CORRECTLY** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **rescind policy benefits**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;


Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Person's Signature
Name
SPIC/ID No

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Hufemant.

DECLARATION

I/We declare the foregoing statements are true in every respect.

Policyholder's Signature:
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

Accident Sketch Plan

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG THE STATED VENUE. SUDDENLY VEHICLE B JAMMED BRAKE. I COULDN'T BRAKE MY VEHICLE IN TIME AND HIT ONTO VEHICLE B REAR PORTION. THERE WERE 3 VEHICLES INVOLVED IN THIS ACCIDENT.

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933
Tel : 6844-1985 Fax : 6844-5185
Reg : 201838521G

Repair Estimate

Date : 10/02/2020

Reference: TOYOTA
Make: DYNA

To Whom It May Concern

Dear Sir,

RE: VEHICLE : GBH4857C
CHASSIS NO.: JTFAT35Y20K209795
ENGINE NO.: 1KD2773479

Name of insured : HOMAX AIR-CONDITIONING ENTERPRISE PTE LTD
Date of accident.: 06/02/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BUMPER / BT	\$ 304.00
2	1	FRT BUMPER STAY RH / 50T	\$ 127.00
3	1	FRT BUMPER STAY LH / 50T	\$ 127.00
4	1	FRT BUMPER EXTENSION MOUNTING	\$ 36.00
5	1	FRT BUMPER FOG LAMP COVER RH X NN	\$ 38.00
6	1	FRT BUMPER FOG LAMP COVER LH X NN	\$ 38.00
7	1	FRT RADIATOR GRILLE / Cut	\$ 241.00
8	1	FRT RADIATOR GRILLE BRACKET X NN	\$ 38.00
9	1	FRT RADIATOR GRILLE TOYOTA LOGO / AC.	\$ 44.00
10	1	FRT DYNA EMBLEM / AC.	\$ 35.00
11	1	FRT WINDSCREEN MLDG / AC.	\$ 121.00
12	1	FRT PANEL / BUC.	\$ 508.00
13	1	FRT CORNER PANEL RH X NN	\$ 120.00
14	1	FRT CORNER PANEL LH / MIS.	\$ 120.00
15	1	FRT CORNER PANEL BRACKET LH / BT.	\$ 54.00
16	1	FRT PANEL TOP COVER / Cut.	\$ 165.00
17	1	FRT PANEL TOP COVER BRACKET LH X NN	\$ 38.00
18	1	FRT CHASSIS PANEL CROSSMEMBER X Repair.	\$ 139.00
19	1	RH HEADLAMP X AC.	\$ 406.00
20	1	LH HEADLAMP X AC.	\$ 406.00
21	1	LH WING MIRROR ASSY	\$ 279.00
22	1	LH WING MIRROR GROMMET	\$ 25.00
23	1	LH WING MIRROR HOLDER	\$ 44.00
24	1	LH WING MIRROR FOLDER MOTOR	\$ 304.00
25	1	FRT HORN X	\$ 76.00
26	1	A/C FAN BLOWER ASSY X NN	\$ 2,265.00
27	1	A/C CONDENSER X	\$ 698.00
28	1	RADIATOR X	\$ 914.00
29	1	FRT DOOR LH X Repair.	\$ 825.00
30	1	FRT DOOR HINGE UPP LH X	\$ 44.00
31	1	FRT DOOR HINGE LOW LH X NN	\$ 44.00
32	1	FRT STEP GARNISH LH X	\$ 165.00

Parts Total: \$ 8,788.00
Cost + 10%: \$ 878.80
Total : \$ 9,666.80

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement	\$ 1,200.00
2	Carry out spray painting on accident affected area, FRT BUMPER, FRT PANEL, FRT CORNER PANEL RH, FRT CORNER PANEL LH, FRT DOOR LH, FRT DOOR RH	\$ 1,200.00
3	To disconnect wire harness of electrical component to facilitate	\$ 100.00
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 180.00
5	To remove and refit radiator and conduct pressure test	\$ 80.00
6	To remove and replace dashboard system and internal wiring	\$ 600.00
7	To refocus headlamp	\$ 80.00
8	Remove and refit front windscreen	\$ 180.00

600.
600.
30.
8 {NN
180.
x NN
100.

Labour Total : \$ 3,620.00

Others

No.	Other Description	Price (SGD)
1	10 FRT BUMPER CLIP	\$ 30.00
2	10 FRT RADIATOR GRILLE CLIP	\$ 30.00
3	10 FRT CORNER PANEL CLIP	\$ 30.00
4	1 FRT NUMBER PLATE	\$ 45.00
5	2 COMPANY ADDRESS STICKER	\$ 60.00

Other Total: \$ 195.00

TOTAL: \$ 13,481.80

GRAND TOTAL : \$ 13,481.80

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Eric Tan
HP: 8222 8966

8292 5595 kelvin.

12/3/2020

6 Days.

part by part.

before part photos.

Gino Qian - 82880282

14/2/2020.

excess \$350.

Not Authorised.

Uth Auto Consultants hence notify the Repairer of the following:

- To resurvey, before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6544-1985 Fax : 6544-5185

Reg : 201838521G

Repair Estimate

Date : 10/02/2020

Reference: TOYOTA

Make: DYNA

To Whom It May Concern

Dear Sir,

RE: VEHICLE : GBH4857C

CHASSIS NO.: JTFAT35Y20K209795

ENGINE NO.: 1KD2773479

Name of insured : HOMAX AIR-CONDITIONING ENTERPRISE PTE LTD

Date of accident: 06/02/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BUMPER / 67	\$ 304.00
2	1	FRT BUMPER STAY RH / 40T	\$ 127.00
3	1	FRT BUMPER STAY LH / 40T	\$ 127.00
4	1	FRT BUMPER EXTENSION MOUNTING / 2H M	\$ 36.00
5	1	FRT BUMPER FOG LAMP COVER RH / 2H M	\$ 38.00
6	1	FRT BUMPER FOG LAMP COVER LH / 2H M	\$ 38.00
7	1	FRT RADIATOR GRILLE / Cut	\$ 241.00
8	1	FRT RADIATOR GRILLE BRACKET / 2H M	\$ 38.00
9	1	FRT RADIATOR GRILLE TOYOTA LOGO / 2H M	\$ 44.00
10	1	FRT DYNA EMBLEM / 2H M	\$ 35.00
11	1	FRT WINDSCREEN MLDG / 2H M	\$ 121.00
12	1	FRT PANEL / 2H M	\$ 508.00
13	1	FRT CORNER PANEL RH / X	\$ 120.00
14	1	FRT CORNER PANEL LH / 2H M	\$ 120.00
15	1	FRT CORNER PANEL BRACKET LH / 2H M	\$ 54.00
16	1	FRT PANEL TOP COVER / 2H M	\$ 165.00
17	1	FRT PANEL TOP COVER BRACKET LH / X	\$ 38.00
18	1	FRT CHASSIS PANEL CROSSMEMBER / X Repair	\$ 139.00
19	1	RH HEADLAMP / 2H M	\$ 406.00
20	1	LH HEADLAMP / 2H M	\$ 406.00
21	1	LH WING MIRROR ASSY /	\$ 279.00
22	1	LH WING MIRROR GROMMET /	\$ 25.00
23	1	LH WING MIRROR HOLDER /	\$ 44.00
24	1	LH WING MIRROR FOLDER MOTOR /	\$ 304.00
25	1	FRT HORN / 2H M	\$ 76.00
26	1	A/C FAN BLOWER ASSY / 2H M	\$ 2,265.00
27	1	A/C CONDENSER / 2H M	\$ 698.00
28	1	RADIATOR / 2H M	\$ 914.00
29	1	FRT DOOR LH / X Repair	\$ 825.00
30	1	FRT DOOR HINGE UPP LH / X	\$ 44.00
31	1	FRT DOOR HINGE LOW LH / X	\$ 44.00
32	1	FRT STEP GARNISH LH / X	\$ 165.00

Parts Total: \$ 8,788.00

Cost + 10%: \$ 878.80

Total : \$ 9,666.80

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20002240/GYF3N2

Date: 23/03/2020

REFERENCE

Insured/Claimant: M/S HOMAX AIR-CONDITIONING
ENTERPRISE PTE LTD

Policy No: DMCVSN18189219011

Date of Loss: 06/02/2020

Nature of
Claim: OD

Claim
No: SNM20D200665C01/TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH4857C	Engine No:	1KD2773479
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y20K209795
Reg. Date:	18/06/2018 (Man. Year, 2017)	Odometer:	44931 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$55,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75R15	Rear Tyre Size:	155R12
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,861.80	3,836.00	6,025.80	61.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,620.00	1,510.00	2,110.00	58.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,481.80	5,346.00	8,135.80	60.35
- Excess (\$\$)	350.00	350.00	0.00	0.00
(\$\$)	13,131.80	4,996.00	8,135.80	61.95
+ GST 7.00/7.00% (\$\$)	919.23	349.72	569.51	61.96
Nett Amount (\$\$)	14,051.03	5,345.72	8,705.31	61.95

INSPECTION

Date of Assignment: 10/02/2020

Date Inspected: 14/02/2020 Inspected At:

Xin Hua Workshop Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01
Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 23 Mar 2020)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH4857C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER (WCP)	Bent	304.00 F	*304.00 F
2	1		*FRT BUMPER STAY RH (WCP)	Bent	127.00 F	*127.00 F
3	1		*FRT BUMPER STAY LH (WCP)	Bent	127.00 F	*127.00 F
4	1		*FRT BUMPER EXTENSION MOUNTING (WCP)	Not Necessary	36.00 F	*- F
5	1		*FRT BUMPER FOG LAMP COVER RH (WCP)	Not Necessary	38.00 F	*- F
6	1		*FRT BUMPER FOG LAMP COVER LH (WCP)	Not Necessary	38.00 F	*- F
7	1		*FRT RADIATOR GRILLE (WCP)	Cut	241.00 F	*241.00 F
8	1		*FRT RADIATOR GRILLE BRACKET (WCP)	Not Necessary	38.00 F	*- F
9	1		*FRT RADIATOR GRILLE TOYOTA LOGO (WCP)	Necessary	44.00 F	*44.00 F
10	1		*FRT DYNA EMBLEM (WCP)	Necessary	35.00 F	*35.00 F
11	1		*FRT WINDSCREEN MLDG (WCP)	Necessary	121.00 F	*121.00 F
12	1		*FRT PANEL (WCP)	Buckled	508.00 F	*508.00 F
13	1		*FRT CORNER PANEL RH (WCP)	Not Necessary	120.00 F	*- F
14	1		*FRT CORNER PANEL LH (WCP)	Missing	120.00 F	*120.00 F
15	1		*FRT CORNER PANEL BRACKET LH (WCP)	Bent	54.00 F	*54.00 F
16	1		*FRT PANEL TOP COVER (WCP)	Cut	165.00 F	*165.00 F
17	1		*FRT PANEL TOP COVER BRACKET LH (WCP)	Not Necessary	38.00 F	*- F
18	1		*FRT CHASSIS PANEL CROSSMEMBER (WCP)	Repair	139.00 F	*- F
19	1		*RH HEADLAMP (WCP)	Broken	406.00 F	*406.00 F
20	1		*LH HEADLAMP (WCP)	Cracked	406.00 F	*406.00 F
21	1		*LH WING MIRROR ASSY (WCP)	Missing	279.00 F	*279.00 F
22	1		*LH WING MIRROR GROMMET (WCP)	Missing	25.00 F	*25.00 F
23	1		*LH WING MIRROR HOLDER (WCP)	Missing	44.00 F	*44.00 F
24	1		*LH WING MIRROR FOLDER MOTOR (WCP)	Missing	304.00 F	*304.00 F
25	1		*FRT HORN (WCP)	Not Necessary	76.00 F	*- F
26	1		*A/C FAN BLOWER ASSY (WCP)	Not Necessary	2,265.00 F	*- F
27	1		*A/C CONDENSER (WCP)	Not Necessary	698.00 F	*- F
28	1		*RADIATOR (WCP)	Not Necessary	914.00 F	*- F
29	1		*FRT DOOR LH (WCP)	Repair	825.00 F	*- F
30	1		*FRT DOOR HINGE UPP LH (WCP)	Not Necessary	44.00 F	*- F
31	1		*FRT DOOR HINGE LOW LH (WCP)	Not Necessary	44.00 F	*- F
32	1		*FRT STEP GARNISH LH (WCP)	Not Necessary	165.00 F	*- F
33	10		*FRT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
34	10		*FRT RADIATOR GRILLE CLIP	Necessary	30.00 FS	*30.00 FS
35	10		*FRT CORNER PANEL CLIP	Necessary	30.00 FS	*30.00 FS
36	1		*FRT NUMBER PLATE	Bent	45.00 FS	*45.00 FS
37	1		*COMPANY ADDRESS STICKER	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNetL.

Sub Total (\$\$)	8,983.00	3,505.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	878.80	331.00
Total Parts (\$\$)	9,861.80	3,836.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT	New	1,200.00	600.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.FRT BUMPER,FRT PANEL,FRT CORNER PANEL RH,FRT CORNER PANEL LH,FRT DOOR LH,FRT DOOR RH	New	1,200.00	600.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE	New	100.00	30.00
4	TO REMOVE AND REFIT AIRCON CONDENSOR,VACUUM,REFILL AND CHECK AIR CON GAS SYSTEM	New	180.00	0.00
5	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
6	TO REMOVE AND REPLACE DASHBOARD SYSTEM AND INTERNAL WIRING	New	600.00	180.00
7	TO REFOCUS HEADLAMP	New	80.00	0.00
8	REMOVE AND REFIT FRONT WINDSCREEN	New	180.00	100.00
Gross Labour Cost (S\$)			3,620.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >