

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

not Adhish
10/2/20
1/5 6150
5 days.

VEHICLE NO: SJS 1530L

QTY	PARTICULAR			
1 PCS	REAR WINDSCREEN MOULDING		118.50	—
1 PCS	TAILGATE	1288.50	1455.20	—
1 PCS	TAILGATE REAR LOGO	35.20	68.50	—
1 PCS	TAILGATE 'FREED' EMBLEM		66.20	—
1 PCS	TAILGATE OUTER HANDLE		341.10	x
1 PCS	TAILGATE INNER TRIM BOARD	433.20	745.20	—
1 PCS	TAILGATE INNER TRIM BOARD CLIPS		50.00	—
1 PCS	TAILGATE WEATHERSTRIP		299.00	—
1 PCS	TAILGATE INNER LOCK	265.00	366.50	—
1 PCS	TAILGATE INNER PULLPOCKET		66.50	—
1 PCS	REAR BUMPER	685.20	1050.00	—
2 PCS	REAR BUMPER SIDE RETAINERS @\$35.00		70.00	x
1 SET	REAR BUMPER CLIPS		50.00	—
2 PCS	REAR BUMPER BRACKETS @\$68.50		137.00	x
1 PCS	REAR END PANEL	622.30	655.10	—
1 PCS	REAR END PANEL TOP GARNISH		288.20	—
1 PCS	REAR FLOOR PANEL		1420.00	x
1 PCS	REAR FLOOR PANEL TOP CLOTH		288.20	x
2 PCS	TAILLAMPS @\$380.20		760.40	—
2 PCS	REAR FENDER INNER TRIM BOARDS @\$455.10		910.20	—
1 PCS	REAR EXHAUST		662.30	x
			9,868.10	
	S.NETT			
1 PCS	REAR WINDSCREEN SEALANT		50.00	40
1 PCS	REAR LICENCE PLATE W/HOLDER		50.00	40
1 PCS	REAR WINDSCREEN INNER SEAL		50.00	40
1 SET	REAR FLOOR PANEL INSULATOR		280.00	x
1 SET	REAR BUMPER REVERSE SENSOR		280.00	200
1 SET	REAR REVERSE CAMERA		480.00	380
	LABOUR CHARGES			
	TO CHECK WIRING		80.00	30
	TO DISMANTLE & REPLACING REAR REVERSE SENSOR		80.00	50
	TO DISMANTLE & REFIX REAR WINDSCREEN		150.00	120
	TO TRANSFER TAILGATE COMPONENTS		100.00	60
	TO DISMANTLE & REFIX CUSHION UPHOLSTREY		120.00	80
	TO DISMANTLE & REFIX REAR EXHAUST		100.00	60
	TO SPRAY RUST PROOFING		100.00	60
	LABOUR FOR PANEL BEATING & REPLACING PARTS		1,800.00	800
	TO PUTTY & SPRAY PAINTING		1,500.00	1000
	TOTAL		\$15,088.10	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5938.4
203
4750.72
7710.72
6168.