



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Date : 07/02/2020

TO: Great American Insurance Company
3 Temasek Avenue
#16-01 Centennial Tower Shirley.
Singapore 039190

Our Customer : Chua Kim Siang
Vehicle No : SKM8045U
Model : Mercedes Benz CLS350
Manufacture Year : 2011
Date of Accident : 07/02/2020
Total Estimate Repair Days : 5
Total Pages : 2

Attn : Motor Claims Department
Fax : 6235 2616

WDD2183592A028837

Re: Repair Estimate For Third Party Claim against GBJ1427U

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear door LH <i>Dented</i>	1	\$2,680.00	\$2,680.00	✓ 2340.
2	Rear door regulator motor LH <i>new</i>	1	\$622.00	\$622.00	+
3	Rear door regulator LH <i>new</i>	1	\$480.00	\$480.00	+
4	Rear door regulator bracket LH <i>new</i>	1	\$82.00	\$82.00	+
5	Rear door trimboard LH <i>new</i>	1	TBA	TBA	+
6	Rear door outer handle LH <i>Dented</i>	1	\$475.00	\$475.00	✓ 369
7	Rear door outer chrome LH <i>new</i>	1	\$180.00	\$180.00	+
8	Rear door sash pillar black sticker LH <i>new</i>	1	\$120.00	\$120.00	✓ 60
9	Rear door hinge LH <i>2</i>	2	\$215.00	\$430.00	+
10	Rear door striker LH <i>new</i>	1	\$285.00	\$285.00	+
11	Rear door channel LH	1	TBA	TBA	+
12	Rear door lower weatherstrip LH <i>new</i>	1	\$258.00	\$258.00	+
13	Rear door weatherstrip LH <i>new</i>	1	\$363.00	\$363.00	+
14	Rocker panel LH <i>new</i>	1	repair	repair	+
	Total			\$5,975.00	3132
	Less 10%			\$597.50	2888.50
	Sub-Total 1			\$5,377.50	
B.	Spare Parts (S/Nett)				
1	Rear door trimboard clip <i>gal</i>	10	\$9.00	\$90.00	+
2	Rear door rivet LH <i>gal</i>	10	\$9.00	\$90.00	+
	Sub-Total 2			\$180.00	
	Total for Spare Parts			\$5,557.50	
C.	Labour				
1	To check wiring.			\$80.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$400.00	250
3	Spray painting all affected parts & areas.			\$600.00	250
4	To remove and refit rear door glass LH.			\$100.00	60
5	To remove and refit rear door quarter glass LH.			\$80.00	30
	Total Labour			\$1,260.00	
	Total Repair Cost			\$6,817.50	

7,326.00



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Adrian Ling
L/s 12/02/20
03 Days

Supplementary : 220.50
Total: 3659.30
L/s 2.9K.

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To disassemble damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Date : 27/02/2020

TO: Great American Insurance Company
3 Temasek Avenue
#16-01 Centennial Tower
Singapore 039190

Our Customer : Chua Kim Siang
Vehicle No : SKM8045U
Model : Mercedes Benz CLS350
Manufacture Year : 2011
Date of Accident : 07/02/2020
Total Estimate Repair Days : 5
Total Pages : 1

Attn : Motor Claims Department
Fax : 6235 2616

Re: Repair Estimate For Third Party Claim against GBJ1427U

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear door outer handle inner bracket LH	1	\$565.00	\$565.00	245
			Total	\$565.00	
			Less 10%	\$56.50	
			Total Repair Cost	\$508.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Adnan Y
N/S 27/02/20.

245
220.50

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No