

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 7-Feb-20

INSURANCE: _____

MODEL: HYUNDAI IONIQ

VEHICLE NO.: SH6199D

Description	Qty	List Price	Amount	
Front Bumper Cover <i>distorted / mostly crack</i>	1	\$ 418.30	\$ 418.30	✓
Front Bumper Sponge/Absorber <i>HN</i>	1	\$ 86.90	\$ 86.90	X
Front Bumper Reinforcement <i>HN</i>	1	\$ 1,075.10	\$ 1,075.10	X
Front Bumper Grille (LH) <i>HN</i>	1	\$ 186.90	\$ 186.90	X
Front Bumper Towing Cover <i>HN</i>	1	\$ 29.00	\$ 29.00	X
Front Bumper Moulding Centre Upper (LH) <i>HN</i>	1	\$ 108.50	\$ 108.50	X
Front Bumper Lower Stiffener <i>HN</i>	1	\$ 85.10	\$ 85.10	X
Front Bumper Bracket Top (LH) <i>HN</i>	1	\$ 35.00	\$ 35.00	X
Front Bumper Bracket (LH) <i>HN</i>	1	\$ 28.00	\$ 28.00	X
Front Bumper Clips 10 pcs <i>HN</i>	1	\$ 22.00	\$ 22.00	✓
Front Bumper Centre Grille <i>HN</i>	1	\$ 318.80	\$ 318.80	X
Headlamp(LH) <i>HN</i>	1	\$ 3,987.30	\$ 3,987.30	X
Day Light ,LH <i>HN</i>	1	\$ 642.50	\$ 642.50	X
Day Light Wire, LH <i>HN</i>	1	\$ 585.50	\$ 585.50	X
Front Fender(LH) <i>Distorted</i>	1	\$ 490.70	\$ 490.70	✓
Front Fender Apron Panel (LH) <i>HN</i>	1	\$ 756.20	\$ 756.20	X
Front Fender Apron Panel Upper(LH) <i>HN</i>	1	\$ 129.60	\$ 129.60	X
Front Fender Shield (LH) <i>to rm</i>	1	\$ 114.70	\$ 114.70	✓
Front Fender Retainer <i>HN</i>	1	\$ 41.40	\$ 41.40	X
Frt Door(LH) <i>reg</i>	1	\$ 1,797.20	\$ 1,797.20	X
Frt Door Rubber <i>HN</i>	1	\$ 250.00	\$ 250.00	X
Front Door Glass (LH) <i>HN</i>	1	\$ 215.20	\$ 215.20	X
Front Door Gear / Regulator (LH) <i>HN</i>	1	\$ 250.40	\$ 250.40	X
Front Door Hinge Upper (LH) <i>HN</i>	1	\$ 65.76	\$ 65.76	X
Front Door Hinge Lower (LH) <i>HN</i>	1	\$ 65.76	\$ 65.76	X
Front Door Check (LH) <i>HN</i>	1	\$ 72.98	\$ 72.98	X
Front Door Inner Lock (LH) <i>HN</i>	1	\$ 285.60	\$ 285.60	X
Front Door Mirror ASSY (LH) <i>reg</i>	1	\$ 1,391.70	\$ 1,391.70	X
Front Door Trim Board (LH) <i>HN</i>	1	\$ 796.80	\$ 796.80	X
Front Door Protector(LH) <i>HN</i>	1	\$ 116.20	\$ 116.20	X
Rear Door (LH) <i>Distorted</i>	1	\$ 1,789.90	\$ 1,789.90	✓
Rear Door Rubber(LH) <i>HN</i>	1	\$ 270.00	\$ 270.00	X
Rear Door Outer Handle (LH) <i>HN</i>	1	\$ 124.80	\$ 124.80	X
Rear Door Lock Assy <i>HN</i>	1	\$ 306.40	\$ 306.40	X
Rear Door Hinge Upper (LH) <i>HN</i>	1	\$ 73.88	\$ 73.88	X
Rear Door Hinge Lower (LH) <i>HN</i>	1	\$ 73.88	\$ 73.88	X
Rear Door Check(LH) <i>HN</i>	1	\$ 85.92	\$ 85.92	X
Rear Door Trim Board (LH) <i>HN</i>	1	\$ 613.60	\$ 613.60	X
Door Centre Pillar Outer (LH) <i>HN</i>	1	\$ 3,764.90	\$ 3,764.90	X
Rocker Panel Outer Garnish <i>HN</i>	1	\$ 290.00	\$ 290.00	X
Front Wheel Rim (LH) <i>end dist</i>	1	\$ 1,124.20	\$ 1,124.20	✓
Front Wheel Hub Cap (LH) <i>end</i>	1	\$ 346.40	\$ 346.40	✓

Front Wheel Bearing <i>2 Done</i>		✓ 12	\$ 454.00	\$ 454.00
Front Shock Absorber(Assy)(LH) <i>2 distance</i>		✓ 12	\$ 372.50	\$ 372.50
Front Shock Absorber Mounting (LH) <i>HH</i>		1 X	\$ 206.90	\$ 206.90
Front Shock Absorber Fork (LH) <i>NS</i>		1 X	\$ 206.90	\$ 206.90
Front Suspension Upper Arm (LH) <i>2 HH</i>		X 12	\$ 244.30	\$ 244.30
Front STG Tie Rod <i>HH</i>		1 X	\$ 125.60	\$ 125.60
front STG Tie End <i>HH</i>		1 X	\$ 94.70	\$ 94.70
front Stabilizer Bar <i>HH</i>		1 X	\$ 246.80	\$ 246.80
front Stabilizer Bar Bush (LH) <i>HH</i>		1 X	\$ 22.30	\$ 22.30
front Stabilizer Bar Link <i>HH</i>		1 X	\$ 92.10	\$ 92.10
front Stabilizer Bracket <i>HH</i>		1 X	\$ 10.50	\$ 10.50
Front Suspension Lower Arm (LH) <i>2 distance</i>		✓ 12	\$ 296.80	\$ 296.80
Front Knuckle Arm (LH) <i>2 distance</i>		✓ 12	\$ 363.60	\$ 363.60
Front ABS Sensor <i>HH</i>		1 X	\$ 290.00	\$ 290.00
Rear Bumper <i>HH</i>		1 X	\$ 459.40	\$ 459.40
Rear Bumper Cover Clips <i>HH</i>		1 X	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>HH</i>		1 X	\$ 53.85	\$ 53.85
Rear Bumper Side Under(LH) <i>HH</i>		1 X	\$ 33.10	\$ 33.10
Rear Bumper Rear Hook <i>HH</i>		1 X	\$ 5.40	\$ 5.40
Rear Bumper Reflector Lamp(LH) <i>HH</i>		1 X	\$ 31.90	\$ 31.90
Rear Bumper Fog Lamp <i>HH</i>		1 X	\$ 201.50	\$ 201.50
Rear Bumper Towing Cover <i>HH</i>		1 X	\$ 98.80	\$ 98.80
Rear Bumper Reserve Light (Parking Brake Light) <i>HH</i>		1 X	\$ 257.10	\$ 257.10
Tail Lamp(LH) <i>HH</i>		1 X	\$ 870.40	\$ 870.40
Tail Lamp Quarter Panel(LH) <i>HH</i>		1 X	\$ 208.90	\$ 208.90
Rear Bumper Reflector Lamp(LH) <i>HH</i>		1 X	\$ 31.90	\$ 31.90
Rear Fender(LH) <i>Revised</i>		1 ✓	\$ 1,768.30	\$ 1,768.30
Rear Windscreen Moulding <i>HH</i>		1 X	\$ 48.50	\$ 48.50
Fuel Tank Sub Hose <i>HH</i>		1 X	\$ 109.10	\$ 109.10
Fuel Tank Upper Neck <i>HH</i>		1 X	\$ 221.10	\$ 221.10
Fuel Lid Cover <i>HH</i>		1 X	\$ 83.30	\$ 83.30
Rear Tyre Rim (LH) <i>2 distance</i>		✓ 12	\$ 1,124.20	\$ 1,124.20
Rear Wheel Hup-Cap (LH) <i>Can</i>		1 ✓	\$ 346.40	\$ 346.40
Rear Wheelbearing ING & Hub <i>2 done</i>		✓ 12	\$ 454.00	\$ 454.00
Rear Trailing Arm(LH) <i>2 distance</i>		✓ 12	\$ 265.40	\$ 265.40
Rear Assist (LH) <i>2 distance</i>		✓ 12	\$ 227.90	\$ 227.90
Rear shock Absorber(LH) <i>2 distance</i>		✓ 12	\$ 230.50	\$ 230.50
Rear Shock Absorber Mounting (LH) <i>HH</i>		1 X	\$ 133.10	\$ 133.10
Stabilizer Bar <i>HH</i>		1 X	\$ 387.30	\$ 387.30
Stabilizer Link <i>HH</i>		1 X	\$ 147.30	\$ 147.30
Rear Upper Arm(LH) <i>2 distance</i>		✓ 12	\$ 239.50	\$ 239.50
Rear Lower Arm(LH) <i>2 distance</i>		✓ 12	\$ 393.10	\$ 393.10
Rear Knuckle Arm (LH) <i>2 distance</i>		✓ 12	\$ 538.10	\$ 538.10
SUB TOTAL				\$ 35,331.33
LESS 20%				\$ 7,066.27
DISCOUNTED TOTAL				\$ 28,265.06
Front Fender Advertisement Logo (LH) <i>Heu</i>	NETT	1 ✓	\$ 100.00	\$ 100.00
Emblem-Blue Drive (LH) <i>Heu</i>	NETT	1 ✓	\$ 26.60	\$ 26.60
Front Door Advertisement Logo (LH) <i>Heu</i>	NETT	1 ✓	\$ 100.00	\$ 100.00
Rear Door Protector(LH) <i>HH</i>	NETT	1 X	\$ 116.20	\$ 116.20
Rear Door Tel No.Sticker(LH) <i>NS</i>	NETT	1 X	\$ 10.00	\$ 10.00
Rear Door Comfortdelgro & Apps Sticker(LH) <i>Heu</i>	NETT	1 ✓	\$ 80.00	\$ 80.00

Rear Bumper Advertisement Logo <i>NH</i>	NETT	1 ✓	\$ 50.00	\$ 50.00
Rear Bumper Rubber Mat <i>NH</i>	NETT	1 X	\$ 50.00	\$ 50.00
Rear Bumper Reverse Sensor <i>NH</i>	NETT	1 X	\$ 180.00	\$ 180.00
Rear Fender Advertisement Logo (LH) <i>NH</i>	NETT	1 ✓	\$ 100.00	\$ 100.00
Rear Windscreen Sealant <i>NH</i>	NETT	1 X	\$ 46.00	\$ 46.00
Front Tyre(LH) <i>NH</i>	NETT	1 X	\$ 216.00	\$ 216.00
Rear Tyre(LH) <i>NH</i>	NETT	1 X	\$ 216.00	\$ 216.00
SUB TOTAL				\$ 1,290.80
Labour Charge				
Panel Beating <i>800/-</i>		1	\$ 1,800.00	\$ 1,800.00
Spray Painting Charge <i>1000/-</i>		1	\$ 2,100.00	\$ 2,100.00
Wiring Charge <i>NH</i>		1	\$ 50.00	\$ 50.00 X
Tuff Kote <i>40/-</i>		1	\$ 50.00	\$ 50.00 X
Towing Charge <i>NH</i>		1	\$ 60.00	\$ 60.00 X
Remove/Refix Cushion & Upholstery Rear <i>80/-</i>		1	\$ 150.00	\$ 150.00
Remove/Refix Rear Windscreen Glass <i>NH</i>		1	\$ 150.00	\$ 150.00 X
Remove/Refix Reverse Sensor <i>NH</i>		1	\$ 120.00	\$ 120.00 X
Remove/Refix Undercarriage(FRT) <i>150/-</i>		1	\$ 400.00	\$ 400.00
Remove/Refix Fuel Tank <i>NH</i>		1	\$ 150.00	\$ 150.00 X
Transfer of Door Front <i>NH</i>		1	\$ 120.00	\$ 120.00 X
Transfer of Door Rear <i>60/-</i>		1	\$ 120.00	\$ 120.00
Remove/Refix Undercarriage(RR) <i>150/-</i>		1	\$ 400.00	\$ 400.00
4 Wheel Alignment <i>60/-</i>		1	\$ 120.00	\$ 120.00
Re-set Frt & Rear ABS System		1	\$ 200.00	\$ 200.00
Re-set Frt Power Window System <i>150/-</i>		1	\$ 200.00	\$ 200.00
Re-set Rear Power Window System		1	\$ 200.00	\$ 200.00
Diagnostic & Resetting To Erase Fault Code		1	\$ 480.00	\$ 480.00
TOTAL LABOUR				\$ 6,870.00
ESTIMATE TOTAL				\$ 36,425.86
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

10/02/2020 @ 0945hr

N/A Antenna

2/3 hrs 7 days.

[Signature]

LKK Auto

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: