

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

FCIL

ATTN: MOTOR CLAIMS DEPT

QUOTE NO

ACCIDENT DATE 01/02/2020@1840HRS

VRN SLB7882Y

MODEL Toyota Altis

TP VRN SHD3127H

Qty S\$ Unit S\$ Amt S\$ Labor

PARTS REPLACEMENT

1. Body Repair

1 Front Bumper	1	\$	458.00	\$	458.00	
2 Front Bumper Clips	10	\$	5.50	\$	55.00	
3 Front Bumper Outer Bracket LH/RH	1/2	\$	81.00	\$	162.00	
4 Front Fog Lamp LH	1	\$	325.00	\$	325.00	
5 Front Fog Lamp Cover LH	1	\$	92.00	\$	92.00	
6 Front Reinforcement	1	\$	382.00	\$	382.00	
7 Front Reinforcement Sponge	1	\$	79.00	\$	79.00	
8 Front Centre Grille	1	\$	564.00	\$	564.00	
9 Front Centre Lower Grille	1	\$	155.00	\$	155.00	
10 Headlamp LH	1	\$	850.00	\$	850.00	
11 Headlamp Chrome LH	1	\$	181.00	\$	181.00	
12 Front Fender LH	1	\$	781.00	\$	781.00	
13 Front Fender Shield LH	1	\$	200.00	\$	200.00	
14 Front Fender Shield Clips LH	10	\$	5.50	\$	55.00	
15 Front Fender Square Clips LH	10	\$	5.50	\$	55.00	
16 Front VVT-I Logo LH	1	\$	48.00	\$	48.00	
17 Bonnet	1	\$	1,037.00	\$	1,037.00	
18 Bonnet Hinge LH/RH	2	\$	75.00	\$	150.00	
19 Bonnet Lock	1	\$	130.00	\$	130.00	
20 Front Door LH	1	\$	1,100.00	\$	1,100.00	
21 Air Cleaner Box	1	\$	1,100.00	\$	1,100.00	
22 Air Cleaner Tube	1	\$	160.00	\$	160.00	
23 Shock Absorber LH	1	\$	402.00	\$	402.00	
24 Shock Absorber Mounting LH	1	\$	182.00	\$	182.00	
25 Lower Arm LH	1	\$	608.00	\$	608.00	
26 Kunkle Arm LH	1	\$	521.00	\$	521.00	
27 Front Wheel Bearing LH	1	\$	142.00	\$	142.00	
28 Lower Arm Ball Joint LH	1	\$	228.00	\$	228.00	
29 Tie Rod End LH	1	\$	146.00	\$	146.00	
30 Steering Rack	1	\$	1,625.00	\$	1,625.00	
31 Stabilizer Link LH	1	\$	202.00	\$	202.00	
32 Front Rim 16 Inch	1	\$	800.00	\$	800.00	S/N 500
33 Front Tyre LH	1	\$	82.00	\$	82.00	
34 Front Fender RH	1	\$	-	\$	-	

Supp - Headlamp RH - \$850.00 CRA / Resorator - \$103.00 CRA /
wheel Hub - \$220.00 BT /

Discount -25%

7228
25%
5421

\$ (3,243.75)

TOTAL

\$ 9,813.25

2. Labor Charges

- 1 Remove, repair and replace parts for affected areas
- 2 Spray paint on the affected areas
- 3 Check wiring, re-align headlamps & ensure proper functioning
- 4 Remove & replace front undercarriage & subframe
- 5 Check , re-adjust and computerise wheel alignment / side slip test
- 5 Dismantle & replace steering system, brake pump & booster to facilitate repair
- 6 Remove, replace & balance rim/tyre

750
\$ 1,250.00 ~~1000~~
\$ 1,250.00 ~~1000~~
\$ 100.00 ~~30~~
\$ 400.00 ~~100?~~
\$ 200.00 ~~60~~
\$ 180.00 ~~NN~~
\$ 40.00
1980

Sub Total

\$ 3,420.00

Grand Total : \$ 13,233.25
Add 7% GST : \$ 926.33
Net Total : \$ 14,159.58

No. of repair days: 10

Repair
Hp 9000000
7 days
p/p
10/02/2020 @ 1245

5421
500
+ 1980
7901

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

*Resurvey before
paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____