



ASSESSMENT FOR REPAIR : FBJ1109M
PIAGGIO VESPA LX 150 I.E. 3V
COE EXPIRY : 05 Jan 2024

Lump Sum / Part by Part

Qty	Description
1	RIGHT REAR VIEW MIRROR ✓ <i>scr</i>
1	R/H BRAKE LEVER ✓ <i>CRG</i>
1	FRONT BODY SHIELD ✓ <i>scr</i>
1	R/H SHIELD EDGE LINING ✓ <i>CRG</i>
1	FLOORBOARD FOOT ✓ <i>CRG</i>
1	FRONT MUDGUARD ✓ <i>scr</i>
1	R/H PAD FOOTPAD ✓ <i>scr</i>

Repairer's Estimate	1st Survey	Repair Survey	Final Survey
118.00			
58.00			
482.00			
71.00			
580.00			
220.00			
49.00			

1,578.00

Special Nett Items

STEERING CONE & BEARING X
 ALIGNMENT X

220.00			

220.00

Total Parts

1,798.00

Labour Charges

- | | | |
|---|---|--|
| 1 | Spray Painting ✓ | |
| 1 | Panel Beating (Body Only) X | |
| 1 | Towing X | |
| 2 | Workmanship to renew damage parts & areas ✓ | |

~~1200~~ 300
~~1200~~
~~60.00~~
~~500.00~~ 240
560.00

Total Parts & Labours Concluded

2,358.00

*2/5 repair
 without painting
 longer after paint
 3 day 4.00pm
 10/2/20
 H. ANN
 85312883
 Hock ANN@lkkAuto.com*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SANFU MOTOR PTE LTD

Company Reg No.: 200612487G

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com