

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 769P**AAD2002-047***Not Arthur
1/Sup & Book*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

07 FEB 2020

Date of Accident :

Third Party Insurer :

Date of Registration :

SHF 769P

VF1ABL15AUC283238

RENAULT

LATITUDE

6.2.2020

AIG

30/6/2016

PART		LIST	
1	BUMPER COVER REAR	\$	<i>n</i> 561.70 <i>X</i>
1	BUMPER LOWER REAR	\$	<i>nd/bm</i> 411.90 <i>—</i>
1	BUMPER BRACKET CTR REAR	\$	<i>Ln</i> 98.10
1	BUMPER BRACKET SIDE RH REAR	\$	<i>Ln</i> 82.10
1	BUMPER RETAINER RH REAR	\$	<i>Ln</i> 59.80
1	BUMPER REFLECTOR RH	\$	<i>Ln</i> 16.60
1	BUMPER BRACKET SIDE LH REAR	\$	<i>Ln</i> 80.80
1	BUMPER RETAINER LH REAR	\$	<i>Ln</i> 54.20
1	BUMPER REFLECTOR LH	\$	<i>Ln</i> 16.60
1	BUMPER BEAM REAR	\$	<i>n</i> 547.80
1	BUMPER BEAM BRACKET LH REAR	\$	<i>n</i> 114.50
1	BUMPER BEAM BRACKET RH REAR	\$	<i>n</i> 100.90
1	OUTER PANEL REAR (End Panel)	\$	<i>n</i> 745.80 <i>X</i>
1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>Ln</i> 404.56
1	TAILLAMP RH	\$	<i>Ln</i> 313.10
1	TAILLAMP PANEL RH	\$	<i>n</i> 401.40
1	TAILLAMP LH	\$	<i>Ln</i> 401.40
1	TAILLAMP PANEL LH	\$	<i>n</i> 401.40
1	BOOT REAR	\$	<i>n</i> 1,677.20
1	BOOT FINISHER	\$	<i>Ln</i> 344.70
1	BOOT WHEATERSTRIP	\$	<i>Ln</i> 178.20
1	BOOT REFLECTOR LAMP LH	\$	<i>Ln</i> 277.70
1	BOOT REFLECTOR LAMP RH	\$	<i>Ln</i> 277.70
1	BOOT BADGE 'RENAULT'	\$	<i>nn</i> 82.40
1	BOOT BADGE	\$	<i>nn</i> 95.80
1	BOOT INNER TRIM BOARD	\$	<i>Ln</i> 611.00

Trans-cab Auto Services Pte Ltd**AAD2002-047**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 769P

1	BOOT LOCK	\$	246.60	} X SH
1	BOOT HINGE LH	\$	254.20	
1	BOOT HINGE RH	\$	253.80	
1	BOOT STRUT LH	\$	145.10	
1	BOOT STRUT RH	\$	145.10	
1	EXHAUST CAP REAR	\$	125.40	
TOTAL		\$	9,527.56	
10%		\$	952.76	
		\$	8,574.80	

Special Nett

1SET PARKING AID	\$	SH 700.00	}	X
1SET REAR BUMPER CLIP	\$	nn 66.00		
1SET BUMPER BRACKET CTR CLIP	\$	nn 33.00		
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn 10.00		
1SET BUMPER RETAINER RH CLIP RR	\$	nn 20.00		
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn 10.00		
1SET BUMPER RETAINER CLIP LH RR	\$	nn 20.00		
1SET BUMPER LOWER REAR RIVET	\$	nn 22.00		
1SET BUMPER LOWER REAR CLIP	\$	nn 66.00	}	X
1 BOOT STICKER "Trans-cab"	\$	nn 30.00		
1 BOOT STICKER "6555-3333"	\$	nn 30.00		
1 BOOT INNER TRIM CLIP	\$	nn 45.00		
1SET BOOT FINISHER CLIP	\$	nn 24.20		
1 TAILLAMP CLIP LH	\$	nn 5.00		
1 TAILLAMP CLIP RH	\$	nn 5.00		
1 Rear Bumper Protector	\$	nn 100.00		
1 REAR LICENCE PLATE WITH HOLDER	\$	SH 80.00		
TOTAL		\$	1,266.20	
TOTAL PARTS		\$	9,841.00	

LABOUR

To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
---	----	-----------	---

Trans-cab Auto Services Pte Ltd**AAD2002-047**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 769P

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>10d</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	<i>4</i> 170.00	<i>X</i>
Putty and spray painting of the affected portion.	\$	6,000.00	<i>22d</i>
To Check Electrical Lighting Concerned.	\$	<i>na</i> 170.00	<i>X</i>
TOTAL	\$	14,170.00	
Over All Total	\$	24,011.00	

LKK Auto Consultants hence notify the Repairer of the **LUMP SUM (REPAIR DAY)**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

20 DAYS*1 day*