

Speed Auto Works
(Co Reg. No. 5321801E)
Blk 90 Bedok North Street 4
#13-1537 Singapore 460090
Tel: 6789 5155 Fax : 6783 5155

TO : AXA DATE : 4-Feb-20
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM
ESTIMATE REPORT :

OWNER'S PARTICULAR

VEHICLE DETAILS

NAME :

VEHICLE NO : SLG8336A

ADDRESS :

MODEL : NISSAN QASHQAL

TEL. NO. :

CHASSIS NO :

OWNER'S INSURANCE :

POLICY NO. :

ACCIDENT DETAILS

DATE
TIME

THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER X	1	\$ 898.00	\$ 898.00
2	FRONT BUMPER LOWER X	1	\$ 552.20	\$ 552.20
3	FRONT BUMPER SIDE RETAINER X	1	\$ 76.40	\$ 76.40
4	FRONT FENDER RH X	1	\$ 789.00	\$ 789.00
5	FRONT FENDER WHEEL ARCH GARNISH RH X	1	\$ 658.00	\$ 658.00
6	FRONT LOWER ARM RH X	1	\$ 498.20	\$ 498.20
7	FRONT SHOCK ABSORBER RH X	1	\$ 568.80	\$ 568.80
8	FRONT KNUCKLE ARM RH X	1	\$ 652.20	\$ 652.20
9	FRONT KNUCKLE ARM BEARING RH X	1	\$ 215.20	\$ 215.20
10	FRONT STEERING RACK AND PINION X	1	\$ 2,596.30	\$ 2,596.30
11	FRONT DOOR RH / 00	1	\$ 1,266.00	\$ 1,266.00
12	FRONT DOOR GLASS RH BR X Repeated	1	\$ 654.00	\$ 654.00

Item 20

1104.80 /

13	FRONT DOOR PROTECTOR LOWER RH / CUT	1	\$	321.50	\$	321.50
14	FRONT DOOR SPEAKER RH X	1	\$	212.00	\$	212.00
15	FRONT DOOR SIDE MIRROR X	1	\$	985.00	\$	985.00
16	FRONT DOOR INNER TRIM RH / CR4	1	\$	1,354.00	\$	1,354.00
17	FRONT DOOR WEATHERSTRIP RH / TN	1	\$	205.20	\$	205.20
18	FRONT DOOR REGULATOR RH ? / DT	1	\$	545.00	\$	545.00
19	FRONT DOOR GLASS MOTOR RH ? / JWS	1	\$	598.00	\$	598.00
20	FRONT DOOR GLASS RH / DR	1	\$	398.00	\$	398.00
21	FRONT DOOR GLASS CHANNEL RH / CUT	1	\$	225.00	\$	225.00
22	FRONT DOOR OUTER CHROME MOULDING RH / DO	1	\$	358.00	\$	358.00
23	FRONT DOOR INNER LOCK RH / Jemard	1	\$	328.20	\$	328.20
24	FRONT DOOR OUTER HANDLE RH / DR	1	\$	262.00	\$	262.00
25	FRONT DOOR HINGES RH X / DT	2	\$	112.00	\$	224.00
26	FRONT DOOR SPEAKER RH X	1	\$	186.00	\$	186.00
27	FRONT SIDE MIRROR RH X	1	\$	598.20	\$	598.20
28	HEADLAMP RH X	1	\$	985.60	\$	985.60
29	DOOR CENTER PILLAR OUTER RH X	1	\$	1,025.00	\$	1,025.00
30	DOOR CENTER PILLAR INNER RH X	1	\$	658.20	\$	658.20
31	REAR BUMPER X	1	\$	845.00	\$	845.00
33	REAR BUMPER SIDE RETAINER X	2	\$	54.00	\$	108.00
34	REAR DOOR RH / DO	1	\$	1,152.00	\$	1,152.00
35	REAR DOOR PROTECTOR LOWER RH / CUT	1	\$	321.50	\$	321.50
36	REAR DOOR OUTER CHROME MOULDING RH X	1	\$	358.00	\$	358.00
37	REAR DOOR WEATHERSTRIP RH / TN	1	\$	205.20	\$	205.20
38	REAR FENDER COWLING RH X	1	\$	215.00	\$	215.00
39	REAR FENDER WHEEL ARCH RH / DR	1	\$	658.00	\$	658.00

TOTAL PRICE \$ 22,755.90
 LESS 10% \$ 2,275.59
 SUB TOTAL PRICE \$ 20,480.31

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS X MC	10	\$ 6.50	\$ 65.00
2	FRONT DOOR INNER TRIM CLIPS / MC	5	\$ 6.50	\$ 32.50
3	FRONT FENDER INNER COWLING CLIPS X	10	\$ 6.50	\$ 65.00
4	FRONT FENDER WHEEL ARCH CLIPS X	6	\$ 6.50	\$ 39.00
5	FRONT PILLAR INSULATION SEAL X	1	\$ 150.00	\$ 150.00

1267.40 /
 437.70 /
 389.50 /

540.50 /

20

6	FRONT DOOR OUTER STICKER (BLACK) / <i>MC</i>	1	\$ 150.00	\$ 150.00	
7	SPORTS RIM <i>X</i>	2	\$ 600.00	\$ 1,200.00	
8	TYRE <i>X</i>	2	\$ 280.00	\$ 560.00	
9	REAR DOOR INNER TRIM CLIPS / <i>MC</i>	5	\$ 6.50	\$ 32.50	20
10	REAR DOOR OUTER STICKER (BLACK) / <i>MC</i>	1	\$ 150.00	\$ 150.00	
11	REAR FENDER INNER COWLING CLIPS <i>X</i>	10	\$ 6.50	\$ 65.00	
12	REAR FENDER WHEEL ARCH CLIPS / <i>MC</i>	6	\$ 6.50	\$ 39.00	20
13	REAR BUMPER CLIP <i>X</i>	10	\$ 6.50	\$ 65.00	
14	TAIL LAMP CLIP <i>X</i>	2	\$ 8.00	\$ 16.00	
15	REAR FENDER COWLING CLIP <i>X</i>	10	\$ 6.50	\$ 65.00	
16	REAR FENDER INNER TRIM CLIPS <i>X</i>	10	\$ 6.50	\$ 65.00	
17	REAR QUARTER GLASS SEALANT <i>X</i>	1	\$ 80.00	\$ 80.00	

TOTAL \$ **2,839.00**

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,800.00	<i>700900</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,400.00	<i>800</i>	
3	TUFF COAT	\$ 400.00	<i>50</i>	
4	CONDUCT FULL WHEEL ALIGNMENT	\$ 150.00	<i>X</i>	
5	WIRING CHECK	\$ 250.00	<i>30</i>	
6	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>X</i>	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>X</i>	
8	REMOVE AND REFIX REAR QUARTER GLASS RH	\$ 120.00	<i>X</i>	
9	REMOVE AND REFIX FRONT AND REAR UNDERCARRIAGE	\$ 480.00	<i>X</i>	
10	REMOVE AND REFIX FRONT DESKBORAD TO ASSIST REPAIR	\$ 400.00	<i>X</i>	

11	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X	
12	REMOVE AND REFIX REAR DOOR MECHANISM	\$ 150.00	50	
13	REMOVE AND REFIX FRONT DOOR MECHANISM	\$ 150.00	50	
14	MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	X	

TOTAL

\$8,090.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 26,895.91
TOTAL LABOUR COST : \$ 8,090.00
TOTAL REPAIR COST : \$ 34,985.91

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

Steve (LKK) ML ML
10/2/29, 2.99pm
L/S
My L/S
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: