



樹發汽車修理廠 SHU FATT AUTO WORKS



BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
6th February 2020
TP3-AXA

SMC 2106 X NISSAN QASHQAI

			SS	
Spare Parts	1	Rt rear tail light. ?	362.70	Nett
	4	Rt rear tail light holders. @\$7.40 X	30.80	Nett
	1	Rt rear fender. bt -	1105.80	Nett
	1	Rt rear fender inner cowling de -	196.40	Nett
	1	Set rt rear fender inner cowling clips. nee -	74.00	Nett
	1	Rt rear fender inner garnish. X	451.60	Nett
	1	Set rt rear fender inner garnish clips. X	74.00	Nett
	1	Rt rear arch garnish. de -	483.50	Nett
	1	Set rt rear arch garnish clips. nee -	74.00	Nett
	1	Rear bumper. de -	771.00	Nett
	1	Rear bumper tow cover. X	28.60	Nett
	1	Set rear bumper clips. nee -	88.80	Nett
	1	Rear bumper side retainers. @\$39.50 R4 nee -	79.00	Nett
	1	Rt rear door. repair	1114.80	Nett
	1	Rt rear door glass outer moulding X	199.80	Nett
	1	Set rt rear door pillar stickers. X	85.80	Nett
	1	Rt frt door. repair	1140.80	Nett
	1	Rt frt door glass outer moulding. X	199.80	Nett
	1	Set rt frt door pillar stickers. X	85.80	Nett
	1	Rt frt door outer handle. repair	195.20	Nett
	1	Rt rocker step panel. X (old damage)	1021.90	Nett
	1	Rear axle. ?	1521.90	Nett
	1	Rt rear wheel hub. ?	381.90	Nett
	1	Rt rear quarter glass moulding nee ?	420.00	Snet
	1	Rt rear shock absorber. ?	184.00	Snet
	1	Rt rear shock absorber bush. ?	65.00	Snet
	1	Rt rear rim (17"). sca -	300 1535.40	Snet
	1	Rt rear quarter glass inner seal nee -	45.00	Snet
	1	Rt rear quarter glass sealant. nee -	55.00	Snet
			12072.30	
Less 10% on Nett			976.79	
			11095.51	

Labour

To knock rear inner panel, rear lower panel, rear side panel, rt rear fender inner panel, rt rear arch panel, rt rear arch inner panel, rt rear door pillar, rt rocker panel, rt rear floor board, rt rear support panel, renew rear fender, rear light, rear bumper, rt rear door, rt frt door, rt step panel and assembly.

~~1800.00~~ 800

To respray damaged parts.

~~1650.00~~ 800

To remove, replace rt rear quarter glass.

~~150.00~~ 60

To remove rear garnishes, carpets, upholstery, seats, roof lining, spare wheel base, fender covers, boards to facilitate repairs and assembly.

~~380.00~~ 80

To check under carriage, replace damaged parts and assembly

~~450.00~~ 200? photo

To remove, replace rt rear wheel, balance and assembly.

~~60.00~~ 40

To reseal joints, reinsulate, anti rust panels and assembly.

~~150.00~~ 60

To check and adjust wheel alignment.

~~150.00~~ 60

To check and reset ECU.

~~150.00~~ 80

=====

16035.51

=====

Bridgestone 215/60R17
SINFEAJ11U2316265
49655

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rame

Hp 90010068

9 days

7/P

11/02/2020 @ 1230

Resurvey after repair

NOTE: TO provide wheel alignment copy