



樹發汽車修理廠 SHU FATT AUTO WORKS



BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
6th February 2020
TP3-AXA

SMC 2106 X NISSAN QASHQAI SJNFEA 311123/2018

Spare Parts			SS	
1	Rt rear tail light. ? Xnn		362.70	Nett X
4	Rt rear tail light holders. @\$7.40 Xnn		30.80	Nett X
1	Rt rear fender bt -		1105.80	Nett
1	Rt rear fender inner cowling de -		196.40	Nett
1	Set rt rear fender inner cowling clips nee -		3074.00	Nett snet
1	Rt rear fender inner garnish. Xnn		451.60	Nett X
1	Set rt rear fender inner garnish clips. Xnn		74.00	Nett X
1	Rt rear arch garnish. de -		483.50	Nett
1	Set rt rear arch garnish clips nee Xnn		74.00	Nett X
1	Rear bumper de -		771.00	Nett
1	Rear bumper tow cover. Xnn		28.60	Nett X
1	Set rear bumper clips nee -		36 88.80	Nett snet
1	Rear bumper side retainers. @ \$39.50 R4-nee -		345079.00	Nett 39.50 -
1	Rt rear door. repair		1114.80	Nett X
1	Rt rear door glass outer moulding Xnn		199.80	Nett X
1	Set rt rear door pillar stickers. Xnn		85.80	Nett X
1	Rt frt door. repair		1140.80	Nett XR
1	Rt frt door glass outer moulding Xnn		199.80	Nett X
1	Set rt frt door pillar stickers. Xnn		85.80	Nett X
1	Rt frt door outer handle. repair ? kiv		195.20	Nett XR
1	Rt rocker step panel. ^{svc} X (cold damage) Right rear partition detached.		1021.50	Nett X
1	Rear axle. ? bt -		1521.90	Nett
1	Rt rear wheel hub. ? bt -		381.90	Nett
1	Rt rear quarter glass moulding. nee ? Xnn Templet & glass		420.00	Snet
1	Rt rear shock absorber. ? bt -		184.00	Snet
1	Rt rear shock absorber bush ? ne -		65.00	Snet
1	Rt rear rim (17"). sca - AS PER INVOICE - \$1434.50 300		535.40	Snet - original from Agent sk
1	Rt rear quarter glass inner seal. ne -		45.00	Snet
1	Rt rear quarter glass sealant. ne -		55.00	Snet
			12072.30	
		Less 10% on Nett	976.79	
			11095.51	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Labour

To knock rear inner panel, rear lower panel, rear side panel, rt rear fender inner panel, rt rear arch panel, rt rear arch inner panel, rt rear door pillar, rt rocker panel, rt rear floor board, rt rear support panel, renew rear fender, rear light, rear bumper, rt rear door, rt frt door, rt step panel and assembly.

To respray damaged parts. *R/F door R/R fender R bumper - 2-tone*

To remove, replace rt rear quarter glass.

To remove rear garnishes, carpets, upholstery, seats, roof lining, spare wheel base, fender covers, boards to facilitate repairs and assembly.

To check under carriage, replace damaged parts and assembly

To remove, replace rt rear wheel, balance and assembly.

To reseal joints, reinsulate, anti rust panels and assembly.

To check and adjust wheel alignment.

To check and reset ECU.

~~1250~~
1800.00 ~~800~~ 900

~~1650.00~~ 900
~~150.00~~ 60
~~380.00~~ 80

~~450.00~~ 200? photo

~~60.00~~ 40
~~150.00~~ 60
~~150.00~~ 60
~~150.00~~ 80

16035.51

Bridgestone 215/60R17
SJNF EAJ11U2316265
49655

15,925.07#

Ram

Hp 90010068

9 days

~~1/3~~ P/P

11/02/2020 @ 1230

Reservy after repair.

Note: To provide wheel alignment copy