



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1922Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	CRACKED	459.40	459.40
10	REAR BUMPER CLIPS @ \$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING	DISTORTED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	294.80	-
2	REAR BUMPER REINFORCEMENT BRACKET - RH/LH @ \$138.10	NOT NECESSARY	276.20	-
1	REAR BUMPER LOWER CENTRE MOULDING	NOT NECESSARY	47.50	-
1	SMARTK ANTENNA	NOT NECESSARY	689.50	-
1	REAR PANEL	NOT NECESSARY	532.00	-
1	BOOT LID	BENT	2,480.40	2,480.40
1	BOOT LID 'H' EMBLEM	NOT NECESSARY	28.00	-
1	HYBRID' EMBLEM	NECESSARY	24.30	24.30
1	IONIQ' EMBLEM	NECESSARY	31.30	31.30
1	BOOT LID LOWER GLASS	CRACKED	384.90	384.90
2	TAIL LAMP (BOOT) - LH/RH @ \$794.40	NOT NECESSARY	1,588.80	-
2	REAR LICENSE LAMP - RH/LH @\$60.40	NOT NECESSARY	120.80	-
1	REAR FOGLAMP	NOT NECESSARY	201.50	-
	LESS 20% DISCOUNT		-1,526.53	-770.71
			6,106.12	3,082.84
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	NOT WORKING	135.70	135.70
1	REAR LICENSE PLATE & CASING (SN)	CRACKED	55.00	45.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
1	COMFORT STICKER (SN)	NECESSARY	15.00	15.00
1	TEL NO. STICKER (SN)	NECESSARY	15.00	15.00
1	BOOKING APP STICKER (SN)	NECESSARY	40.00	40.00
1	REAR LICENSE PLATE AND CASING (SN)	REPEATED	55.00	-
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	46.00	-
			407.70	250.70

Report Ref No. NS/INC20002318/T1qd3s2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR CHARGE.		1,500.00	640.00
	SPRAY PAINTING CHARGE.		800.00	400.00
	WIRING CHARGE.		80.00	30.00
	TUFF KOTE.		80.00	30.00
	REMOVE / REFIX REAR WINDSCREEN (UPPER & LOWER).		300.00	200.00
	COMPUTER PROGRAMMING FOR BSD.		250.00	150.00
			3,010.00	1,450.00
	GRAND TOTAL		9,523.82	4,783.54
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			4,783.54

Report Ref No. NS/INC20002318/T1qd3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.