

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

M2053REH104339946

HENDRA PUTRA BIN AMAT SAHAR

BLK 122A EDGEDALE PLAINS

#12-175

S 821122

TPMS16

JVonne

Date

:14.02.2020

Vehicle No

:SKX 8134 M

Make/Model

:TOYOTA ALTIS

Accident date

:09.02.2020

| No | DESCRIPTION | Qty | Amount (\$\$) |
|----|-------------|-----|---------------|
|----|-------------|-----|---------------|

### List Items

|               |                                                      |   |                        |
|---------------|------------------------------------------------------|---|------------------------|
| 1             | Front bonnet <i>Regis</i>                            | 1 | \$ 1130.90 X           |
| 2             | Front bonnet hinges @ \$56.30                        | 2 | \$ 112.60 X            |
| 3             | Front bonnet lock                                    | 1 | \$ 141.80 X            |
| 4             | Front bonnet lock bracket                            | 1 | \$ 113.40 X            |
| 5             | Front bumper <i>del</i>                              | 1 | \$ 503.90 ✓            |
| 6             | Front bumper side holder @ \$97.60 <i>RH New</i>     | 2 | \$ 195.20 <i>97.60</i> |
| 7             | Front bumper RH side fod lamp <i>new</i>             | 1 | \$ 104.50 X            |
| 8             | Front bumper RH side fod lamp cover <i>del</i>       | 1 | \$ 104.50 ✓            |
| 9             | Front RH headlamp <i>ut</i>                          | 1 | \$ 2652.00 ✓           |
| 10            | Front RH fender <i>Dented</i>                        | 1 | \$ 790.40 ✓            |
| 11            | Front RH fender VVTi emblem <i>new</i>               | 1 | \$ 41.00 ✓             |
| 12            | Front RH fender Dual emblem <i>new</i>               | 1 | \$ 41.00 ✓             |
| 13            | Front RH fender inner shield <i>horn</i>             | 1 | \$ 260.40 ✓            |
| 14            | Front RH fender inner shield clips (1set) <i>new</i> | 1 | \$ 70.00 <i>30</i>     |
| 15            | Front RH fender top quarter garnish <i>new</i>       | 1 | \$ 43.80 X             |
| 16            | Front RH fender inner rear garnish <i>del</i>        | 1 | \$ 71.80 ✓             |
| 17            | Front RH door <i>Dented</i>                          | 1 | \$ 1187.60 ✓           |
| 18            | Front RH door top hinge <i>new</i>                   | 1 | \$ 84.10 X             |
| 19            | Front RH door lower hinge                            | 1 | \$ 91.10 X             |
| 20            | Front RH door stopper <i>new</i>                     | 1 | \$ 152.20 X            |
| 21            | Front RH door side mirror                            | 1 | \$ }                   |
| 22            | Front RH door side mirror lamp                       | 1 | \$ }                   |
| 23            | Front RH door side mirror housing                    | 1 | \$ }                   |
| 24            | Front RH door side mirror cover <i>Regis</i>         | 1 | \$ 60.40 X             |
| 25            | Front RH lower arm <i>best</i>                       | 1 | \$ 505.20 <i>394</i>   |
| 26            | Front RH shock absorber <i>best</i>                  | 1 | \$ 512.50 <i>425</i>   |
| 27            | Front RH knuckle arm <i>Dented</i>                   | 1 | \$ 485.50 X            |
| 28            | Front RH knuckle arm bearing <i>new</i>              | 1 | \$ 131.30 ✓            |
| 29            | Front RH drive shaft <i>HP new</i>                   | 1 | \$ 1796.50 X           |
|               |                                                      |   | \$ 12859.50            |
| Less 25% Disc |                                                      |   | \$ 3214.90             |
| Total         |                                                      |   | \$ 9644.60             |

8222

6166.50

1475.90 1006

394

425

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

HENDRA PUTRA BIN AMAT SAHAR  
BLK 122A EDGEDALE PLAINS  
#12-175  
S 821122

Date :14.02.2020  
Vehicle No :SKX 8134 M  
Make/Model :TOYOTA ALTIS  
Accident date :09.02.2020

| No | DESCRIPTION | Qty | Amount (\$\$) |
|----|-------------|-----|---------------|
|----|-------------|-----|---------------|

### Special Nett Items

- 1 Front RH sport rim *lit*
- 2 Front RH tyre *NxL NxR*

*400*

|       |        |            |
|-------|--------|------------|
| \$    | 880.00 | <i>500</i> |
| \$    | 380.00 | <i>X</i>   |
| Total | \$     | 1260.00    |

### Labour Cost

- 1 To check wheel alignment
- 2 Remove & reinstall door ~~glass~~ *Fittings*
- 3 Remove & reinstall front RH suspension
- 4 Remove ,replace & repair consistent to the accident
- 5 Respray painting
- 6 Tuff kote

|                |         |            |
|----------------|---------|------------|
| \$             | 100.00  | <i>80</i>  |
| \$             | 100.00  | <i>80</i>  |
| <i>1880</i> \$ | 450.00  | <i>220</i> |
| \$             | 1200.00 | <i>600</i> |
| \$             | 1500.00 | <i>900</i> |
| \$             | 100.00  | <i>X</i>   |
| Total          | \$      | 3450.00    |

|             |    |          |
|-------------|----|----------|
| Grand Total | \$ | 14354.60 |
|-------------|----|----------|

*Total 8546.50*

*1/5 6:8K*  
*05Days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: