

**ACCIDENT REPAIR ESTIMATES**

Our Ref: TP / SLT6865J

Type of Claim : TPVehicle No. : SLT6865JMake & Model : BLUECARYear of Manufacture : 2017Chassis No. : VL4BCEB4RHT002918Ins Company : AIG ASIA PACIFIC  
INSURANCE PTE LTDEngine No. : 921955Q16W461500392Excess : 0Policy No. : Date of Accident : 22/1/2020Time of Accident : 22:30Suggested Days of Repair : 4Case Owner : BLUECAR EAST ASIA PTE**Repair Estimates**TP Vehicle No. : SKA15Y**Parts** (a) Cost / List Price Items \$ 1,313.00Plus/Less 20.0% \$ 262.60Total of Cost / List \$ 1,575.60(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 90.00**Total Parts Cost (Appendix A)** \$ 1,665.60**Labour (Appendix B)** \$ 950.00**Total Repair Cost** \$ 2,615.60

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Stew (LKK) 8322 8813Company : LKKSurvey conducted on : 10/2/20 at 4.30 PMRemarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 3 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ (e) Signature of surveyor : [Signature] Date: 10/2/20

**ESTIMATED REPAIR COST DETAILS**

Vehicle No : SLT6865J Case Owner : BLUECAR EAST ASIA  
PTE LTD / BLUESG PTE

Make & Model : BLUECAR Year Manufacture : 2017

Chassis No : VL4BCEB4RHT002918 Engine No : 921955Q16W461500392

Date & Time : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	REAR BUMPER ASSY / <i>OK</i>	1	\$ 823.00	\$ 823.00			
2	REAR BUMPER SCREW / <i>OK</i>	10	\$ 2.00	\$ 20.00			
3	REAR BUMPER REFLECTOR LH ?	1	\$ 48.00	\$ 48.00			
4	REAR BUMPER REFLECTOR RH / <i>OK</i>	1	\$ 48.00	\$ 48.00			
5	REAR BUMPER REINFORCEMENT ?	1	\$ 80.00	\$ 80.00			
6	REAR BUMPER REINFORCEMENT BRACKET 1 ?	1	\$ 11.00	\$ 11.00			
7	REAR BUMPER REINFORCEMENT BRACKET 1 ?	1	\$ 11.00	\$ 11.00			
8	REAR NUMBER PLATE W CASING / <i>OK</i>	1		\$ -			\$ 45.00
9	NUMBER PLATE LAMP LH / <i>OK</i>	1	\$ 42.00	\$ 42.00			
10	NUMBER PLATE LAMP RH / <i>OK</i>	1	\$ 42.00	\$ 42.00			
11	FRONT NUMBER PLATE W CASING / <i>OK</i>	1		\$ -			\$ 45.00
12	REAR RH FENDER COVER / <i>OK</i>	1	\$ 188.00	\$ 188.00			
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**TOTAL** \$ 1,295.00 \$ 1,313.00 \$ - \$ - \$ 90.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

BLUECAR  
EAST ASIA

: PTE LTD /

2017

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- **Supplementary item(s) must be resurveyed and** is subject to final approval from Insurance Company

Date: \_\_\_\_\_

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*