

ASS. REC. BY:

REF: CSI CTI 20002343 / Hf3

Special Instruction:

Surveyor: Hock Ann

## ASSIGNMENT (Office)

From (Person): Irene Tay

of CTI

Date/Time: 11.2.2020 1.31 PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 2670P

Insured: SLU 3108B

at Workshop m/s Vision AutoWork

Tel: 9856 4815

of 8 kabi Bukit 4 108-09 Premier

Policy No:

Claim No: SNM 20D 200708 / SLU 3108B / IRENE

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 7.2.2020

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time: 11.2.2020 1.30 PM

Person Contacted:

medium

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLD 2670P - NBA / AIG 20002234/4

D.O.A - 07/02/2020

SLU 3108B - NA / CTI 20002246/h4

D.O.A - 07/01/2020

unconfirm \$21,000/- (ump sum)  
(led: 17452.45; 690/0)

ASS. REC. BY: H. ANN

REF: C71

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD 2670P

at Workshop m/s vision Auto works

of 8 Kaki Bukit Ave 4 #08-09

Insured: primer

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Bal. on Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLD 2670P Yr Regn: 10/06/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota carry C.C. 2494

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 104808h T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR053 AK\*500 4011054

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55/R17

R: / /

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 5 mm 4010 R/Bal. 5 mm 4010

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 7/2/20 D.O.I. 11/2/20

Survey held at vision Auto

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	* SLD 2670P do
	* please inform workshop know, vehicle have limit repair, don't over 25k do 4
	Hock Ann,
	PLS check parts prices.
	MV - 83000
	PV - 57030
	NV - 25900

Date/Time, File Pass to? ☐ : Preli. Report1) ☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 25

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$

Photos

Others

TOTAL

Report Format:

Lump Sum / L.B.J. (\$) 21,000/-



## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	(Not Notified)		11 Feb 2020 13:44 <a href="#">Assign</a>				<a href="#">New Assignment</a> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	LAU YEW CHIN		
Vehicle Reg. No.:	SLD2670P	Date of Loss:	07/02/2020 17:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SLU3108B	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/02/2020]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Summer Lee (LKK Auto)

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Tuesday, 11 February, 2020 1:31 PM  
**To:** Vision Autowork  
**Cc:** Claims Dept of CTI; assignments; Admin A  
**Subject:** FW: OUR REF: SNM20D200708/SLU3108B/IRENE & YOUR REF: SLD2670P (Pre-inspection)  
**Attachments:** My Client (SLD2670P).pdf; Your Client (SLU3108B).pdf

Dear Sir (LKK),

We refer to the above matter.

Please get your surveyor to liaise with Vision Auto to conduct survey.

Regards,

**Irene Tay**  
Executive  
Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896192 | F:(65) 62247478/62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Vision Autowork [mailto:visionautowork@gmail.com]  
**Sent:** Tuesday, February 11, 2020 1:05 PM  
**To:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Subject:** Re: OUR REF: SNM20D200708/SLU3108B/IRENE & YOUR REF: SLD2670P (Pre-inspection)

Dear Irene,

As spoken, Please arrange **LKK Auto Consultant** to survey the above vehicle.

Attach My client (SLD2670P) and your client (SLU3108B) GIA report for your record

Thank You

Yours faithfully,

Michelle

Hp: 9856 4815

8 Kaki Bukit Avenue 4,  
#08-09, Premier @ Kaki Bukit,  
Singapore 415875  
Tel: 6341 6789  
Fax: 6341 6778

On Tue, Feb 11, 2020 at 11:45 AM Vision Autowork <[visionautowork@gmail.com](mailto:visionautowork@gmail.com)> wrote:

Dear Irene,

We refer to the above matter and our letter dated 10/02/2020.

Kindly note we have yet to hear from you regarding the PRS, please arrange accordingly in order to avoid unnecessary cost.

We are looking ahead for your reply soon.

Thank You

Yours faithfully,

Michelle  
Hp: 9856 4815

8 Kaki Bukit Avenue 4,  
#08-09, Premier @ Kaki Bukit,  
Singapore 415875  
Tel: 6341 6789  
Fax: 6341 6778

On Mon, Feb 10, 2020 at 3:28 PM Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)> wrote:

Dear Irene,

Please conduct PRS-SLD2670P soonest possible and our Insured has not filed SAS report

Officer in charge-Irene Tay -DID: 6389 6192

Dear Michelle,

\*\*\* kindly quote our reference number when replying.\*\*\*

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

**From:** Vision Autowork <[visionautowork@gmail.com](mailto:visionautowork@gmail.com)>

**Sent:** Monday, February 10, 2020 11:37 AM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Ong Chin Kiat <[chinkiat.ong@sg.cntaiping.com](mailto:chinkiat.ong@sg.cntaiping.com)>

**Subject:** SLD2670P (Pre-inspection) / YOur vehicle : SLU3108B

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

Hope we can do Direct Settle and please provide the surveyor firm or surveyor name list to conduct the joint pre-repair survey as a single joint expert



**\*\* PLEASE ADVISE LIABILITY \*\***

Thank You

Yours faithfully,

Michelle

Hp: 9856 4815

8 Kaki Bukit Avenue 4,

#08-09, Premier @ Kaki Bukit,

Singapore 415875

Tel: 6341 6789

Fax: 6341 6778

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	10/02/2020 10:24
Date Of Accident	07/02/2020 17:05
Exact Location Of Accident	PIE TOWARDS TUAS (AFTER THOMSON ROAD EXIT)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD2670P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LAU YEW CHIN
NRIC No	SXXXX957Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97830711
Alternative Phone No	OTHERS-97830711

### Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100468246-03
Cover Note Number	

### Driver

Name of Driver	LAU YEW CHIN
NRIC No	SXXXX957Z
Date Of Birth	14/07/1957
Occupation	INDOOR
Date Of Driving Pass	06/07/1978
Driving Experience	41 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97830711
Fax Number	
Contact Number	OTHERS-97830711
EMail Address	NOEMAIL



Address BLK 326 UBI AVENUE 1  
#12-693  
Postcode 400326  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 5  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number *SLU3108B* *BMW 15287*  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number *SDE9599G* *Toyota Lexus ES250*

Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

PRIVATE CAR

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

SMQ9871A

PRIVATE CAR

#### DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

SLX2445T

PRIVATE CAR

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/TIN No:



# Accident Sketch Plan

## SKETCH PLAN



PZE towards  
Tues  
(After Thomson  
Recd Exit)

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attached

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time

Driver's Signature  
(if driver is not the policyholder)  
Date & Time

Reporting Centre Person's Signature  
Name  
NRIC/FIN No:

**ATTACHMENT**

On 07.02.20 at about 17:05 hours at along PIE towards Tuas (After Thomson Road Exit), I was travelling on lane one and when my front vehicle (C) slowed down and stopped hence I followed suit.

Suddenly, I heard a loud bang from behind and I hit the front vehicle (C). When I alighted, I realized it was vehicle (B) who hit my rear portion of my vehicle (A) causing damages to my front & rear portion of my vehicle (A).

It was a chain collision of total 5 vehicles involved. Afterwhich, LTA Traffic marshal told me and the first car to move off.

Vehicle (A): SLD 2670P

Vehicle (B): SLU 3108B

Vehicle (C): SDE 9599G

Vehicle (D): SMQ 9871A

Vehicle (E): SLX 2445T

W 10/02/2020  
Red White

# Dynamic Autowork Pte.Ltd.

( ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 08.02.20

TO : CHINA TAIPING MOTOR CLAIMS DEPTS  
VEHICLE NO : SLD2670P  
MODEL : TOYOTA CAMRY  
DATE OF ACCIDENT : 07.02.20  
TIME OF ACCIDENT : 17:05HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER ✓ CNA	1	\$ 596.80	\$ 596.80
2	FRONT BUMPER GRILLE LOGO ✓ ME	1	\$ 80.10	\$ 80.10
3	FRONT BUMPER GRILLE (UPPER) ✓ CNA	1	\$ 799.50	\$ 799.50
4	FRONT BUMPER GRILLE (UPPER) TOP CHROME ✓ CNA	1	\$ 190.20	\$ 380.40
5	FRONT BUMPER GRILLE (LOWER) ✓ CNA	1	\$ 399.50	\$ 399.50
6	FRONT BUMPER GRILLE (LOWER) TOP CHROME ✓ CNA	1	\$ 180.60	\$ 180.60
7	FRONT NUMBER PLATE HOLDER GARNISH ✓ CNA	1	\$ 80.70	\$ 80.70
8	FRONT BUMPER FOGLAMP X (SVC)	2	\$ 248.30	\$ 496.60
9	FRONT BUMPER FOGLAMP RING (CHROME) ✓ SVC	2	\$ 83.20	\$ 166.40
10	FRONT BUMPER TOW HOOK COVER X (SVC)	1	\$ 58.70	\$ 58.70
11	FRONT BUMPER SENSOR ✓ S400T	2	\$ 268.30	\$ 536.60
12	FRONT BUMPER SENSOR RING X (SVC)	2	\$ 28.60	\$ 57.20
13	FRONT BUMPER SIDE AIR VENT X (SVC)	2	\$ 236.10	\$ 472.20
14	FRONT BUMPER BOTTOM COVER GARNISH ✓ CNA	1	\$ 258.80	\$ 258.80
15	FRONT BUMPER RETAINER ✓	2	\$ 95.30	\$ 190.60
16	FRONT BUMPER REINFORCEMENT X (R)	1	\$ 425.90	\$ 425.90
17	FRONT BUMPER SPONGE ✓ CNA	1	\$ 80.70	\$ 80.70
18	HEADLAMP ✓ LH (CNA) RH (CNA) ✓	2	\$ 1,807.50	\$ 3,615.00
19	HEADLAMP TOP CHROME ✓ SCR	2	\$ 85.10	\$ 170.20
20	FRONT FENDER RH ✓ BT LH ✓ BT	2	\$ 865.90	\$ 1,731.80
21	FRONT FENDER TOP INNER GARNISH X (SVC)	2	\$ 135.10	\$ 270.20
22	FRONT FENDER INNER COWLING RH ✓ CNA LH ✓ SVC	2	\$ 185.50	\$ 371.00
23	FRONT FENDER EMBLEM 'VVTI' ✓ ME	2	\$ 69.90	\$ 139.80
24	BONNET ✓ BT	1	\$ 1,477.90	\$ 1,477.90
25	BONNET MOULDING ✓ CNA	1	\$ 209.80	\$ 209.80
26	BONNET DAMPER X (SVC)	2	\$ 140.60	\$ 281.20
27	BONNET INSULATOR X (SVC)	1	\$ 525.10	\$ 525.10
28	BONNET HINGE X (R)	2	\$ 76.50	\$ 153.00



TO : CHINA TAIPIING MOTOR CLAIMS DEPTS  
 VEHICLE NO : SLD2670P  
 MODEL : TOYOTA CAMRY  
 DATE OF ACCIDENT : 07.02.20  
 TIME OF ACCIDENT : 17:05HRS

29	BONNET RUBBER X (sve)	1	\$ 78.10	\$ 78.10
30	BONNET LOCK ✓ Jm	1	\$ 213.70	\$ 213.70
31	BONNET STOPPER X (sve)	2	\$ 20.10	\$ 40.20
32	BRACE PANEL ✓ cm	1	\$ 135.20	\$ 135.20
33	RADIATOR SUPPORT PANEL ✓ BT	1	\$ 1,368.60	\$ 1,368.60
34	FRONT WIPER WASHER TANK X (sve)	1	\$ 185.70	\$ 185.70
35	BATTERY BRACKET X (sve)	1	\$ 125.30	\$ 125.30
36	FRONT FUSE BOX X (sve)	1	\$ 987.30	\$ 987.30
37	EXHAUST MANIFOLD X (sve)	1	\$ 986.10	\$ 986.10
38	MANIFOLD INSULATOR ✓ cm	1	\$ 256.30	\$ 256.30
39	FRONT WIREHARNESS X (sve)	1	\$ 1,798.10	\$ 1,798.10
40	HORN ✓ SR	2	\$ 121.30	\$ 242.60
41	AIRCON CONDENSOR ✓ BT DD	1	\$ 1,948.80	\$ 1,948.80
42	AIRCON FAN MOTOR X (sve)	1	\$ 448.30	\$ 448.30
43	AIRCON FAN BLADE X (sve)	1	\$ 165.80	\$ 165.80
44	AIRCON PIPE X (sve)	1	\$ 346.30	\$ 346.30
45	AIR CON COMPRESSOR X (sve)	1	\$ 1,283.50	\$ 1,283.50
46	AIR CON SUCTION PIPE X (sve)	1	\$ 468.50	\$ 468.50
47	AIR CON PRESSURE PIPE X (sve)	1	\$ 398.10	\$ 398.10
48	AIR DUCT ✓ cm	1	\$ 178.10	\$ 178.10
49	RADIATOR ✓ CRA	1	\$ 2,128.30	\$ 2,128.30
50	RADIATOR SPARE TANK X (sve)	1	\$ 97.70	\$ 97.70
51	RADIATOR FAN COWLING ✓ CRA	1	\$ 468.30	\$ 468.30
52	RADIATOR FAN MOTOR X (sve)	1	\$ 475.40	\$ 475.40
53	RADIATOR FAN BLADE X (sve)	1	\$ 179.10	\$ 179.10
54	RADIATOR SIDE GARNISH X (sve)	2	\$ 155.60	\$ 311.20
55	SIDE SKIRT RH X (sve)	1	\$ 496.80	\$ 496.80
56	REAR BUMPER ✓ CRA	1	\$ 657.60	\$ 657.60
57	REAR BUMPER DIFFUSER ✓ CRA	1	\$ 193.30	\$ 193.30
58	REAR BUMPER REFLECTOR R/B only ✓ 44x(sve) 12		\$ 72.30	\$ 144.60
59	REAR BUMPER SIDE RETAINER (SIDE) ✓ me	2	\$ 104.40	\$ 208.80
60	REAR BUMPER SCREW COVER GARNISH X (sve)	2	\$ 28.10	\$ 56.20
61	REAR BUMPER REINFORCEMENT ✓ BT	1	\$ 379.60	\$ 379.60
62	REVERSE SENSOR ✓ short	3	\$ 417.60	\$ 1,670.40
63	REVERSE SENSOR HOLDER ✓ me	4	\$ 28.10	\$ 112.40
64	REVERSE SENSOR WIRE HARNESS ✓ cut	1	\$ 865.10	\$ 865.10
65	TAILLAMP ✓ CRA	2	\$ 473.60	\$ 947.20

X Δ  
photo Δ

X R Δ

TO : CHINA TAIPIING MOTOR CLAIMS DEPTS  
 VEHICLE NO : SLD2670P  
 MODEL : TOYOTA CAMRY  
 DATE OF ACCIDENT : 07.02.20  
 TIME OF ACCIDENT : 17:05HRS

66	TAILLAMP CHROME MOULDING ✓scr	2	\$ 89.60	\$ 179.20
67	TAILLAMP LOWER BRACKET X	2	\$ 104.40	\$ 208.80
68	TAILLAMP PANEL ✓ BT	2	\$ 287.60	\$ 575.20
69	REAR FENDER L/H ✓ BT R/H X (R)	1 2	\$ 1,278.20	\$ 2,556.40
70	REAR FENDER INNER PANEL L/H only ✓ BT R/H X (R)	1 2	\$ 765.30	\$ 1,530.60
71	REAR FENDER AIR VENT LH ✓ c RA	1	\$ 115.40	\$ 115.40
72	REAR FENDER INNER COWLING L/H ✓ c RA R/H X (R)	1 2	\$ 169.40	\$ 338.80
73	REAR FENDER INNER TRIM L/H only ✓ c RA	1 2	\$ 525.00	\$ 1,050.00
74	REAR WHEEL HOUSE PANEL L/H ✓ BT R/H X (R)	1 2	\$ 978.60	\$ 1,957.20
75	REAR FUEL TANK INLET PIPE ✓ c RA	1	\$ 375.80	\$ 375.80
76	REAR FUEL TANK INLET PIPE HOLDER GARNISH X (c RA)	1	\$ 86.10	\$ 86.10
77	REAR FUEL TANK INLET PIPE COVER PANEL X (R)	1	\$ 113.60	\$ 113.60
78	REAR FUEL TAKE INLET PIPE COVER PANEL LOCK C/W CABLE X (svc)	1	\$ 265.60	\$ 265.60
79	REAR DRAIN PANEL ✓ BT	2	\$ 213.50	\$ 427.00
80	REAR WINDSCREEN MOULDING ✓ m	1	\$ 121.30	\$ 121.30
81	REAR CROSS MEMBER X (R)	1	\$ 1,596.30	\$ 1,596.30
82	REAR LOWER ADJUSTABLE ARM RH X (svc)	1	\$ 574.20	\$ 574.20
83	REAR BALANCE SYSTEM X (svc)	1	\$ 385.30	\$ 385.30
84	REAR DOOR L/H only ✓ (BT) R/H X (R)	2	\$ 1,176.10	\$ 2,352.20
85	REAR DOOR OUTER MOULDING X (svc)	2	\$ 106.80	\$ 213.60
86	REAR DOOR INNER LOCK L/H only ✓ Jm	1 2	\$ 569.80	\$ 1,139.60
87	REAR DOOR INNER TRIM L/H only ✓ c RA	1 2	\$ 1,219.70	\$ 2,439.40
88	REAR DOOR WEATHER STRIP L/H only ✓ c RA	1 2	\$ 196.50	\$ 393.00
89	BOOTLID ✓ cut	1	\$ 892.40	\$ 892.40
90	BOOTLID HINGE X (R)	2	\$ 118.30	\$ 236.60
91	BOOTLID CHROME MOULDING (CENTRE) ✓ (svc)	1	\$ 356.20	\$ 356.20
92	BOOTLID STOPPER X (svc)	2	\$ 19.20	\$ 38.40
93	BOOTLID LAMP ✓ c RA	2	\$ 326.70	\$ 653.40
94	BOOTLID INSULATOR X (svc)	1	\$ 294.30	\$ 294.30
95	BOOT LID EMBLEM 'CAMRY' ✓ m	1	\$ 65.00	\$ 65.00
96	BOOTLID EMBLEM '2.5' ✓ m	1	\$ 60.00	\$ 60.00
97	BOOTLID LOGO ✓ m	1	\$ 75.00	\$ 75.00
98	BOOTLID LOCK ✓ Jm	1	\$ 271.40	\$ 271.40
99	BOOTLID CATCHER X (svc)	1	\$ 25.00	\$ 25.00
100	BOOTLID WEATHERSTRIP ✓ c RA	1	\$ 227.20	\$ 227.20
101	BOOTLID DETECTOR X (svc)	1	\$ 198.60	\$ 198.60
102	BOOTLID DETECTOR WIRE HARNESS X (svc)	1	\$ 396.70	\$ 396.70

photo 20

XNS Δ



TO : CHINA TAIPIING MOTOR CLAIMS DEPTS  
 VEHICLE NO : SLD2670P  
 MODEL : TOYOTA CAMRY  
 DATE OF ACCIDENT : 07.02.20  
 TIME OF ACCIDENT : 17:05HRS

103	REVERSE CAMERA X (sue)	1	\$ 1,094.20	\$ 1,094.20
104	REAR END PANEL ✓	1	\$ 670.80	\$ 670.80
105	REAR END PANEL TOP GARNISH ✓ enu	1	\$ 403.70	\$ 403.70
106	REAR FLOOR PANEL ✓	1	\$ 818.70	\$ 818.70
107	REAR FLOOR SIDE PANEL ✓ ena	2	\$ 546.30	\$ 1,092.60
108	REAR FLOOR PANEL TOP BOARD ✓ enu	1	\$ 472.10	\$ 472.10
109	REAR FLOOR PANEL BOTTOM GARNISH ✓ ena	1	\$ 438.70	\$ 438.70
110	REAR FLOOR TOP SPONGE (SIDE) ✓ enu	2	\$ 198.80	\$ 397.60
111	REAR FLOOR TOP SPONGE (CENTER) ✓ enu	1	\$ 312.90	\$ 312.90
112	REAR SPARE TYRE BOLT X (sue)	1	\$ 38.10	\$ 38.10
113	REAR CHASSIS MEMBER RH 4H ✓ cut	1	\$ 1,438.60	\$ 1,438.60
114	REAR EXHAUT INSULATOR X	1	\$ 109.80	\$ 109.80
115	CENTER EXHAUST X (R)	1	\$ 1,088.70	\$ 1,088.70
116	CENTER EXHAUST INSULATOR X (sue)	1	\$ 136.10	\$ 136.10
117	CENTER EXHAUST GASKET (SET) X (sue)	1	\$ 60.00	\$ 60.00
118	REAR EXHAUST PIPE X ✓ BT	1	\$ 989.40	\$ 989.40
119	REAR EXHAUST MOUNTING X (sue)	4	\$ 39.20	\$ 156.80
120	REAR EXHAUST GASKET X (sue)	1	\$ 60.10	\$ 60.10

TOTAL PRICE \$ 67,816.60  
 LESS 25% \$ 16,954.15  
**SUB TOTAL PRICE \$ 50,862.45**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE ✓ SCR	1	\$ 50.00	\$ 50.00	30
2	FRONT BUMPER CLIPS (SET) ✓ me	1	\$ 80.00	\$ 80.00	30
3	BONNET INSULATOR CLIP (SET) ✓ me	1	\$ 50.00	\$ 50.00	15
4	FRONT FENDER COWLING CLIPS (SET) ✓ me	1	\$ 60.00	\$ 60.00	25
5	RADIATOR SUPPORT PANEL SEALANT X	1	\$ 80.00	\$ 80.00	
6	RADIATOR COOLANT ✓	1	\$ 60.00	\$ 60.00	30
7	REAR NUMBER PLATE X (sue)	1	\$ 50.00	\$ 50.00	
8	REAR BUMPER CLIPS (SET) ✓ me	1	\$ 80.00	\$ 80.00	30
9	BOOTLID INSULATOR CLIP (SET) ✓ me	1	\$ 60.00	\$ 60.00	20
10	TAILLAMP CLIPS (SET) ✓ me	1	\$ 30.00	\$ 30.00	10
11	TAILLAMP PANEL SEALANT 3 ✓	2	\$ 60.00	\$ 120.00	250
12	REAR FENDER SEALANT 3 ✓	2	\$ 150.00	\$ 300.00	
13	REAR FENDER COWLING CLIPS (SET) X (sue)	1	\$ 80.00	\$ 80.00	
14	REAR FENDER INNER TRIM CLIPS (SET) X (sue)	1	\$ 80.00	\$ 80.00	
15	REAR WHEEL HOUSE PANEL SEALANT ✓	1	\$ 150.00	\$ 150.00	20



TO : CHINA TAIPIING MOTOR CLAIMS DEPTS  
 VEHICLE NO : SLD2670P  
 MODEL : TOYOTA CAMRY  
 DATE OF ACCIDENT : 07.02.20  
 TIME OF ACCIDENT : 17:05HRS

16	REAR WINDSCREEN SEALANT ✓	1	\$ 80.00	\$ <del>80.00</del>
17	REAR WINDSCREEN INNER SEAL ✓	1	\$ 60.00	\$ <del>60.00</del>
18	REAR DOOR INNER TRIM CLIP (SET) ✓	1	\$ 60.00	\$ <del>60.00</del>
19	REAR END PANEL INSULATION SEAL 7	1	\$ 150.00	\$ <del>150.00</del>
20	REAR FLOOR PANEL INSULATION SEAL 7	1	\$ 350.00	\$ <del>350.00</del>
21	REAR FLOOR PANEL BOTTOM GARNISH CLIP (SET) X (one)	1	\$ 60.00	\$ <del>60.00</del>
22	REAR EXHAUST CHROME (SPECIAL TYPE) X	1	\$ 350.00	\$ <del>350.00</del>

TOTAL \$ 2,440.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ <del>1,800.00</del>	1200 - too high
2	SPRAY PAINTING TO AFFECTED AREA	\$ <del>1,800.00</del>	1200
3	REFOCUS HEADLAMP BEAM	\$ <del>60.00</del>	
4	REMOVE AND REFIX AIRCON CONDENSOR AND AIR CON COMPRESSOR AND REFILL AIRCON GAS	\$ <del>250.00</del>	80
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ <del>X 80.00</del>	
6	REMOVE AND REFIX FUSE BOX AND WIRING	\$ <del>X 450.00</del>	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS + R/R under carriage, R/R door chassis R/R, R/R wheel house R/R, R/R for the door lip	\$ <del>4,800.00</del>	3400 - too high
2	TO SPRAY PAINT AFFECTED AREA	\$ <del>2,800.00</del>	1700
3	TUFF COAT X	\$ <del>250.00</del>	
4	WIRING CHECK	\$ <del>180.00</del>	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ <del>250.00</del>	120
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ <del>80.00</del>	20

TO : CHINA TAIPING MOTOR CLAIMS DEPTS  
 VEHICLE NO : SLD2670P  
 MODEL : TOYOTA CAMRY  
 DATE OF ACCIDENT : 07.02.20  
 TIME OF ACCIDENT : 17:05HRS

7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ <del>80.00</del>	20
8	REMOVE AND REFIX REAR WINDSCREEN GLASS	\$ <del>RPT 120.00</del>	
9	TRANSFER BOOTLID MECHANISM	\$ <del>X 80.00</del>	
10	CONDUCT WATER LEAKAGE TEST	\$ <del>80.00</del>	30 X Δ
11	TRANSFER REAR DOOR MECHANISM	\$ <del>180.00</del>	60
12	REMOVE & REINSTALL REAR WINDOW GLASS	\$ <del>120.00</del>	100
13	REMOVE & REFIX AUDIO SPEAKER	\$ <del>X 120.00</del>	
14	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ <del>650.00</del>	
15	FOUR WHEEL ALIGNMENT	\$ <del>120.00</del>	60
16	REMOVE AND REFIX REAR EXHAUST PIPE	\$ <del>180.00</del>	50
17	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ <del>120.00</del>	50
18	REAR CHASSIS ALIGNMENT	\$ <del>250.00</del>	
19	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ <del>250.00</del>	120

**TOTAL \$15,150.00**

TOTAL PARTS COST : \$ 53,302.45  
 TOTAL LABOUR COST : \$ 15,150.00  
 TOTAL REPAIR COST : \$ 68,452.45

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

**ABBY**

SERVICE ADVISOR  
 ABBY  
 HP : 9856 4815

*H/S report  
 without post-claim  
 Repairer after part  
 H-ANW (1/11/20)  
 3.00pm  
 Hock ANW Office Auto ins.  
 25 day*

*Manager taken  
 manager after part  
 H-ANW  
 7.00pm  
 11/2/20*

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	957Z
<b>Vehicle Details</b>	
Vehicle No.:	SLD2670P
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.5 AUTO
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	2ARU323615
Chassis No.:	MR053AK5004011054
Maximum Power Output:	133.0 kW (178 bhp)
Open Market Value:	\$29,296.00
Original Registration Date:	10 Jun 2016
First Registration Date:	10 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$33,015.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jun 2026
PARF Rebate Amount:	\$24,761.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	09 Jun 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,010.00
COE Rebate Amount:	\$32,269.00
<b>Total Rebate Amount:</b>	<b>\$57,030.00</b>

The information contained herein is correct as at 12 Feb 2020

OK



# UNIVERSE

A NEW WORLD AWAITS YOU

TOYOTA CAMRY 2.5A

Price Range

Depreciation

2016

Vehicle Type

Advanced Search

Home » Used Cars » Marquee Kars » Toyota Camry 2.5A

## Toyota Camry 2.5A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$86,500

Depreciation \$11,460 /yr  
View models with similar depreReg Date 22-Mar-2016  
(6yrs 1mth 10days COE left)

Mileage 48,000 km (12.3k /yr)

Manufactured 2016

Road Tax \$1,792 /yr

Transmission Auto

Dereg Value \$53,458 as of today (change)

OMV \$29,296

COE \$46,970

ARF \$33,015

Engine Cap 2,494 cc

Power 133.0 kW (178 bhp)

Curb Weight 1,475 kg

No. of Owners 1

Type of Vehicle Luxury Sedan

## Features

View specs of the Toyota Camry (2012-2015)

## Accessories

Keyless Entry, Push Start/Stop Electric Memory Leather Seats, Dual Climatic Aircon. Air Conditioned Seats, Navigation, Multi Function Steering Wheel.

## Description

Loan 85% Of Car Price, 1 Careful Owner! Full Agent Maintained Unit!. View To Believe, Please Call For More Enquiry Before It's Gone. Accident Free! STA Evaluation Welcome!

## Category

PARF Car

## Status

Available

## Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 29-Jan-2020 | Last Updated on: 09-Feb-2020

## Upfront Payment

Transfer Fee

\$25

Down Payment

\$25,950 (change)

Maximum 70% Loan

1st Instalment

Based on 2.98% interest rate

In Compare

: (Get a quote)


Powered by



Location Map

## Price Chart

## Summary



## Seller Information

## Marquee Kars

9 vehicles for sale, 15 sold in past 3 mths

210 Turf Club Road Lot B18  
Car Mall @ The Grandstand  
Tel: 64620529  
Search cars nearby

Tiff Lee 96396161  
Johnson Lim 97994327