

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Feb 2020		11 Feb 2020 14:04 Edit Adj Rpt	S\$9,072.00 Edit Estimates	S\$9,072.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: ANG SOH YONG (HONG SURONG) , ID: S7127614G									
Vehicle Reg. No.: SKU9282C		Date of Loss: 04/02/2020 08:00 - :59 [25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM20D200636C02		Policy/Cover Note No.: DMCVSN19287119000							
Vehicle Reg. No. (Insured): XE5058R		Policy No. (Claimant): 2000001479							
		Excess: S\$1,500.00							
Repairer: Premium Automobiles Pte Ltd - Alexandra (HQ) 281 Alexandra Pte Ltd, Level B2, 159938 Alexandra - Tel: 63882233									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 20/02/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKU9282C (SNM20D200636C02)

[XE5058R]

TP

ANG SOH YONG (HONG SURONG)

Feb 4 2020 8:00AM

[-]

Premium Automobiles Pte Ltd - Alexandra

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Video									1 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)						Thumbnail		Print	
1	04/02/20 17:35	Video - Accident [Linked Accident Report Documents]						1 Load MP4			
Assessment Reports									1 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)						Thumbnail		Print	
1	04/02/20 17:36	Accident Statement						1 Load HTM			
Photos/Images									3 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)						Thumbnail		Print	
1	04/02/20 17:28	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
2	04/02/20 17:28	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
3	04/02/20 17:28	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
4	04/02/20 17:28	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
5	04/02/20 17:28	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
6	04/02/20 17:28	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
7	04/02/20 17:28	Accident Photo [Linked Accident Report Documents]						1 Load JPG		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	18/03/20 11:11	Odometer Reading						1 Load JPG		☒	
2	18/03/20 11:11	Chassis Number						1 Load JPG		☒	
3	18/03/20 11:11	General View						1 Load JPG		☒	
4	18/03/20 11:11	General View						1 Load JPG		☒	
5	18/03/20 11:11	General View						1 Load JPG		☒	
6	18/03/20 11:11	General View						1 Load JPG		☒	
7	18/03/20 11:11	General View						1 Load JPG		☒	
8	18/03/20 11:11	General View						1 Load JPG		☒	
9	18/03/20 11:11	General View						1 Load JPG		☒	
10	18/03/20 11:11	General View						1 Load JPG		☒	
11	18/03/20 11:11	General View						1 Load JPG		☒	
12	18/03/20 11:11	General View						1 Load JPG		☒	
13	18/03/20 11:11	General View						1 Load JPG		☒	
14	18/03/20 11:11	General View						1 Load JPG		☒	
15	18/03/20 11:11	General View						1 Load JPG		☒	
16	18/03/20 11:11	General View						1 Load JPG		☒	
17	18/03/20 11:11	General View						1 Load JPG		☒	
18	18/03/20 11:11	General View						1 Load JPG		☒	
19	18/03/20 11:11	General View						1 Load JPG		☒	
20	18/03/20 11:11	General View						1 Load JPG			

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
				☒
21	18/03/20 11:11	General View	Load JPG	☒
22	18/03/20 11:11	General View	Load JPG	☒
23	18/03/20 11:11	General View	Load JPG	☒
24	18/03/20 11:11	General View	Load JPG	☒
25	18/03/20 11:11	General View	Load JPG	☒
26	18/03/20 11:11	General View	Load JPG	☒
27	18/03/20 11:11	General View	Load JPG	☒
28	18/03/20 11:11	General View	Load JPG	☒
29	18/03/20 11:11	General View	Load JPG	☒
30	18/03/20 11:11	General View	Load JPG	☒
31	18/03/20 11:11	General View	Load JPG	☒
32	18/03/20 11:11	General View	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/02/20 14:04	Pre-Repair Survey	Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	04/02/20 17:35	Video - Accident	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	04/02/20 17:36	Accident Statement	Load HTM	
2	25/03/20 10:52	Addendum Sheet	Load JPG	☒
3	25/03/20 10:53	Accident Statement Addm. #1	Load HTM	
4	25/03/20 10:53	Addendum Sheet	Load JPG	☒
5	25/03/20 10:53	Accident Statement Addm. #2	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	04/02/20 17:28	Accident Photo	Load JPG	☒
2	04/02/20 17:28	Accident Photo	Load JPG	☒
3	04/02/20 17:28	Accident Photo	Load JPG	☒
4	04/02/20 17:28	Accident Photo	Load JPG	☒
5	04/02/20 17:28	Accident Photo	Load JPG	☒
6	04/02/20 17:28	Accident Photo	Load JPG	☒
7	04/02/20 17:28	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	04/02/20 17:23	Sketch Plan	Load JPG	☒
2	04/02/20 17:23	Sketch Plan #2	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002347/R1QF3E2

Date: 02/04/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN19287119000

Claimant Vehicle
No : SKU9282CInsured Vehicle
No : XE5058R

Date of Loss: 04/02/2020

Nature of Claim: TP

Claim
No: SNM20D200636C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKU9282C

Make & Model: AUDI Q3, 1.4 TFSI (A)

Reg. Date: 10/01/2020 (Man. Year: 2019)

Colour: Grey

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: CZD886148

Chassis No: WAUZZZF31L1010356

Odometer: 2332 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,261.00	5,200.00	12,061.00	69.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,172.00	3,872.00	2,300.00	37.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,433.00	9,072.00	14,361.00	61.29
+ GST 7.00/7.00% (S\$)	1,640.31	635.04	1,005.27	61.29
Nett Amount (S\$)	25,073.31	9,707.04	15,366.27	61.29

INSPECTION

Date of Assignment: 11/02/2020

Date Inspected: 11/02/2020 Inspected At:

Premium Automobiles Pte Ltd - Alexandra
(HQ)
281 Alexandra Pte Ltd, Level B2
Singapore 159938

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$8,902.00 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Apr 2020)
Parts:	M1-SUV	AUDI Q3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU9282C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,946.00 FS	*- FS
2	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Serviceable	110.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Serviceable	204.00 FS	*- FS
4	1		*FRONT BUMPER FRONT SPOILER	Serviceable	361.00 FS	*- FS
5	2		*FRONT BUMPER GRILLE - LH / RH	Serviceable	208.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Serviceable	288.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,349.00 FS	*1,349.00 FS
8	1		*RADIATOR GRILLE STRIKER PLATE	* Check	230.00 FS	*- FS
9	1		*RADIATOR GRILLE COVER CAP	Serviceable	42.00 FS	*- FS
10	1		*RADIATOR GRILLE BRACKET	* Check	39.00 FS	*- FS
11	1		*FRONT CAMERA	* Check	1,098.00 FS	*- FS
12	1		*RADIATOR GRILLE SECURING PLATE	* Check	31.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	* Check	96.00 FS	*- FS
14	1		*FRONT BUMPER CARRIER	* Check	793.00 FS	*- FS
15	1		*FRONT BUMPER COVER	* Check	116.00 FS	*- FS
16	1		*CAUTION SIGN STICKER	* Check	13.00 FS	*- FS
17	1		*AIRCON STICKER	* Check	7.00 FS	*- FS
18	2		*FRONT PARKING AID SENSOR (NPA)	Serviceable	0.00 FS	*- FS
19	2		*FRONT WHEEL COVER - LH / RH	Necessary	506.00 FS	*506.00 FS
20	1		*LED HEADLIGHT - LH	* Check	5,263.00 FS	*- FS
21	1		*BONNET	Bent	3,305.00 FS	*3,305.00 FS
22	1		*BONNET ATTACHMENT PARTS	* Check	279.00 FS	*- FS
23	1		*BONNET IMPACT PROTECTION - CENTRE	* Check	26.00 FS	*- FS
24	2		*BONNET STRIKER - LH / RH	* Check	208.00 FS	*- FS
25	2		*BONNET LID LOCK	* Check	403.00 FS	*- FS
26	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
27	1		*SUNDRIES	* Check	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	17,261.00	5,200.00
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ASSY, BONNET AND LHS HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,600.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	2,700.00	1,600.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			6,172.00	3,872.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >