

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 28431

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0143/2020/NS
Date : 6-Feb-20

Vehicle NOT IN workshop. Kindly arrange for survey.

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street
#19-00 The Octagon
Singapore 069534

Hi Rasul

5 days - ok - jb - 20 Jun 20

Attn: Motor Claims Dept

Tel: 6221 6111 - Fax: 6221 2101

Owner's Name : Ms Ang Soh Yong
Address : 200 Boon Lay Drive
#03-69
Singapore 640200
HP +65 98229685
Telephone : TP CLAIM YOUR INSURED XE 5058R
Type of Claim : 2000001476
Policy No. : **SKU 9282 C**
Vehicle No : Q3 1.4 TFSI S TRONIC
Model Code : Jan-20
Model / Year : CZD 886148
Engine No : WAUZZZF31L1010356
Chassis No : -
Mileage : -
Date In : Johnny Boo / Allan Wu
Estimated By : 4-Feb-20
Accident Date : Jurong West Ave 2

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKU 9282 C

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper assy, bonnet and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,800.00	\$ 1,600.00
3	To respray front bumper and bonnet.	\$ 2,700.00	\$ 1,600.00
4	Added labour - see attached	\$ 300.00	\$ 300.00
5	To carry out diagnostic checks	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 6,472.00	\$ 4,172.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKU 9282 C

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,946.00	
2	FRONT BUMPER CLOSING ELEMENT - LH / RH	2 \$ 110.00	
3	FRONT BUMPER GRILLE - CENTRE	\$ 204.00	
4	FRONT BUMPER FRONT SPOILER	\$ 361.00	
5	FRONT BUMPER GRILLE - LH / RH	2 \$ 208.00	
6	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 288.00	
7	RADIATOR GRILLE	\$ 1,349.00	\$ 1,349.00
8	RADIATOR GRILLE STRIKER PLATE	\$ 230.00	\$ 229.50
9	RADIATOR GRILLE COVER CAP	\$ 42.00	
10	RADIATOR GRILLE BRACKET	\$ 39.00	
11	FRONT CAMERA	\$ 1,098.00	
12	RADIATOR GRILLE SECURING PLATE	\$ 31.00	
13	FRONT BUMPER FOAM FILLER PIECE	\$ 96.00	
14	FRONT BUMPER CARRIER	\$ 793.00	
15	FRONT BUMPER COVER	\$ 116.00	\$ 115.50
16	CAUTION SIGN STICKER	NEC \$ 13.00	\$ 12.80
17	AIRCON STICKER	NEC \$ 7.00	\$ 6.70
18	FRONT PARKING AID SENSOR	2 TBC	
19	FRONT WHEEL COVER - LH / RH	2 \$ 506.00	\$ 506.00
20	LED HEADLIGHT - LH	\$ 5,263.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 12,700.00	\$ 2,219.50

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKU 9282 C

S/N	Parts Description	Damaged Parts & Prices		
			S/Nett	Remarks
		<i>c/f</i>		\$ 2,219.50
21	BONNET		\$ 3,305.00	\$ 3,305.00
22	BONNET ATTACHMENT PARTS		\$ 279.00	
23	BONNET IMPACT PROTECTION - CENTRE		\$ 26.00	
24	BONNET STRIKER - LH / RH	2	\$ 208.00	
25	BONNET LID LOCK	2	\$ 403.00	
26	FRONT NO PLATE	S/N	\$ 40.00	\$ 40.00
27	SUPPLEMENTARY		\$ 209.00	\$ 206.90
28	SUNDRIES		\$ 300.00	\$ 25.70
TOTAL SPARE PARTS CHARGES		:	\$ 17,470.00	\$ 5,797.10
TOTAL LABOUR CHARGES		:	\$ 6,472.00	\$ 4,172.00
GRAND TOTAL		:	\$ 23,942.00	\$ 9,969.10

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0143/2020/NS 26-May-20 Glory Tan 1 of 1 SKU 9282 C Q3 1.4 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Headlight mounting LHS	\$ 112.00	\$ 111.50
2	Radiator air guide LHS	\$ 36.00	\$ 35.10
3	Headlight sealing frame LHS	\$ 61.00	\$ 60.30
			\$ 206.90
<u>Labours</u>			
1	To reapply paint coating on affected area (by owner).	\$ 300.00	\$ 300.00
	TOTAL	\$ 509.00	\$ 506.90

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant