

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 28431

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0143/2020/NS
Date : 6-Feb-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : XE 5058 R

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street
#19-00 The Octagon
Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen
Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Ms Ang Soh Yong
Address : 200 Boon Lay Drive
#03-69
Singapore 640200
Telephone : HP +65 98229685
Type of Claim : Third Party Claim
Policy No. : 2000001476
Vehicle No : **SKU 9282 C**
Model Code : Q3 1.4 TFSI S TRONIC
Model / Year : Jan-20
Engine No : CZD 886148
Chassis No : WAUZZZF31L1010356
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Feb-20
Place of Accident : Jurong West Ave 2

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKU 9282 C

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper assy, bonnet and lhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,800.00 1600	
3	To respray front bumper and bonnet.	\$ 2,700.00 1600	
4	To carry out diagnostic checks	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 6,172.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKU 9282 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Repair</i>	\$	1,946.00
2	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>? X SVC</i>	2 \$	110.00
3	FRONT BUMPER GRILLE - CENTRE <i>? X SVC</i>	\$	204.00
4	FRONT BUMPER FRONT SPOILER <i>X SVC</i>	\$	361.00
5	FRONT BUMPER GRILLE - LH / RH <i>X SVC</i>	2 \$	208.00
6	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>X SVC</i>	2 \$	288.00
7	RADIATOR GRILLE <i>cra</i>	\$	1,349.00
8	RADIATOR GRILLE STRIKER PLATE <i>? cra</i>	\$	230.00 229.5
9	RADIATOR GRILLE COVER CAP <i>X SVC</i>	\$	42.00
10	RADIATOR GRILLE BRACKET <i>? X SVC</i>	\$	39.00
11	FRONT CAMERA <i>? X SVC</i>	\$	1,098.00
12	RADIATOR GRILLE SECURING PLATE <i>? X SVC</i>	\$	31.00
13	FRONT BUMPER FOAM FILLER PIECE <i>? X SVC</i>	\$	96.00
14	FRONT BUMPER CARRIER <i>? X SVC</i>	\$	793.00
15	FRONT BUMPER COVER <i>? cra</i>	\$	116.00 115.50
16	CAUTION SIGN STICKER <i>? nec</i>	NEC \$	13.00 12.80
17	AIRCON STICKER <i>? nec</i>	NEC \$	7.00 6.70
18	FRONT PARKING AID SENSOR <i>X SVC</i>	2	TBC
19	FRONT WHEEL COVER - LH / RH <i>Free</i>	2 \$	506.00
20	LED HEADLIGHT - LH <i>? X SVC</i>	\$	5,263.00
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 12,700.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKU 9282 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	BONNET <i>bt</i> ✓	\$ 3,305.00	
22	BONNET ATTACHMENT PARTS <i>?</i> X SVC	\$ 279.00	
23	BONNET IMPACT PROTECTION - CENTRE <i>?</i> X SVC	\$ 26.00	
24	BONNET STRIKER - LH / RH <i>?</i> X SVC	2 \$ 208.00	
25	BONNET LID LOCK <i>?</i> X SVC	2 \$ 403.00	
26	FRONT NO PLATE <i>bt</i> ✓	S/N \$ 40.00	
27	SUNDRIES <i>?</i> nec ✓	\$ 300.00	25.70
TOTAL SPARE PARTS CHARGES		: \$ 17,261.00	
TOTAL LABOUR CHARGES		: \$ 4,472.00	
GRAND TOTAL		: \$ 21,733.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : PASUL - Hp 90010068
Surveyed Date : 11/02/2020 @ 1630
Authorised Date :
Excess Cost : 5 days
Liability :
Remarks : Resurvey before paint

LPS Auto Consultants hence notify
the Repairer of the following:

- To rectify damaged/sprayed paint
- To display damaged parts being rectified
- Parts prices are subject to confirmation
- This party price is on a "Without Prejudice" basis
- To display damaged parts being rectified
- To display damaged parts being rectified and

Authorised by Repairer

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel.6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant