

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 28974

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0164/2020/NS
Date	:	12-Feb-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No : SMK 2220 G

SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Place

#05-01/06 Singapore Land Tower

Singapore 048623

Attn: Motor Claims Dept

Tel: 6461 6555 Fax 6221 3147

Owner's Name	:	Mr Pok Vic Sent
Address	:	Blk 15 West Coast Walk #08-28 Singapore 127162
Telephone	:	HP +65 96849645
Type of Claim	:	Third Party Claim
Policy No.	:	MT/00520694
Vehicle No	:	SLZ 618 P
Model Code	:	S5 Sportsback 3.0 TFS
Model / Year	:	Apr-18
Engine No	:	CWG 065877
Chassis No	:	WAUZZZF51JA080356
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	9-Feb-20
Place of Accident	:	Bukit Panjang Ring Road To Bankgit Road Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 618 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,200.00 800 ✓	✓
3	To respray rear bumper.	\$ 1,000.00 800 ✓	✓
4	To carry out diagnostic checks	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 2,752.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel. 6366 2323 Fax 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 618 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER By Deformed.	\$ 2,570.00 +	✓
2	REAR BUMPER FIXING SET	\$ 156.00 +	
3	REAR BUMPER SECURING STRIP } New	\$ 210.00 ✓	
4	REAR BUMPER SPOILER Lt	\$ 773.00 ✓	✓
5	REAR BUMPER TRIM Not Nec	\$ 316.00 +	
6	REAR BUMPER TRIM - CENTRE Not in	\$ 545.00 +	
7	REAR BUMPER SIDE MOLDING - LH / RH New	2 \$ 544.00 +	
8	REAR BUMPER LOWER TRIM - LH / RH Not in	2 \$ 76.00 +	
9	REAR LIGHT REFLECTOR - LH / RH New	2 \$ 78.00 +	
10	REAR BUMPER CARRIER } New	\$ 845.00 +	
11	REAR BUMPER SEAL	2 \$ 26.00 +	
12	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 42.00 +	
13	REAR PARKING AID SENSOR - INNER / OUTER } Not	2 TBC +	
14	REAR PARKING AID SEAL RING	4 \$ 14.00 +	
15	SUNDRIES Not Nec	\$ 200.00 ?	X
TOTAL SPARE PARTS CHARGES		: \$ 6,395.00	
TOTAL LABOUR CHARGES		: \$ 2,752.00	
GRAND TOTAL		: \$ 9,147.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adnan Y

Surveyed Date

: 13/02/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Antilocked

03 Days

H.S.

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before repair commencing
- To display damaged parts after resurvey
- Parts prices are subject to insurance company approval
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer:

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd



Allan Wu

Claims Consultant

Johnny Boo

Body Repair Manager