



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2003753
INV Date 11/05/2020
Reference CS/SMO20002351/Avd3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SLZ 618P
Insured Veh. SMK 2220G
Claim No. CMTD2000645/THE
Policy No.
Accident Date 09/02/2020
Inspection Date 13/02/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20002351/Avd3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 11-05-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMK 2220G	Veh. Inspected	SLZ 618P	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2000645/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	11/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	AUDI S5	c.c	2995	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WAUZZZF51JA080356	Colour	BLUE	
Odometer	26035	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/30 R20	MICHELIN	6 mm	
L/H Front Tyre	275/30 R20	MICHELIN	6 mm	
R/H Rear Tyre	275/30 R20	MICHELIN	6 mm	
L/H Rear Tyre	275/30 R20	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/02/2020	Inspection Date	13/02/2020	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 618P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (SN)	DEFORMED	2,570.00	2,570.00
1	REAR BUMPER FIXING SET (SN)	NOT NECESSARY	156.00	-
1	REAR BUMPER SECURING STRIP (SN)	NOT NECESSARY	210.00	-
1	REAR BUMPER SPOILER (SN)	CUT	773.00	772.50
1	REAR BUMPER TRIM (SN)	NOT NECESSARY	316.00	-
1	REAR BUMPER TRIM-CENTRE (SN)	NOT NECESSARY	545.00	-
2	REAR BUMPER SIDE MOULDING-LH/RH (SN)	NOT NECESSARY	544.00	-
2	REAR BUMPER LOWER TRIM-LH/RH (SN)	NOT NECESSARY	76.00	-
2	REAR LIGHT REFLECTOR-LH/RH (SN)	NOT NECESSARY	78.00	-
1	REAR BUMPER CARRIER (SN)	NOT NECESSARY	845.00	-
2	REAR BUMPER SEAL (SN)	NOT NECESSARY	26.00	-
2	REAR BUMPER GUIDE SECTION-LH/RH (SN)	NOT NECESSARY	42.00	-
2	REAR PARKING AID SENSOR-INNER/OUTER (NPA)(SN)	NOT NECESSARY	-	-
4	REAR PARKING AID SEAL RING (SN)	NOT NECESSARY	14.00	-
1	SUNDRIES (SN)	NOT NECESSARY	200.00	-
			6,395.00	3,342.50
<u>LABOUR</u>				
TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.			360.00	360.00
TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.			1,200.00	800.00
TO RESPRAY REAR BUMPER.			1,000.00	800.00
TO CARRY OUT DIAGNOSTIC CHECKS.			192.00	192.00
-			-	-
-			-	-
-			-	-
			2,752.00	2,152.00
GRAND TOTAL			9,147.00	5,494.50
RECOMMENDED COST OF REPAIRS				5,494.50

Report Ref No. CS/SMO20002351/Avd3n2



Report Ref No. CS/SMO20002351/Avd3n2

A handwritten signature in black ink, appearing to read 'A. Ling'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 618P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 618P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 618P

RE-INSPECTION

