

Estimation

Date:
Vehicle:
Make / Model:

10 February 2020
GBJ9387Z
TOYOTA/HIACE

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	FRONT PANEL <i>825.00 3065.00</i>	1	\$ 881.00	\$ 881.00
2	FRONT UPPER GRILLE <i>one</i>	1	\$ 312.00	\$ 312.00
3	FRONT LOWER GRILLE <i>one</i>	1	\$ 321.00	\$ 321.00
4	FRONT EMBLEM <i>78.50 121</i>	1	\$ 131.00	\$ 131.00
5	FRONT HEADLAMP <i>11</i>	2	\$ 731.00	\$ 1,462.00
6	FRONT LOWER GRILLE GARNISH <i>11</i>	1	\$ 192.00	\$ 192.00
7	FRONT BUMPER <i>1</i>	1	\$ 661.00	\$ 661.00
8	FRONT BUMPER BRACKET <i>11</i>	2	\$ 91.00	\$ 182.00
9	FRONT BUMPER REINFORCEMENT <i>11</i>	1	\$ 391.00	\$ 391.00
10	FRONT BUMPER SIDE GRILLE <i>11</i>	2	\$ 182.00	\$ 364.00
				\$ 4,897.00
				Less 25%
				\$ 1,224.25
				Total
				\$ 3,672.75
S/Nett items:				
11	FRONT BUMPER CLIP <i>one</i>	1 SET	\$ 40.00	\$ 40.00
12	FRONT NUMBER PLATE <i>one</i>	1	\$ 80.00	\$ 80.00
13	FRONT GRILLE CLIP <i>11</i>	1 SET	\$ 30.00	\$ 30.00
				\$ 150.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not Authorized
black

11/2/20
2/s \$1700

3 days.
the 1st After repi

LKK Hsiao Toun

9-1537
25%
14275

[illegible]