

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5966P**AAD2002-049***Not Authorized
Resurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

10 FEB 2020

SHD 5966P

JTDKB3FU903078631

TOYOTA

PRIUS

6.2.2020

AIG

19/12/2018

PART**LIST**

1	REAR BUMPER	\$	K	442.60	X
1	REAR BUMPER RE-INFORCEMENT	\$		332.70	?
1	REAR BUMPER TOWING COVER	\$	S	15.40	X
1	GUARD, REAR BUMPER, CENTER	\$	Not Item	576.30	—
1	REAR BUMPER SIDE RETAINER LH	\$	S	116.50	}
1	REAR BUMPER SIDE RETAINER RH	\$	S	117.70	
1	REAR TAILGATE	\$	S	1,147.80	
1	REAR TAILGATE OUTER GARNISH	\$	S	925.60	
1	REAR TAILGATE WEATHERSTRIP	\$	S	372.30	
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	S	650.30	
1	TAILLAMP LOWER RH	\$	S	502.00	
1	TAILLAMP UPPER RH	\$	S	451.80	
1	REAR BUMPER SIDE RH	\$	S	123.70	
1	REAR BUMPER SIDE LH	\$	S	123.70	
1	TAILLAMP LOWER LH	\$	S	502.00	}
1	TAILLAMP UPPER LH	\$	S	443.30	
1	COVER, DECK TRIM, REAR	\$	S	126.70	
1	COVER, FLOOR UNDER, NO 1	\$	S	175.10	
1	COVER, FLOOR UNDER, NO 2	\$	S	241.90	
1	COVER, REAR FLOOR	\$	S	229.90	X

TOTAL	\$	7,617.30
25%	\$	1,904.33
	\$	5,712.98

Special Nett

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5966P**AAD2002-049**

1SET	PARKING AID	\$	Ph	700.00	}	X
1SET	REAR BUMPER CLIP	\$	nn	66.00		
1	REAR TAILGATE TOYOTA LOGO	\$	nn	47.00		
1	REAR TAILGATE WORDING 'PRIUS'	\$	nn	52.90		
1	REAR TAILGATE WORDING 'HYBRID'	\$	nn	53.50		
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn	80.00		
1	REAR TAILGATE STICKER '6555-3333'	\$	nn	80.00	}	
1	REAR BUMPER PROTECTOR	\$	nn	100.00		
1	REAR WHEEL RIM	\$	Ph	1,879.40	}	X
1	REAR TYRE 195/65/15	\$	Ph	350.00		
1	REAR WHEEL RIM COVER	\$	Ph	211.50		
1	REAR RH BUMPER RETAINER CLIP	\$	nn	35.00		
1	REAR LH BUMPER RETAINER CLIP	\$	nn	35.00		
TOTAL		\$		3,690.30		

TOTAL PARTS	\$	9,403.28
--------------------	-----------	-----------------

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$		6,000.00	<i>2200</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD2002-049**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5966P

To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>1501</i>
TOTAL	\$	14,170.00	
Over All Total	\$	23,573.28	

(PART-BY-PART) Repair Days**20 Days***1 day*