

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5966P****AAD2002-049***Not Authorized  
Resurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

10 FEB 2020

**SHD 5966P**

P/P \$842.23

JTDKB3FU903078631

TOYOTA

PRIUS

6.2.2020

**AIG**

19/12/2018

**PART****LIST**

1	REAR BUMPER	\$	<i>h</i>	442.60	X
1	REAR BUMPER RE-INFORCEMENT	\$		SVC 332.70	X
1	REAR BUMPER TOWING COVER	\$	<i>h</i>	15.40	X
1	GUARD, REAR BUMPER, CENTER	\$	<i>Not item</i>	576.30	—
1	REAR BUMPER SIDE RETAINER LH	\$	<i>h</i>	116.50	}
1	REAR BUMPER SIDE RETAINER RH	\$	<i>h</i>	117.70	
1	REAR TAILGATE	\$	<i>h</i>	1,147.80	
1	REAR TAILGATE OUTER GARNISH	\$	<i>h</i>	925.60	
1	REAR TAILGATE WEATHERSTRIP	\$	<i>h</i>	372.30	
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>h</i>	650.30	
1	TAILLAMP LOWER RH	\$	<i>h</i>	502.00	
1	TAILLAMP UPPER RH	\$	<i>h</i>	451.80	
1	REAR BUMPER SIDE RH	\$	<i>h</i>	123.70	
1	REAR BUMPER SIDE LH	\$	<i>h</i>	123.70	
1	TAILLAMP LOWER LH	\$	<i>h</i>	502.00	}
1	TAILLAMP UPPER LH	\$	<i>h</i>	443.30	
1	COVER, DECK TRIM, REAR	\$	<i>h</i>	126.70	
1	COVER, FLOOR UNDER, NO 1	\$	<i>h</i>	175.10	
1	COVER, FLOOR UNDER, NO 2	\$	<i>h</i>	241.90	
1	COVER, REAR FLOOR	\$	<i>h</i>	229.90	X

**TOTAL \$ 7,617.30****25% \$ 1,904.33****\$ 5,712.98****Special Nett**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5966P****AAD2002-049**

1SET	PARKING AID	\$	Ph	700.00	}	X
1SET	REAR BUMPER CLIP	\$	na	66.00		
1	REAR TAILGATE TOYOTA LOGO	\$	na	47.00		
1	REAR TAILGATE WORDING 'PRIUS'	\$	na	52.90		
1	REAR TAILGATE WORDING 'HYBRID'	\$	na	53.50		
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	na	80.00		
1	REAR TAILGATE STICKER '6555-3333'	\$	na	80.00	}	X
1	REAR BUMPER PROTECTOR	\$	na	100.00		
1	REAR WHEEL RIM	\$	Ph	1,879.40	}	X
1	REAR TYRE 195/65/15	\$	Ph	350.00		
1	REAR WHEEL RIM COVER	\$	Ph	211.50		
1	REAR RH BUMPER RETAINER CLIP	\$	na	35.00		
1	REAR LH BUMPER RETAINER CLIP	\$	na	35.00		
TOTAL		\$		3,690.30		

<b>TOTAL PARTS</b>	<b>\$</b>	<b>9,403.28</b>
--------------------	-----------	-----------------

**LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *nn* 170.00 *X*

To transfer of Rear Bumper fittings, attachments and perform water seepage test.

\$ *nn* 170.00 *X*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 6,000.00 *2200*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

**Trans-cab Auto Services Pte Ltd****AAD2002-049**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5966P**

To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>1501</i>
<b>TOTAL</b>	<b>\$</b>	<b>14,170.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>23,573.28</b>	

**(PART-BY-PART) Repair Days****20 Days***1 day*