

ASS. REC. BY:

REF: CS/CTI 20002370/TIVf3

Special Instruction:

Surveyor: TaukikhASSIGNMENT (Office)From (Person): Chang Binn Sen of CTI Date/Time: 11.2.2020 3:58p.m

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: GBG 919AR Insured: GBJ 7866Xat Workshop m/s Efficient motor Tel: 9239 9009of 56-10yang way #06-07Policy No: _____ Claim No: SNM200200699/GBJ 7866X/CS

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 6.2.2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 11.2.2020 4:09 PM Person Contacted: Eric H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GBG 919AR - AT/CTI 20002370/24</u> <u>DOA - 06/01/2020</u>
	<u>GBJ 7866X - AT/CTI 20002370/24</u> <u>DOA - 06/01/2020</u>
<u>25/2/20</u>	<u>LS \$3350 confirmed by email (Recd 3006.25, 14/3)</u>

ASS. REC. BY:

REF: CTI

ASSIGNMENT

From:

Date: 12.2.2020

Estimated Cost:

OD TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: GBG 9199R

at Workshop m/s Efficient motor

of 56 Iyang way #06-07

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Contact: 92399009

After 2:30 pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date: Person Contacted:

SVC

Veh No:

GBG 9199R

Yr Regn:

2017, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace. M

c.c

2982

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

111879

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02PX00234030

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/R15

R:

u ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Duratun.

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

12/2/20

Survey held at

Efficient motor

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 20 FEB 2020

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

25/2 - typist

Rep. Format:

merimen

Lump Sum / L.R. / :

3350/-

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

220

Summer Lee (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 11 February, 2020 3:58 PM
To: efficientloyang@gmail.com
Cc: assignments; Chong Boon Sen
Subject: RE: OUR REF: SNM20D200699/GBJ7866X/CBS & YOUR REF: GBG9199R -SURVEY INVITATION for accident on 06/02/2020 at HDB service rd beside Blk 205/206 Pasir Ris St 21 involving vehicles GBG9199R & GBJ7866X

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

;b

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: efficientloyang@gmail.com [mailto:efficientloyang@gmail.com]
Sent: Tuesday, February 11, 2020 3:51 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: OUR REF: SNM20D200699/GBJ7866X/CBS & YOUR REF: GBG9199R -SURVEY INVITATION for accident on 06/02/2020 at HDB service rd beside Blk 205/206 Pasir Ris St 21 involving vehicles GBG9199R & GBJ7866X

Dear Sir / Mdm

kindly arrange LKK to survey the vehicle

Thank you

Regards
Eric

On Mon, 10 Feb 2020 at 17:52, Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without prejudice
Save as to costs

Dear Sir,
LKK
LBS
STA

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, February 10, 2020 5:51 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; efficientloyang@gmail.com

Subject: OUR REF: SNM20D200699/GBJ7866X/CBS & YOUR REF: GBG9199R -SURVEY INVITATION for accident on 06/02/2020 at HDB service rd beside Blk 205/206 Pasir Ris St 21 involving vehicles GBG9199R & GBJ7866X

Dear Boon Sen,

Please conduct PRS -GBG9199R soonest possible

Officer in charge-Chong Boon Sen-DID: 6389 6171

Dear Mas,

*** kindly quote our reference number when replying.***

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: efficientloyang@gmail.com <efficientloyang@gmail.com>

Sent: Monday, February 10, 2020 5:19 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Cc: Eric <eric@panpacificleasing.com.sg>; Jessie <jessie.ong@panpacificleasing.com.sg>

Subject: SURVEY INVITATION for accident on 06/02/2020 at HDB service rd beside Blk 205/206 Pasir Ris St 21 involving vehicles GBG9199R & GBJ7866X

Dear Claim Officer,

We refer to the above matter. (DOA 06/02/2020)

We are the appointed repair workshop of vehicle no. GBG9199R.

We understand that you are the insurer of vehicle no. GBJ7866X.

The owner of the vehicle no. GBG9199R has authorised us to carry out the repairs to their vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and /or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damages to the vehicle prior to the commencement of the repair.

Contact Person: Mr Eric Kee H/P: 9239 9009 or Ms Jessie Ong H/P: 8723 3003

Best Regards,

Mas Ariyanti

Efficient Motor & Engineering Works Pte Ltd

56 Loyang Way #06-07 Loyang Enterprise Building, S(508775)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 25 February 2020 12:36 PM
To: efficientloyang@gmail.com
Cc: SUR; ALEX NG
Subject: RE: GBG 9199R-DOA: 6/2/2020

Dear Alex,

WITHOUT PREJUDICE

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: efficientloyang@gmail.com <efficientloyang@gmail.com>
Sent: Tuesday, 25 February 2020 12:27 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; ALEX NG <alex.ng@panpacificleasing.com.sg>
Subject: Re: GBG 9199R-DOA: 6/2/2020

Hi Veron,

Yes, Please proceed.

Thank you.

Regards
Alex Ng
H/P 87310838

On Tue, 25 Feb 2020 at 11:51, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Eric,

WITHOUT PREJUDICE

Offer Lump Sum \$3350 @ 5 working days.

PARTS-\$3580 (less 25%)=\$2685

LABOUR-\$1890

TOTAL-4215 (less 20%)=\$3372

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
GBG9199R

Make / Model
TOYOTA / HIACE VAN TURBO 5DR MT

Vehicle Type :
A50 - Goods (Closed) Van/Van Panel (Delivery)

Vehicle Scheme :
Normal

Propellant :
Diesel

Motor No. :
-

Power Rating :
-

Maximum Laden Weight :
2800 kg

Year Of Manufacture :
2017

Lifespan Expiry Date :
28 Nov 2037

PQP Paid :
\$37,686.00

Road Tax Expiry Date :
28 May 2020

Inspection Due Date :
28 Nov 2020

CO2 Emission :
210.00 (g/km)

CO Emission :
-

NOx Emission :
-

Vehicle Attachment 1 :
No Attachment

Chassis No. :
JTFHT02PX00234030

Engine No. :
1KD2752600

Engine Capacity :
2982 cc

Maximum Power Output :
-

Unladen Weight :
1700 kg

Original Registration Date :
29 Nov 2017

COE Category :
C - Goods Vehicle & Bus

COE Expiry Date :
28 Nov 2027

PARF Eligibility Expiry Date :
-

Intended Transfer Date :
12 Feb 2020

CEV/VES Rebate Utilised Amount :
-

HC Emission :
-

PM Emission :
-

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBG9199R

MAKE & MODEL : TOYOTA HIACE

CHASSIS NO : JTFHT02PX00234030

DATE : 10/02/2020

CLAIM TYPE : TP CLAIM

TO : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

PARTS DESCRIPTION

LIST ITEMS

QTY UNTIL PRICE AMOUNT

1	LH REAR SLIDING DOOR	1	\$ 1,550.00	\$ 1,550.00	66
2	LH REAR SLIDING DOOR RAILING	1	\$ 480.00	\$ 480.00	66
3	LH REAR SLIDING DOOR ROLLER BEARING TOP	1	\$ 85.00	\$ 85.00	Xnn
4	LH REAR SLIDING DOOR ROLLER BEARING BOTTOM	1	\$ 350.00	\$ 350.00	Xnn
5	LH REAR FENDER	1	\$ 1,550.00	\$ 1,550.00	66
6	LH REAR SLIDING DOOR INNER TRIM BOARD	1	\$ 380.00	\$ 380.00	Xnn

TOTAL :	\$ 4,395.00	\$ 4,395.00	3580.
LESS 25 %	\$ 1,098.75	\$ 1,098.75	
TOTAL :	\$ 3,296.25	\$ 3,296.25	2685.

TOTAL PARTS :	\$ 3,296.25	\$ 3,296.25
---------------	-------------	-------------

LABOUR

1	LABOUR FOR PANEL BEATING	\$ 1,600.00	800
2	LABOUR FOR SPRAYPAINTING	\$ 1,000.00	600
3	WIRING	\$ 80.00	30
4	LABOUR FOR TRANSFER LH REAR SLIDING DOOR FITTING	\$ 180.00	60
5	TO APPLY RUST PROOF ON LH ACCIDENT AREAS	\$ 200.00	40

TOTAL :	\$ 3,060.00	1890.
---------	-------------	-------

TOTAL PARTS AND LABOUR : \$ 6,356.25

PREPARE BY:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]
Bp/pomo
Taufik 97445744 #575
WP
12/2/2020 350pm
Lump sum 4215
Resurvey after repair 4583350
5 days
taufik@lkkauto.com
sure@lkkauto.com

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002370/T1VF3N2
Date: 27/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30628419000
Claimant Vehicle No: GBG9199R Insured Vehicle No: GBJ7866X
Date of Loss: 06/02/2020 Nature of Claim: TP Claim No: SNM20D200699C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG9199R
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M) Engine No: 1KD2752600
Reg. Date: 29/11/2017 (Man. Year: 2017) Chassis No: JTFHT02PX00234030
Colour: White Odometer: 111879 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15 Rear Tyre Size: 195R15
Front Left Side: DURATURN 6 mm Rear Left Side: DURATURN 6 mm
Front Right Side: DURATURN 6 mm Rear Right Side: DURATURN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,296.25	2,685.00	611.25	18.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	1,530.00	1,530.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,356.25	4,215.00	2,141.25	33.69
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	6,356.25	3,350.00	3,006.25	47.30
+ GST 7.00/7.00% (S\$)	444.94	234.50	210.44	47.30
Nett Amount (S\$)	6,801.19	3,584.50	3,216.69	47.30

INSPECTION

Date of Assignment: 11/02/2020
Date Inspected: 12/02/2020 Inspected At: Efficient Motor & Engineering Works Pte Ltd (HQ)
56 Loyang Way #06-07, Loyang Enterprise Building
Singapore 508775
Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 27 Feb 2020)

Parts: 213 TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBG9199R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH REAR SLIDING DOOR	Bent	1,550.00 FL	*1,550.00 FL
2	1		*LH REAR SLIDING DOOR RAILING	Bent	480.00 FL	*480.00 FL
3	1		*LH REAR SLIDING DOOR ROLLER BEARING TOP	Not Necessary	85.00 FL	*- FL
4	1		*LH REAR SLIDING DOOR ROLLER BEARING BOTTOM	Not Necessary	350.00 FL	*- FL
5	1		*LH REAR FENDER	Bent	1,550.00 FL	*1,550.00 FL
6	1		*LH REAR SLIDING DOOR INNER TRIM BOARD	Not Necessary	380.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,395.00	3,580.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,098.75	895.00
Total Parts (\$\$)	3,296.25	2,685.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,600.00	800.00
2	LABOUR FOR SPRAYPAINTING	New	1,000.00	600.00
3	WIRING	New	80.00	30.00
4	LABOUR FOR TRANSFER LH REAR SLIDING DOOR FITTING	New	180.00	60.00
5	TO APPLY RUST PROOF ON LH ACCIDENT AREAS	New	200.00	40.00
Gross Labour Cost (S\$)			3,060.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >