



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

SIN FATT HIN SUPPLIERS

07/02/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP111

Xiao Tony

JN1MC2E2620007260

Accident date: 05/02/2020

Estimated repair cost for vehicle no: GBF8317D NISSAN NV350 2.5 M '17

CHASSIS: JN1MC2E2620007260

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Windscreen Seal <i>new</i>		\$135.00 ✓
4	1	Front Panel <i>Dented</i>		\$1,350.30 ✓ 1206
5	1	Front Grille <i>Cracked</i>		\$521.50 ✓
6	10	Front Grille Clip <i>new</i>	\$6.50	\$65.00 ✓ 10
7	1	Front Grille Emblem Logo <i>new</i>		\$79.90 ✓

Subtotal :- \$2,151.70

1952.4

175716

Labour charges

To remove & refit air-con blower, coolant coil, air duct blower & top up gas	\$380.00	X
To remove & refit front windscreen	\$120.00	✓
Gum	\$60.00	✓
To remove & refit front dashboard	\$450.00	X
To check wiring	\$100.00	30
Tuff kote	990	\$150.00 80
Panel beating	\$800.00	400.
Spray painting	\$600.00	300.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$2,660.00

Total:- \$4,811.70

total: 2747.16

4/s: 2.2K

04 days

2212