

45190 2024

GOLD AUTOWORKS PTE LTD

48 Toh Guan Road East Enterprise Hub #01-119 Singapore 608586

Email : claims@goldautoworks.com.sg

Company Reg no. 201716329M

CAR MODEL : HY AVANTE 1.6AT

VEH NO: SKP5068H

CHASS NO : KMHDU41BMAU987080

HP:8199-9149

Estimate Bill

	List Item	Qty	Unit Price	Amount
1	rear boot lid <i>bt</i>	1	\$ 907.00	\$ 907.00
2	rear boot lid hinge L/R <i>X su</i>	2	\$ 120.80	\$ 241.60
3	rear boot lid no.plate garnishes <i>X su</i>	1	\$ 228.70	\$ 228.70
4	rear boot lid no.plate lamp L/R <i>X su</i>	2	\$ 89.10	\$ 178.20
5	rear boot lid emblem (logo) <i>na</i>	1	\$ 61.60	\$ 61.60
6	rear boot lid emblem (avante) <i>na</i>	1	\$ 66.20	\$ 66.20
7	rear boot lid inner trim <i>X su</i>	1	\$ 120.40	\$ 120.04
8	boot lid inner trim clip <i>na</i>	10	\$ 3.50	\$ 35.00
9	boot lid weatherstrip <i>na</i>	1	\$ 83.37	\$ 83.37
10	rear boot lid lock assy <i>bt</i>	1	\$ 283.50	\$ 283.50
11	rear tailamp R/L (boot lid) <i>LH - cm / RH - Xsu</i> <i>1pc</i>	2	\$ 208.03	\$ 416.06
12	rear tailamp R/L (panel) <i>3.2 cm</i>	2	\$ 430.67	\$ 861.34
13	rear bumper <i>de</i>	1	\$ 531.80	\$ 531.80
14	rear bumper clip <i>na</i>	8	\$ 3.40	\$ 27.20
15	rear bumper retainer L/R <i>X su</i>	2	\$ 33.10	\$ 66.20
16	rear bumper absorber <i>cm</i>	1	\$ 136.04	\$ 136.04
17	rear bumper beam <i>cm</i>	1	\$ 284.16	\$ 284.16
18	rear bumper bracket RH <i>na</i>	1	\$ 83.26	\$ 83.26
19	rear bumper lower bracket <i>cm</i> <i>1pc</i>	1	\$ 36.68	\$ 110.04
20	rear side fender LH <i>X su</i>	1	\$ 919.20	\$ 919.20
21	rear fender panel inner trim LH <i>na</i>	1	\$ 218.04	\$ 218.04
22	fender panel inner trim clip <i>na</i> <i>6pcs</i>	1	\$ 3.20	\$ 38.40
23	rear door weatherstrip LH (panel) <i>X su</i>	1	\$ 100.05	\$ 100.05
24	rear end panel <i>bt</i>	1	\$ 759.50	\$ 759.50
25	rear end panel garnishes <i>de</i>	1	\$ 207.11	\$ 207.11
26	end panel garnishes clip <i>na</i>	5	\$ 3.80	\$ 19.00
27	spare tyre panel <i>repair</i>	1	\$ 983.20	\$ 983.20
28	rear side fender shield RH <i>X su</i>	1	\$ 103.15	\$ 103.15
29	rear tailamp panel L/R <i>LH - Repair RH - Xsu</i> <i>1pc</i>	2	\$ 155.90	\$ 311.80
Total list amount				\$ 8,380.76
list 20% discount				\$ 1,676.15
after discount				\$ 6,704.60
Special Nett Item				
30	reverse sensor <i>? X su</i>	1	\$ 250.00	\$ 250.00
31	rear end panel sealant <i>na</i>	1	\$ 60.00	\$ 60.00
32	spare tyre panel sealant <i>na</i>	1	\$ 60.00	\$ 60.00
33	side fender RH sealant <i>na X</i>	1	\$ 80.00	\$ 80.00
34	rear windscreen sealant <i>na X</i>	1	\$ 60.00	\$ 60.00
35	rear windscreen moulding <i>na X</i>	1	\$ 110.00	\$ 110.00
36	side fender quarter glass LH with moulding <i>na X</i>	1	\$ 430.00	\$ 430.00

208.03

4847.23

20%

3877.78

36.68

X

X

X

200? X

78.80

60

37	PHV sticker (LTA) <i>xm</i>	1	\$ 30.00	\$ 30.00	X
38	rear reverse camera (infrared type) <i>xm</i>	1	\$ 300.00	\$ 300.00	X
Labour					
A	to check rear electrical wiring system	-	\$ 60.00	\$ 60.00	30
B	to transfer boot compartment parts to new boot	-	\$ 100.00	\$ 100.00	60
C	to remove and reinstall rear interior trims, garnishes, etc				
	for necessary repair	-	\$ 200.00	\$ 200.00	60
D	to straighten, repair, realign rear exhaust silencer	-	\$ 100.00	\$ 100.00	<i>xm</i>
E	to remove, replace and reinstall rear reverse sensor &				
	control unit with rear camera	-	\$ 200.00	\$ 200.00	60
F	to straighten, repair, realign on rear affected area and				
	replace damaged parts	-	\$ 1,800.00	\$ 1,800.00	800 800
G	to spray painting, blending on rear affected and adjacent	-	\$ 2,000.00	\$ 2,000.00	800
H	to apply anti-rust coating on new and affected panels	-	\$ 200.00	\$ 200.00	80
total labour & s/n				\$ 6,040.00	
lump-sum 20%				\$ 10,195.68	

30
 60
 60
xm
 60
 800
 800
 80
 1890

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Repair
 Hp 900/10068
 7 days
 4/5
 12/02/2020 @ 1530
 Resurvey after repair

3877.78
 60.00
 1890.00
 5827.78
 20%
 4662.22
 4/5 - 4,650
 7 days