

GOLD AUTOWORKS PTE LTD

48 Toh Guan Road East Enterprise Hub #01-119 Singapore 608586

Email : claims@goldautoworks.com.sg

Company Reg no. 201716329M

CAR MODEL : HY AVANTE 1.6AT

VEH NO: SKP5068H

CHASS NO : KMHDU41BMAU987080

HP:8199-9149

Estimate Bill

	List Item	Qty	Unit Price	Amount
1	rear boot lid <i>lt</i>	1	\$ 907.00	\$ 907.00
2	rear boot lid hinge L/R <i>X</i>	2	\$ 120.80	\$ 241.60
3	rear boot lid no.plate garnishes <i>X</i>	1	\$ 228.70	\$ 228.70
4	rear boot lid no.plate lamp L/R <i>X</i>	2	\$ 89.10	\$ 178.20
5	rear boot lid emblem (logo) <i>na</i>	1	\$ 61.60	\$ 61.60
6	rear boot lid emblem (avante) <i>na</i>	1	\$ 66.20	\$ 66.20
7	rear boot lid inner trim <i>X</i>	1	\$ 120.40	\$ 120.04
8	boot lid inner trim clip <i>na</i>	10	\$ 3.50	\$ 35.00
9	boot lid weatherstrip <i>na</i>	1	\$ 83.37	\$ 83.37
10	rear boot lid lock assy <i>lt</i>	1	\$ 283.50	\$ 283.50
11	rear tailamp R/L (boot lid) <i>X</i>	2	\$ 208.03	\$ 416.06
12	rear tailamp R/L (panel) <i>322?</i>	2	\$ 430.67	\$ 861.34
13	rear bumper <i>de</i>	1	\$ 531.80	\$ 531.80
14	rear bumper clip <i>na</i>	8	\$ 3.40	\$ 27.20
15	rear bumper retainer L/R <i>X</i>	2	\$ 33.10	\$ 66.20
16	rear bumper absorber <i>crh</i>	1	\$ 136.04	\$ 136.04
17	rear bumper beam <i>crh</i>	1	\$ 284.16	\$ 284.16
18	rear bumper bracket RH <i>na</i>	1	\$ 83.26	\$ 83.26
19	rear bumper lower bracket <i>X</i>	3	\$ 36.68	\$ 110.04
20	rear side fender LH <i>X</i>	1	\$ 919.20	\$ 919.20
21	rear fender panel inner trim LH <i>cut</i>	1	\$ 218.04	\$ 218.04
22	fender panel inner trim clip <i>na</i> <i>6 pcs</i> <i>X</i>	1	\$ 3.20	\$ 38.40
23	rear door weatherstrip LH (panel) <i>X</i>	1	\$ 100.05	\$ 100.05
24	rear end panel <i>bt</i>	1	\$ 759.50	\$ 759.50
25	rear end panel garnishes <i>de</i>	1	\$ 207.11	\$ 207.11
26	end panel garnishes clip <i>na</i>	5	\$ 3.80	\$ 19.00
27	spare tyre panel <i>repair</i>	1	\$ 983.20	\$ 983.20
28	rear side fender shield RH <i>X</i>	1	\$ 103.15	\$ 103.15
29	rear tailamp panel L/R <i>LH-Repair</i> <i>1 pc</i> <i>X</i>	1	\$ 155.90	\$ 311.80
	Total list amount			\$ 8,380.76
	list 20% discount			\$ 1,676.15
	after discount			\$ 6,704.60
	Special Nett Item			
30	reverse sensor <i>?</i>	1	\$ 250.00	\$ 250.00 <i>200?</i>
31	rear end panel sealant <i>na</i> <i>na</i>	1	\$ 60.00	\$ 60.00
32	spare tyre panel sealant <i>na</i> <i>X</i>	1	\$ 60.00	\$ 60.00
33	side fender RH sealant	1	\$ 80.00	\$ 80.00 <i>X</i>
34	rear windscreen sealant	1	\$ 60.00	\$ 60.00 <i>X</i>
35	rear windscreen moulding	1	\$ 110.00	\$ 110.00 <i>X</i>
36	side fender quarter glass LH with moulding	1	\$ 430.00	\$ 430.00 <i>X</i>

37	PHV sticker (LTA)	1	\$ 30.00	\$ 30.00	X
38	rear reverse camera (infrared type)	1	\$ 300.00	\$ 300.00	X
	Labour				
A	to check rear electrical wiring system	-	\$ 60.00	\$ 60.00	30
B	to transfer boot compartment parts to new boot	-	\$ 100.00	\$ 100.00	60
C	to remove and reinstall rear interior trims, garnishes, etc				
	for necessary repair	-	\$ 200.00	\$ 200.00	60
D	to straighten, repair, realign rear exhaust silencer	-	\$ 100.00	\$ 100.00	X
E	to remove, replace and reinstall rear reverse sensor &				
	control unit with rear camera	-	\$ 200.00	\$ 200.00	60
F	to straighten, repair, realign on rear affected area and				
	replace damaged parts	-	\$ 1,800.00	\$ 1,800.00	800
G	to spray painting, blending on rear affected and adjacent	-	\$ 2,000.00	\$ 2,000.00	800
H	to apply anti-rust coating on new and affected panels	-	\$ 200.00	\$ 200.00	80
	total labour & s/n			\$ 6,040.00	
	lump-sum 20%			\$ 10,195.68	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

7 days

L/S

12/02/2020 @ 1530

Resurvey after repair