



FALCON-AIR

LONPAC INSURANCE BHD
100 BEACH ROAD #19-00
SHAW TOWER S189702Attention : Motor Claim Department
Contact : 62507388 Fax No. : 62962706

Estimate : ES003610

Date : 10/02/2020
Vehicle Num. : SKP3990H
Make/Model : HONDA JAZZ
Chassis/Eng# : JHMGD18507S225972
Accident Date : 08/02/2020
Claim No. :
Reference : TP NTUC VS LONPAC
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAILGATE / <i>DN</i>		849.60
2.	1	TAILGATE GLASS (BLACK) / <i>DR</i>		980.00
3.	1	TAILGATE LOCK / <i>ST</i>		109.40
4.	1	TAILGATE TRIMBOARD / <i>CR1</i>		118.60
5.	1	TAILGATE EMBLEM JAZZ / <i>MC</i>		58.80
6.	1	TAILGATE LOGO / <i>MC</i>		20.70
7.	1	TAILGATE WEATHERSTRIP / <i>?</i>		97.20
8.	1	TAILGATE GARNISH / <i>DR</i>		120.40
9.	1	WIPER MOTOR / <i>?</i>		250.50
10.	1	WIPER BLADE / <i>TN</i>		48.00
11.	1	WIPER ARM COVER / <i>M15</i>		12.50
12.	1	RH TAIL LAMP / <i>DR</i>		243.10
13.	1	REAR END PANEL / <i>?</i>		296.60
14.	1	REAR BUMPER / <i>DN</i>		490.80
15.	1	REAR BUMPER SIDE RETAINER RH / <i>DR</i>		12.00
16.	1	REAR END PANEL TOP GARNISH / <i>?</i>		56.10
List TotalS\$:				3,764.30
20.00% Discount S\$:				752.86
				3,011.44
SPECIAL NETT ITEMS :				
1.	1	REVERSE SENSOR / <i>SL1</i>		200.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD


(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

FALCON-AIR

LONPAC INSURANCE BHD
100 BEACH ROAD #19-00
SHAW TOWER S189702

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

Estimate : ES003610

Date : 10/02/2020
Vehicle Num. : SKP3990H
Make/Model : HONDA JAZZ
Chassis/Eng# : JHMGD18507S225972
Accident Date : 08/02/2020
Claim No. :
Reference : TP NTUC VS LONPAC
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	SEALANT / MC		40.00
3.	1	REAR NUMBER PLATE / CM		45.00
Special Nett Total S\$:				285.00
LABOUR :				
TO TRANSFER TAILGATE PARTS/MECHANISM				50.00
TO REMOVE/REFIX TAILGATE GLASS				100.00
TO REMOVE/REFIX REVERSE SENSOR & CHECK WIRING				100.00
TO RUSTPROOF & WATER LEAKAGE TEST				150.00
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER				950.00
TO CUT OUT/ REWELD REAR END PANEL, REPAIR REAR CHASSIS				
RH REAR FENDER, REAR FLOOR PANEL INCLUDES KNOCKING				
& REPLACEMENT OF PARTS				
Labour Total S\$:				2,100.00

SingDollars : Five Thousand Three Hundred Ninety-Six & Cents Forty-Four Only

E. & O.E.

Total S\$: 5,396.44

for FALCON AIR AUTO SERVICES PTE LTD



Steve (LKK) 11/2/20, 11.00am
5 dys
L/S
My MC Sy

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Date:

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)



FALCON-AIR

LONPAC INSURANCE BHD
100 BEACH ROAD #19-00
SHAW TOWER S189702

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

Estimate : ES003610

Date : 10/02/2020
Vehicle Num. : SKP3990H
Make/Model : HONDA JAZZ
Chassis/Eng# : JHMGD18507S225972
Accident Date : 08/02/2020
Claim No. :
Reference : TP NTUC VS LONPAC
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	SEALANT / <i>MC</i>		40.00
3.	1	REAR NUMBER PLATE / <i>CM</i>		45.00
Special Nett Total S\$:				285.00
LABOUR :				
TO TRANSFER TAILGATE PARTS/MECHANISM				50.00 ✓
TO REMOVE/REFIX TAILGATE GLASS				100.00 ✓
TO REMOVE/REFIX REVERSE SENSOR & CHECK WIRING				20 100.00
TO RUSTPROOF & WATER LEAKAGE TEST				30 150.00
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER				800 950.00
TO CUT OUT/ REWELD REAR END PANEL, REPAIR REAR CHASSIS				
RH REAR FENDER, REAR FLOOR PANEL INCLUDES KNOCKING				
& REPLACEMENT OF PARTS				600 750.00
Labour Total S\$:				2,100.00

SingDollars : Five Thousand Three Hundred Ninety-Six & Cents Forty-Four Only

E. & O.E.

Total S\$: 5,396.44



for FALCON AIR AUTO SERVICES PTE LTD

Steve (LKK)

nr R
11/2/20, 11.00am
5 dys
L/S
*My LK Sy***LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Acknowledged by Repairer

Signature: Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Date: Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg