



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

FWD/FC(SHC1007P)
DOA: 20/01/2020@2155

07/02/2020

MS FIRST CAPITAL INSURANCE LTD

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SKQ 9919 X - HONDA JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
CHASSIS NO: JHMGK5850FX202076 (2015)

1 pc	Rim	\$ 890.00
	LESS 20%	\$ 178.00
		<u>\$ 712.00</u>

Alignment

\$ 70.00

Labour to jacking, panel beating, repair and straighten
front bumper and front fender RH.

\$ 350.00

Putty and respray front bumper and front fender RH.

\$ 450.00

\$ 1,582.00

\$ 110.74

ADD 7% GST

\$ 1,692.74

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

Steve (LKK) Mr. Neil
8322 8813 12/2/20, 1.30pm
3 days
P/P
Ry Bk Sy

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: