



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

FWD/FC(SHC1007P)
DOA: 20/01/2020@2155

07/02/2020

MS FIRST CAPITAL INSURANCE LTD

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SKQ 9919 X - HONDA JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
CHASSIS NO: JHMGK5850FX202076 (2015)

1 pc	Rim ✓ CM	\$ 890.00
	LESS 20%	\$ 178.00
		\$ 712.00 ✓
	Alignment	\$ 70.00 60
	Labour to jacking, panel beating, repair and straighten front bumper and front fender RH.	\$ 350.00 300
	Putty and respray front bumper and front fender RH.	\$ 450.00 400
		\$ 1,582.00
		\$ 110.74 760
	ADD 7% GST	\$ 1,692.74

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

P - 712
L - 760
1472

Steve (LKK) Mr. Neil
8322 8813 12/2/20, 1:30pm
3 days
P/P
Ry Bcl Sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: