

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20002401/QDA3Q2

Date: 12/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800004823

Claimant
Vehicle No : SMB1418H **Insured Vehicle No :** EM323R

Date of Loss: 27/12/2019 **Nature of Claim:** TP **Claim No:** 9438537256SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB1418H	Engine No:	50334960563492
Make & Model:	MAN NL320F (A22), 10.5 D (M)	Chassis No:	WMAA22ZZ4D7002006
Reg. Date:	06/01/2014 (Man. Year: 2013)	Odometer:	541675 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,868.80	0.00	1,868.80	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,411.00	962.00	449.00	31.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	3,279.80	962.00	2,317.80	70.67
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 03/02/2020

Date Inspected: 03/02/2020 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 1.0 days

Adjuster: OI SUN PIN

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR ,CENTRE, FOR MAN A22 BUS	Repair	1,868.80 F	*- F
						F=Franchise part.
Total Parts (S\$)					1,868.80	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR REAR PORTION	New	795.00	530.00
2	TO PUTTY & RESPRAY	New	616.00	432.00
Gross Labour Cost (\$)			1,411.00	962.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >