



Case Details

Case Reference Number : BUS/12/19/5048

Company Type : SMRT Buses Ltd

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Type of Repair : Accident Repair

Estimation ID : EST-10189-ID

Accident Date and Time : 27/12/2019 08:08 AM

Vehicle Registration Number : SMB1418H

Assigned By : Claiming Case Owner Team

Vehicle Age(In Months) : 71

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Appro		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/
Standard	Main	Body	6010064	BUMPER:REAR,CENTRE,FOR MAN A22 BUS	1	1,868.80	1,868.80	100.00	0.00	Repair	1	0.00	Repa
Total Spare Part Cost												0.00	
Lump Sum Discount (%)												Lump Sum Dis (%)	0
Final Spare Part Cost												Final Sur Total	0.00

XR

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	795.00	530	
Total:			795.00	530.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	616.00	432	
Total:			616.00	432.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	0.00	0.00
Total Labour Cost	795.00	530.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spray Painting	616.00	432.00
Other	0.00	0.00
Overall Total	1,411.00	962.00
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	962.00
Surveyor Approved Amount		962.00
No of Repair Days*	2	1
Remarks	-	Surveyor Remarks
Surveyor Name		Sun Pin (LKK)
Signature		
Survey Date	22/01/2020	Save Clear

Repair day 1 day

P/P

After paint photo.

Sun Pin (LKK)

03/02/2020

TP without prejudice.