

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 28265

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0146/2020/NS
Date : 7-Feb-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Koh Zhan Yu
Address : Blk 244 Bukit Panjang Ring Road
Singapore 670244
Telephone : HP +65 90033995
Type of Claim : Own Damage Claims
Policy No. : 1800124130-01
Vehicle No : **SMF 367 G**
Model Code : Audi A3 Sedan 1.4 TF
Model / Year : Oct-18
Engine No : CZE 802018
Chassis No : WAUZZZ8V3J1082087
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Jan-20
Place of Accident : BKE After PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMF 367 G

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$	360.00	✓
2	To remove and reinstall rear parking aid. Check function.	S/N \$	280.00	✓
3	To remove and transfer both rhs front and rear door's multi-lock system and power window devices.	S/N \$	560.00 280.	
4	To remove and reinstall rear seats, back rest, ABCD pillar trims, roof liner, hat trays, carpets, curtain airbag and sill trims.	S/N \$	1,400.00	X
5	To remove and renew rhs quarter glass and rear windscreen for fender renewal.	S/N \$	600.00	X
SUB TOTAL LABOUR CHARGES		:	<u><u>\$ 3,200.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMF 367 G

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
6	To remove and reinstall rear wire harness for tail lights, fuse units, battery manager, fuse and relay trays, and electrical components.	S/N \$	1,400.00	X
7	To remove and reinstall rear seat, back rest, hat tray, ABCD pillar trims, luggage compartment trims, seat belts, dislodge roof liner and disemqage curtain airbaq etc.	S/N \$	1,400.00	X
8	To dismantle front bumper, rhs front fender, rhs front and rear doors and rear bumper cut out and weld rhs rear fender. Renew damaged panels including rhs headlight, align to position. Reinstall all parts removed.	\$	8,050.00	3000.
9	To respray front bumper, rhs front fender, rhs front and rear doors, rhs rear fender, sill panel, door entrance, roof channel, drain panel, end panelling and rear bumper. To carry out joint sealer works and stone chip treatment.	\$	7,600.00	4600.
10	To renew rhs front rim and carry out wheel alignment.	S/N \$	280.00	✓
11	To carry out diagnostic check.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 22,122.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 367 G

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Deformed</i>	\$ 1,894.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 176.00	+
3	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$ 36.00	+
4	FRONT FENDER - RH <i>Dented</i>	\$ 802.00	✓
5	FRONT FENDER BRACKET - RH <i>new</i>	\$ 26.00	✓
6	FRONT FENDER BRACKET - RH	\$ 36.00	✓
7	FRONT FENDER BRACE - RH <i>Bent</i>	\$ 90.00	✓
8	FRONT FENDER ATTACHMENT PARTS <i>?</i>	\$ 68.00	?
9	FRONT WHEEL HOUSING LINER - RH <i>Deformed</i>	\$ 159.00	✓
10	WHEEL HOUSING LINER ATTACHMENT PARTS <i>?</i>	\$ 84.00	?
11	FRONT FENDER INSULATION - RH <i>?</i>	\$ 40.00	?
12	FRONT FENDER CLOSING ELEMENT - RH <i>?</i>	\$ 31.00	?
13	LED HEADLIGHT - RH <i>cut</i>	\$ 5,193.00	✓
14	FRONT DOOR - RH <i>Dented</i>	\$ 2,375.00	✓
15	OUTER DOOR SEAL - RH <i>new</i>	NEC \$ 151.00	✓
16	BONDING AGENT <i>?</i>	NEC \$ 46.00	?
17	CLEANING SOLUTION <i>?</i>	NEC \$ 64.00	?
18	FRONT DOOR ATTACHMENT PARTS <i>Not new</i>	\$ 227.00	x
19	FRONT DOOR CATCH <i>new</i>	\$ 99.00	+
20	WINDOW REGULATOR - RH <i>new</i>	\$ 249.00	x
SUB TOTAL SPARE PARTS CHARGES		: \$ 11,846.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 367 G

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
21	REAR DOOR - RH <i>Repair</i>	\$	2,375.00	X
22	REAR DOOR OUTER SEAL	NEC \$	151.00	X
23	BONDING AGENT	NEC \$	46.00	X
24	CLEANING SOLUTION	NEC \$	64.00	X
25	REAR DOOR CATCH	\$	89.00	X
26	SIDE PANEL - RH <i>Repair</i>	\$	2,195.00	X
27	SIDE WINDOW - RH	\$	537.00	X
28	REAR WINDSCREEN	\$	766.00	X
29	PRIMER	2 \$	37.00	X
30	REAR BUMPER GUIDE SECTION - LH / RH	2 \$	30.00	X
31	FRONT ALUMINIUM RIM - RH	\$	666.00	✓
32	REAR WINDSCREEN SEALANT	S/N \$	200.00	X
33	1/4 GLASS SEALANT	S/N \$	100.00	X
34	ACRYLIC SEALANT	S/N \$	180.00	X
35	CAVITY WAX	S/N \$	140.00	X
36	STONE CHIP	S/N \$	180.00	X
37	METAL FILLER POWDER	S/N \$	280.00	X
38	SUNDRIES	S/N \$	1,000.00	?

TOTAL SPARE PARTS CHARGES	:	\$ 20,882.00
TOTAL LABOUR CHARGES	:	\$ 22,122.00
GRAND TOTAL	:	\$ 43,004.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 11/02/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 09 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant