

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 28824

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0152/2020/NS
Date : 10-Feb-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

3 days - 0k - jb 15 Apr 20

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Hitachi Capital Asia Pacific Pte Ltd
Address : 111 Somerset Road
#11-05
Singapore 238164
Telephone : HP +65 91015822
Type of Claim : Own Damage Claims
Policy No. : 1900159163
Vehicle No : **SMQ 210 S**
Model Code : Audi Q7 2.0 TFSI QU
Model / Year : Dec-17
Engine No : CYR 051022
Chassis No : WAUZZZ4M0JD014468
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Feb-20
Place of Accident : Towards Paya Lebar Road After PIE Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMQ 210 S

| S/n | Nature of Jobs | | Estimated Charges | Surveyor's Recommendations |
|-----------------------------|---|----------|--------------------|----------------------------|
| 1 | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid. | S/N \$ | 480.00 | \$ 480.00 |
| 2 | To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed. | \$ | 2,250.00 | \$ 600.00 |
| 3 | To respray front bumper, front bumper rhs spoiler, rhs front fender, both front wheel arch trims. | \$ | 3,500.00 | \$ 1,000.00 |
| 4 | To carry out diagnostic check. | S/N \$ | 192.00 | \$ 192.00 |
| TOTAL LABOUR CHARGES | | : | \$ 6,422.00 | \$ 2,272.00 |

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMQ 210 S

| S/N | Parts Description | Damaged Parts & Prices | |
|--------------------------------------|---|------------------------|--------------------|
| | | S/Nett | Remarks |
| 1 | FRONT BUMPER | \$ 2,449.00 | \$ 1,959.20 |
| 2 | FRONT BUMPER FIXING PARTS | \$ 420.00 | |
| 3 | FRONT BUMPER TOWING EYE COVER | \$ 37.00 | |
| 4 | FRONT BUMPER AIR GUIDE - RH | \$ 63.00 | |
| 5 | FRONT BUMPER END CAP - RH | \$ 34.00 | \$ 26.48 |
| 6 | FRONT BUMPER CLOSINGELEMENT - UPPER CENTRE | \$ 261.00 | \$ 208.40 |
| 7 | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE | \$ 194.00 | |
| 8 | FRONT BUMPER UNDERRUN BAR | \$ 759.00 | \$ 607.20 |
| 9 | FRONT BUMPER CLOSING ELEMENT | \$ 198.00 | \$ 158.80 |
| 10 | FRONT BUMPER FRONT SPOILER | \$ 199.00 | |
| 11 | FRONT BUMPER SPOILER - RH OUTER | \$ 41.00 | |
| 12 | RADIATOR GRILLE | \$ 2,327.00 | \$ 1,861.60 |
| 13 | RADIATOR GRILLE COVER | \$ 65.00 | \$ 51.44 |
| 14 | RADIATOR GRILLE INNER COVER | \$ 58.00 | |
| 15 | RADIATOR GRILLE COVER CAP | \$ 128.00 | |
| 16 | FRONT BUMPER AIR GUIDE GRILLE - RH | \$ 280.00 | \$ 224.00 |
| 17 | FRONT BUMPER END CAP - RH | \$ 32.00 | \$ 24.96 |
| 18 | RADIATOR GRILLE SPOILER - RH INNER | \$ 56.00 | \$ 44.48 |
| 19 | FRONT BUMPER CARRIER | \$ 817.00 | \$ 653.20 |
| 20 | FRONT BUMPER GUIDE SECTION - RH | \$ 41.00 | |
| SUB TOTAL SPARE PARTS CHARGES | | \$ 8,459.00 | \$ 5,819.76 |

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMQ 210 S

| S/N | Parts Description | Damaged Parts & Prices | | Remarks |
|----------------------------------|------------------------------------|------------------------|---------------------|--------------------|
| | | S/Nett | | |
| | | | | \$ 5,819.76 |
| 21 | FRONT BUMPER SUPPORT - LH / RH | 2 | \$ 68.00 | |
| 22 | FRONT BUMPER SIGHT SHIELD | | \$ 123.00 | |
| 23 | FRONT BUMPER FOAM FILLER PIECE | | \$ 161.00 | \$ 128.80 |
| 24 | CAUTION SIGN STICKER | NEC | \$ 13.00 | |
| 25 | HORN - RH HIGH TONE | | \$ 213.00 | |
| 26 | FRONT PARKING AID - INNER / OUTER | | TBC | \$ 83.54 |
| 27 | FRONT PARKING AID - SIDE | | TBC | |
| 28 | FRONT PARKING AID SEAL RING | 4 | \$ 14.00 | |
| 29 | FRONT WHEEL COVER - LH / RH | 2 | \$ 1,080.00 | \$ 863.20 |
| 30 | HEADLIGHT MOUNTING - RH | | \$ 112.00 | |
| 31 | LED HEADLIGHT | | \$ 9,356.00 | |
| 32 | LIFT CYLINDER - RH | | \$ 187.00 | |
| 33 | RADIATOR AIR GUIDE - RH | | \$ 27.00 | |
| 34 | RADIATOR AIR GUIDE - UPPER / LOWER | 2 | \$ 80.00 | |
| 35 | FRONT NO PLATE | S/N | \$ 40.00 | \$ 40.00 |
| 35a | ADDED PARTS - SEE ATTACHED | | \$ 594.00 | \$ 475.20 |
| 36 | SUNDRIES | | \$ 300.00 | |
| TOTAL SPARE PARTS CHARGES | | : | \$ 20,827.00 | \$ 7,410.50 |
| TOTAL LABOUR CHARGES | | : | \$ 6,422.00 | \$ 2,272.00 |
| GRAND TOTAL | | : | \$ 27,249.00 | \$ 9,682.50 |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.