

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 28824

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0152/2020/NS
Date : 10-Feb-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Hitachi Capital Asia Pacific Pte Ltd
Address : 111 Somerset Road
#11-05
Singapore 238164
Telephone : HP +65 91015822
Type of Claim : Own Damage Claims
Policy No. : 1900159163
Vehicle No : **SMQ 210 S**
Model Code : Audi Q7 2.0 TFSI QU
Model / Year : Dec-17
Engine No : CYR 051022
Chassis No : WAUZZZ4M0JD014468
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Feb-20
Place of Accident : Towards Paya Lebar Road After PIE Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMQ 210 S

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed. ✓	\$ 2,250.00 600 ✓	✓
3	To respray front bumper, front bumper rhs spoiler, rhs front fender, both front wheel arch trims. ✓✓	\$ 3,500.00 1000 ✓	600 Budget 400 Arch Trim x 2
4	To carry out diagnostic check.	S/N \$ 192.00 ✓✓	
TOTAL LABOUR CHARGES		: <u>\$ 6,422.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMQ 210 S

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>Del'd</i>	\$	2,449.00 ✓	1959 20
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$	420.00 *	
3	FRONT BUMPER TOWING EYE COVER <i>new</i>	\$	37.00 *	
4	FRONT BUMPER AIR GUIDE - RH <i>Not new</i>	\$	63.00 X	
5	FRONT BUMPER END CAP - RH <i>missing</i>	\$	34.00 ✓	2648
6	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>could</i>	\$	261.00 +	20840
7	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>could</i>	\$	194.00 +	
8	FRONT BUMPER UNDERRUN BAR <i>Del'd</i>	\$	759.00 ✓	13320
9	FRONT BUMPER CLOSING ELEMENT <i>could</i>	\$	198.00 +	15880
10	FRONT BUMPER FRONT SPOILER <i>Not new</i>	\$	199.00 X	
11	FRONT BUMPER SPOILER - RH OUTER <i>By</i>	\$	41.00 X	
12	RADIATOR GRILLE <i>could</i>	\$	2,327.00 ✓	126130
13	RADIATOR GRILLE COVER <i>could</i>	\$	65.00 ✓	5144
14	RADIATOR GRILLE INNER COVER <i>Not new</i>	\$	58.00 X	
15	RADIATOR GRILLE COVER CAP <i>Not new</i>	\$	128.00 X	
16	FRONT BUMPER AIR GUIDE GRILLE - RH <i>missing</i>	\$	280.00 -	234
17	FRONT BUMPER END CAP - RH <i>Del'd</i>	\$	32.00 ✓	2496
18	RADIATOR GRILLE SPOILER - RH INNER <i>could</i>	\$	56.00 -	4448
19	FRONT BUMPER CARRIER <i>Best</i>	\$	817.00 ✓	65320
20	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$	41.00 T	
SUB TOTAL SPARE PARTS CHARGES			\$ 8,459.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMQ 210 S

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
21	FRONT BUMPER SUPPORT - LH / RH <i>Not new</i>	2	\$ 68.00	X
22	FRONT BUMPER SIGHT SHIELD <i>Not new</i>		\$ 123.00	X
23	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>		\$ 161.00	✓ 127 70
24	CAUTION SIGN STICKER <i>new</i>	NEC	\$ 13.00	+
25	HORN - RH HIGH TONE <i>new</i>		\$ 213.00	+
26	FRONT PARKING AID - INNER / OUTER <i>2 pieces damaged</i>		TBC	? 83 54
27	FRONT PARKING AID - SIDE <i>Not new</i>		TBC	X
28	FRONT PARKING AID SEAL RING <i>Not new</i>	4	\$ 14.00	X
29	FRONT WHEEL COVER - LH / RH <i>new</i>	2	\$ 1,080.00	✓ 863 20
30	HEADLIGHT MOUNTING - RH <i>Not new</i>		\$ 112.00	X
31	LED HEADLIGHT <i>Not new</i>		\$ 9,356.00	X
32	LIFT CYLINDER - RH <i>new</i>		\$ 187.00	X
33	RADIATOR AIR GUIDE - RH <i>Not new</i>		\$ 27.00	X
34	RADIATOR AIR GUIDE - UPPER / LOWER <i>Not new</i>	2	\$ 80.00	X
35	FRONT NO PLATE <i>Dented</i>	S/N	\$ 40.00	✓ 40
36	SUNDRIES <i>Not new</i>		\$ 300.00	X
TOTAL SPARE PARTS CHARGES		:	\$ 20,233.00	
TOTAL LABOUR CHARGES		:	\$ 6,422.00	
GRAND TOTAL		:	\$ 26,655.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Edwin G
Surveyed Date : 11/02/20
Authorised Date :
Excess Cost :
Liability :
Remarks : All Authorised, 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

hence notify
the following:
after spray painting
part(s) during resurvey
subject to confirmation
is on a "Without Prejudice"
is allowed
must be resurveyed
approval from Insurance

Authorised by Repairer
Signature:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0152/2020/NS 17-Mar-20 Glory Tan 1 of 1 SMQ 210 S Audi Q7 2.0 TFSI QU
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Wiring set for front bumper. <i>lit.</i>	\$ 594.00	\$ 475.20 ✓
TOTAL		\$ 594.00	\$ 475.20

For Premium Automobiles Pte Ltd



Authorised Signature