

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Steve 11/2/20

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0150/2020/NS
Date 11-Feb-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SLQ 8547 E
Model No A4 Sedan 1.4 TFSI S

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Rear fender LHS / 00	\$ 2,518.00	\$2014.40
2	Rear windscreen / n/c	\$ 1,085.00	\$868.00
3	Primer / n/c	\$ 19.00	\$14.80
4	1/4 glass rear LHS / n/c	\$ 579.00	\$463.20
5	Metal filler powder / n/c	\$ 280.00	\$280.00
6	Rear windscreen sealant / n/c	\$ 200.00	\$200.00
7	1/4 glass rear LHS sealant / n/c	\$ 100.00	\$100.00
		<u>\$ 4,781.00</u>	

Labours

1	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. Inspect for damage and renew where necessary. phh	S/N \$ 1,400.00	\$1400.00	X Repeated
2	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag and etc. phh	S/N \$ 1,400.00	\$1400.00	
3	To renew rear windscreen and lhs 1/4 glass to facilitate fender renewal.	S/N \$ 600.00	\$600.00	
4	To install solar film for rear windscreen.	S/N \$ 400.00	\$400.00	
5	To cut out and weld lhs rear fender. 500x6	\$ 4,200.00	3000	\$3000.00
6	To respray lhs rear fender, lhs sill panel, 550x2.5 roof channel, door entrances, and drain channel.	\$ 3,250.00	1375	\$1375.00

Labours total	\$ 11,250.00
Parts total	\$ 4,781.00
GRAND TOTAL	\$ 16,031.00

For Premium Automobiles Pte Ltd

Authorised Signature