

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 28852

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0153/2020/NS
Date : 11-Feb-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tan Meng Khai Ivan
Address : 100 Gerald Drive
#04-89
Singapore 798592
Telephone : HP +65 97496004
Type of Claim : Own Damage Claims
Policy No. : 1800071832
Vehicle No : **SMA 202 A**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Jun-18
Engine No : CHZ 439400
Chassis No : WAUZZZ8V5J1056400
Mileage : 17372
Date In : 8-Feb-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Feb-20
Place of Accident : Junction Of Sengkang East Dr & Sengkang East Ave

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMA 202 A

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 //	
2	To remove and renew aircond condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 X	
3	To dismantle and renew front bumper, bonnet and rhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. 520	\$ 4,550.00 1250 /	
4	To respray front bumper and bonnet. 550	\$ 2,000.00 1100 /	
5	To carry out diagnostic check.	S/N \$ 192.00 //	
SUB TOTAL LABOUR CHARGES		: \$ 8,302.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 202 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER ✓ DR	\$ 1,894.00	1515.20
2	FRONT BUMPER FIXING PARTS ✗ X NM	\$ 176.00	X
3	FRONT BUMPER GUIDE SECTION - RH ✓ MIS	\$ 36.00	28.64
4	FRONT BUMPER GRILLE - CENTRE ? ✓ DR	\$ 151.00	120.40 ✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ? ✓ DR	\$ 505.00	404 ✓
6	FRONT BUMPER CLOSING ELEMENT - RH ? ✓ DR	\$ 280.00	223.60 ✓
7	FRONT BUMPER COVER TRIM - RH ✓ MIS	\$ 153.00	120.40
8	WHEEL HOUSING LINER ADAPTER - RH ✓ MIS	\$ 36.00	28.16
9	RADIATOR GRILLE ✓ DR	\$ 1,338.00	1070.40
10	RADIATOR GRILLE CLOSING ELEMENT ? ✓ DR	\$ 180.00	143.60 ✓
11	FRONT BUMPER AIR GUIDE GRILLE - RH ✓ MIS	\$ 177.00	141.20
12	FRONT BUMPER SIDE REINFORCEMENT BEAM ✓ DD	\$ 681.00	544.80
13	FRONT BUMPER FOAM FILLER PIECE ✓ DR	\$ 178.00	142.40
14	FOAM FILLER PIECE COVER ✓ DR	\$ 115.00	91.60
15	SIGNAL HORN RETAINER - RH LOW TONE ✗ NM	\$ 188.00	
16	BONNET ✓ DD	\$ 2,988.00	2390.40
17	BONNET ATTACHMENT PARTS ✗ NM	\$ 155.00	
18	BONNET GAS FILLED STRUT ✗ NM	\$ 112.00	
19	BONNET SAFETY CATCH ✗ NM	\$ 84.00	
20	BONNET STRIKER - RH ✗ NM	\$ 104.00	
SUB TOTAL SPARE PARTS		: \$ 9,531.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 202 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
21	BONNET EDGE PROTECTION / <i>mc</i>	\$ 26.00	<i>20.80</i>
22	BONNET CATCH HOOK X <i>MM</i>	\$ 60.00	
23	BONNET LID LOCK X <i>MM</i>	\$ 202.00	
24	BONNET BOWDEN CABLE - CENTRE X <i>MM</i>	\$ 54.00	
25	LED HEADLIGHT - RH / <i>CH</i>	\$ 5,193.00	<i>4154.40</i>
26	LIFT CYLINDER - RH ? X <i>MM</i>	\$ 134.00	X
27	HEADLIGHT HOSE ? X <i>MM</i>	\$ 64.00	X
28	LOCK CARRIER ? X <i>MM</i>	\$ 685.00	X
29	AIRCON CONDENSER X <i>MM</i>	\$ 519.00	
30	RADIATOR X <i>MM</i>	\$ 932.00	
31	ADDITIONAL RADIATOR X <i>MM</i>	\$ 851.00	
32	READY MIX COOLANT X <i>MM</i>	\$ 86.00	
33	RADIATOR AIR GUIDE - LH / (RH) ? / <i>DR</i> 2	\$ 46.00	<i>18.16</i> ✓
34	RADIATOR AIR GUIDE - UPPER CENTRE ? X <i>MM</i>	\$ 12.00	X
35	CAUTION SIGN STICKER <i>mc</i> / <i>mc</i>	NEC \$ 13.00	<i>10.24</i> ✓
36	FRONT NO PLATE / <i>JT</i>	S/N \$ 40.00	✓
37	SUNDRIES ? / <i>mc</i>	\$ 300.00	<i>240</i> ✓
TOTAL SPARE PARTS CHARGES		: \$ 18,748.00	
TOTAL LABOUR CHARGES		: \$ 8,302.00	
GRAND TOTAL		: \$ 27,050.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Steve (LKK)

[Signature]
13/2/2020

OD - Not Author (Revert)

11/2/20, 2.00pm

P/P

Ry AE SH
BEL

78 days
Excess - ?

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

- LKK Auto Consultants hence notify
the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0153/2020/NS

Date

20-Feb-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMA 202 A

Model No

Audi A3 Sedan 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

- | | | | |
|---|------------------------------------|-----------|--------|
| 1 | Wheel housing liner RHS front / DR | \$ 159.00 | 127.20 |
| 2 | Noise insulation - DR | \$ 244.00 | 195.20 |
| 3 | Sticker for air conditioner - MK | \$ 7.00 | 5.36 |
| 4 | Rhs front fender / DD | \$ 802.00 | 641.20 |

Labours

- | | | | |
|---|------------------------------|-------------|-------|
| 1 | To renew rhs front fender. | \$ 1,050.00 | 500 ✓ |
| 2 | To respray rhs front fender. | \$ 1,000.00 | 550 ✓ |

TOTAL

\$ 3,262.00

For Premium Automobiles Pte Ltd

Steve
20/2/20

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 28852

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0153/2020/NS
Date : 11-Feb-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tan Meng Khai Ivan
Address : 100 Gerald Drive
#04-89
Singapore 798592
Telephone : HP +65 97496004
Type of Claim : Own Damage Claims
Policy No. : 1800071832
Vehicle No : **SMA 202 A**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Jun-18
Engine No : CHZ 439400
Chassis No : WAUZZZ8V5J1056400
Mileage : 17372
Date In : 8-Feb-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Feb-20
Place of Accident : Junction Of Sengkang East Dr & Sengkang East Ave

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMA 202 A

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove and renew aircond condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 ✓	
3	To dismantle and renew front bumper, bonnet and rls headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. <i>550</i>	\$ 4,550.00 <i>1250</i>	
4	To respray front bumper and bonnet. <i>550</i>	\$ 2,000.00 <i>1100</i>	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
SUB TOTAL LABOUR CHARGES		: \$ 8,302.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 202 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER ✓ DR	\$	1,894.00
2	FRONT BUMPER FIXING PARTS ✓ MC	\$	176.00
3	FRONT BUMPER GUIDE SECTION - RH ✓ MIS	\$	36.00
4	FRONT BUMPER GRILLE - CENTRE ? ✓ DR	\$	151.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ? ✓ DR	\$	505.00
6	FRONT BUMPER CLOSING ELEMENT - RH ? ✓ DR	\$	280.00
7	FRONT BUMPER COVER TRIM - RH ✓ MIS	\$	153.00
8	WHEEL HOUSING LINER ADAPTER - RH ✓ MIS	\$	36.00
9	RADIATOR GRILLE ✓ DR	\$	1,338.00
10	RADIATOR GRILLE CLOSING ELEMENT ? ✓ DR	\$	180.00
11	FRONT BUMPER AIR GUIDE GRILLE - RH ✓ MIS	\$	177.00
12	FRONT BUMPER SIDE REINFORCEMENT BEAM ✓ DD	\$	681.00
13	FRONT BUMPER FOAM FILLER PIECE ✓ DR	\$	178.00
14	FOAM FILLER PIECE COVER ✓ DR	\$	115.00
15	SIGNAL HORN RETAINER - RH LOW TONE ✕	\$	188.00
16	BONNET ✓ DD	\$	2,988.00
17	BONNET ATTACHMENT PARTS ✕	\$	155.00
18	BONNET GAS FILLED STRUT ✕	\$	112.00
19	BONNET SAFETY CATCH ✕	\$	84.00
20	BONNET STRIKER - RH ✕	\$	104.00

SUB TOTAL SPARE PARTS

: \$ 9,531.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 202 A

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/NETT		
21	BONNET EDGE PROTECTION ✓ / MC	\$	26.00	
22	BONNET CATCH HOOK ✗	\$	60.00	
23	BONNET LID LOCK ✗	\$	202.00	
24	BONNET BOWDEN CABLE - CENTRE ✗	\$	54.00	
25	LED HEADLIGHT - RH ✓ / CV	\$	5,193.00	
26	LIFT CYLINDER - RH ?	\$	134.00	
27	HEADLIGHT HOSE ?	\$	64.00	
28	LOCK CARRIER ?	\$	685.00	
29	AIRCON CONDENSER ✗	\$	519.00	
30	RADIATOR ✗	\$	932.00	
31	ADDITIONAL RADIATOR ✗	\$	851.00	
32	READY MIX COOLANT ✓	\$	86.00	
33	RADIATOR AIR GUIDE - LH / RH ? / DR 2	\$	46.00	
34	RADIATOR AIR GUIDE - UPPER CENTRE ?	\$	12.00	
35	CAUTION SIGN STICKER ✗ / MC	NEC \$	13.00	
36	FRONT NO PLATE ✓ / BT	S/N \$	40.00	
37	SUNDRIES ?	\$	300.00	

TOTAL SPARE PARTS CHARGES	:	\$ 18,748.00
TOTAL LABOUR CHARGES	:	\$ 8,302.00
GRAND TOTAL	:	\$ 27,050.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Steve (LKK)

OD - Not Authorised (Reval)

11/2/20, 2.00pm

P/P

Ry AE SM
BEL

78 days

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 28852

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0153/2020/NS
Date : 11-Feb-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Steve

7 days exclude 1 Sunday - ok

jb 18 Mar 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tan Meng Khai Ivan
Address : 100 Gerald Drive
#04-89
Singapore 798592
Telephone : HP +65 97496004
Type of Claim : Own Damage Claims
Policy No. : 1800071832
Vehicle No : **SMA 202 A**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Jun-18
Engine No : CHZ 439400
Chassis No : WAUZZZ8V5J1056400
Mileage : 17372
Date In : 8-Feb-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Feb-20
Place of Accident : Junction Of Sengkang East Dr & Sengkang East Ave

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMA 202 A

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00 ✓
2	To remove and renew aircond condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	na
3	To dismantle and renew front bumper, bonnet and rhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$	4,550.00	\$ 1,250.00 ✓
4	To respray front bumper and bonnet.	\$	2,000.00	\$ 1,100.00 ✓
5	Added labours - see attached	\$	2,050.00	\$ 1,050.00 ✓
6	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00 ✓
SUB TOTAL LABOUR CHARGES		:	\$ 10,352.00	\$ 3,952.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 202 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
1	FRONT BUMPER	\$ 1,894.00	\$ 1,515.20
2	FRONT BUMPER FIXING PARTS	\$ 176.00	
3	FRONT BUMPER GUIDE SECTION - RH	\$ 36.00	\$ 28.64
4	FRONT BUMPER GRILLE - CENTRE	\$ 151.00	\$ 120.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 505.00	\$ 404.00
6	FRONT BUMPER CLOSING ELEMENT - RH	\$ 280.00	\$ 223.60
7	FRONT BUMPER COVER TRIM - RH	\$ 153.00	\$ 122.40
8	WHEEL HOUSING LINER ADAPTER - RH	\$ 36.00	\$ 28.16
9	RADIATOR GRILLE	\$ 1,338.00	\$ 1,070.40
10	RADIATOR GRILLE CLOSING ELEMENT	\$ 180.00	\$ 143.60
11	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 177.00	\$ 141.20
12	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$ 681.00	\$ 544.80
13	FRONT BUMPER FOAM FILLER PIECE	\$ 178.00	\$ 142.40
14	FOAM FILLER PIECE COVER	\$ 115.00	\$ 91.60
15	SIGNAL HORN RETAINER - RH LOW TONE	\$ 188.00	
16	BONNET	\$ 2,988.00	\$ 2,390.40
17	BONNET ATTACHMENT PARTS	\$ 155.00	
18	BONNET GAS FILLED STRUT	\$ 112.00	
19	BONNET SAFETY CATCH	\$ 84.00	
20	BONNET STRIKER - RH	\$ 104.00	
SUB TOTAL SPARE PARTS		\$ 9,531.00	\$ 6,966.80

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 202 A

S/N	Parts Description		<u>Damage Parts & Prices</u>	
			S/NETT	Remarks
		c/f		\$ 6,966.80
21	BONNET EDGE PROTECTION		\$ 26.00	\$ 20.80
22	BONNET CATCH HOOK		\$ 60.00	
23	BONNET LID LOCK		\$ 202.00	
24	BONNET BOWDEN CABLE - CENTRE		\$ 54.00	
25	LED HEADLIGHT - RH		\$ 5,193.00	\$ 4,154.40
26	LIFT CYLINDER - RH		\$ 134.00	
27	HEADLIGHT HOSE		\$ 64.00	
28	LOCK CARRIER		\$ 685.00	
29	AIRCON CONDENSER		\$ 519.00	
30	RADIATOR		\$ 932.00	
31	ADDITIONAL RADIATOR		\$ 851.00	
32	READY MIX COOLANT		\$ 86.00	
33	RADIATOR AIR GUIDE - LH / RH	2	\$ 46.00	\$ 18.16
34	RADIATOR AIR GUIDE - UPPER CENTRE		\$ 12.00	
35	CAUTION SIGN STICKER	NEC	\$ 13.00	\$ 10.24
36	FRONT NO PLATE	S/N	\$ 40.00	\$ 40.00
37	Added parts - see attached		\$ 1,212.00	\$ 968.96
38	SUNDRIES		\$ 300.00	\$ 2.40
TOTAL SPARE PARTS CHARGES			\$ 19,960.00	\$ 12,181.76
TOTAL LABOUR CHARGES			\$ 10,352.00	\$ 3,952.00
GRAND TOTAL			\$ 30,312.00	\$ 16,133.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0153/2020/NS 20-Feb-20 Glory Tan 1 of 1 SMA 202 A Audi A3 Sedan 1.0 TFSI 8V	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	Wheel housing liner RHS front	\$ 159.00	\$	127.20
2	Noise insulation	\$ 244.00	\$	195.20
3	Sticker for air conditioner	\$ 7.00	\$	5.36
4	Rhs front fender	\$ 802.00	\$	641.20
		\$ 1,212.00	\$	968.96
<u>Labours</u>				
1	To renew rhs front fender.	\$ 1,050.00	\$	500.00
2	To respray rhs front fender.	\$ 1,000.00	\$	550.00
	Labour	\$ 2,050.00	\$	1,050.00
	Partd	\$ 1,212.00	\$	968.96
	TOTAL	\$ 4,474.00	\$	2,018.96

For Premium Automobiles Pte Ltd

Authorised Signature