

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20002416/EVF3E2

**Date:** 03/06/2020

#### REFERENCE

Insured/Claimant: MYTNIK-GONTA VADIM ANDREIVICH Policy No: 2100481218  
Date of Loss: 09/02/2020 Nature of Claim: OD Claim No: 1622854770SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKJ5859Z**  
Make & Model: AUDI Q7, 2.0 TFSI QU (A) Engine No: CYR012909  
Reg. Date: 30/08/2016 (Man. Year: 2016) Chassis No: WAUZZZ4M0GD060343  
Colour: White Odometer: 47928 km  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$169,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

#### CONDITION OF TYRES

Front Tyre Size: 255/55 R19 Rear Tyre Size: 255/55 R19  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	24,044.00	6,956.24	17,087.76	71.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,012.00	3,032.00	2,980.00	49.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>30,056.00</b>	<b>9,988.24</b>	<b>20,067.76</b>	<b>66.77</b>
<b>- Excess (S\$)</b>	<b>1,000.00</b>	<b>1,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>29,056.00</b>	<b>8,988.24</b>	<b>20,067.76</b>	<b>69.07</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,033.92</b>	<b>629.18</b>	<b>1,404.74</b>	<b>69.07</b>
<b>Nett Amount (S\$)</b>	<b>31,089.92</b>	<b>9,617.42</b>	<b>21,472.50</b>	<b>69.07</b>

#### INSPECTION

Date of Assignment: 12/02/2020

Date Inspected: 11/02/2020 Inspected At:

24 BENOI SECTOR

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LID	Dented	4,516.00 FS	*3,612.80 FS
2	1		*REAR LID ATTACHMENT PARTS	Not Necessary	146.00 FS	*- FS
3	2		*REAR LID HINGE - LH / RH	Not Necessary	290.00 FS	*- FS
4	2		*REAR LID DRIVE UNIT - LH / RH	Not Necessary	3,414.00 FS	*- FS
5	1		*TAILGATE CLOSING AID MOTOR	Not Necessary	855.00 FS	*- FS
6	1		*REAR LID LOCK	Not Necessary	239.00 FS	*- FS
7	1		*BONNET COVER CAP ANTI THEFT GUARD	Not Necessary	14.00 FS	*- FS
8	1		*REAR LID BOWDEN CABLE	Not Necessary	52.00 FS	*- FS
9	1		*FLAP LOCK COVER CAP	Not Necessary	12.00 FS	*- FS
10	1		*REAR LID LOCK STRIKER	Not Necessary	81.00 FS	*- FS
11	2		*REAR LID GAS FILLED STRUT	Not Necessary	224.00 FS	*- FS
12	2		*REAR LID HINGE COVER - LH / RH	Not Necessary	42.00 FS	*- FS
13	1		*REAR LID FLAP GASKET	Not Necessary	275.00 FS	*- FS
14	1		*REAR LID COVER	Not Necessary	156.00 FS	*- FS
15	1		*LID LOCK PUSH BUTTON	Not Necessary	1,267.00 FS	*- FS
16	1		*PACKING ADHESIVE	Necessary	18.00 FS	*14.24 FS
17	1		*AUDI EMBLEM	Necessary	117.00 FS	*93.20 FS
18	1		*Q7 INSCRIPTION	Necessary	90.00 FS	*71.76 FS
19	1		*TFSI INSCRIPTION	Necessary	90.00 FS	*71.76 FS
20	1		*QUATTRO INSCRIPTION	Necessary	90.00 FS	*71.76 FS
21	2		*REAR SPOILER - LH / RH	Necessary	436.00 FS	*348.00 FS
22	1		*REAR WINDSCREEN	Broken	1,105.00 FS	*884.00 FS
23	1		*PRIMER	Necessary	19.00 FS	*14.80 FS
24	1		*REAR LID SPOILER	Not Necessary	2,147.00 FS	*- FS
25	1		*SET FOAM STRIPS	Not Necessary	130.00 FS	*- FS
26	1		*SET SPOILER FIXING	Not Necessary	59.00 FS	*- FS
27	1		*WIPER ARM	Cut	93.00 FS	*74.00 FS
28	1		*WIPER BLADE	Not Necessary	26.00 FS	*- FS
29	1		*WIPER MOTOR	Broken	433.00 FS	*346.40 FS
30	1		*WIPER CAP	Cut	18.00 FS	*14.32 FS
31	1		*WATER JET	Not Necessary	31.00 FS	*- FS
32	1		*SET BEARING BUSHES	Not Necessary	48.00 FS	*- FS
33	2		*LED TAIL LIGHT - LH / RH	Not Necessary	3,612.00 FS	*- FS
34	2		*LED LICENSE PLATE LIGHT	Not Necessary	108.00 FS	*- FS
35	1		*ADDITIONAL BRAKE LIGHT	Not Necessary	221.00 FS	*- FS
36	1		*REAR LID TRIM PANEL	Cut	1,164.00 FS	*931.20 FS
37	2		*REAR LID TRIM PANEL - LH / RH	Cut	260.00 FS	*208.00 FS
38	1		*SIDE GATE TRIM - RH	Not Necessary	130.00 FS	*- FS
39	1		*BOOT COVER DRIVE UNIT	Not Necessary	1,476.00 FS	*- FS
40	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
41	1		*REAR NO PLATE	Not Necessary	40.00 FS	*- FS
42	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 24,044.00 6,956.24**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TOW FROM SCENE OF ACCIDENT	New	280.00	0.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY	New	480.00	480.00
3	TO RENEW REAR WINDSCREEN	New	480.00	480.00
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	400.00
5	TO DISMANTLE AND RENEW REAR LID. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,350.00	600.00
6	TO RESPRAY REAR LID, HINGES AND REAR LID TOP SPOILER	New	2,550.00	600.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO CARRY OUT VACUUM TO CLEAN UP THE REAR STORAGE COMPARTMENT	New	280.00	280.00
<b>Gross Labour Cost (S\$)</b>			<b>6,012.00</b>	<b>3,032.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >