

Date: 14.02.2020
Vehicle No: SJF657E
Model: FORD FOCUS
Chassis: WF05XXGCC5FK32680-2015
Reg.Year: 2015

Third Party Insurer: AIG
Third Party Veh No: SLG4403R
Date of Accident: 07.02.2020

*Not Authorized
11 Day @ 5150/hr
Running After Repair 5 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>1422</i>	1		<i>Pr</i> \$2,347.60
2	REAR TAILGATE "FOCUS" EMBLEM <i>86</i>	1		<i>Pr</i> \$112.00
3	REAR WINDSCREEN RUBBER	1		<i>Pr</i> \$112.00
4	REAR TAILGATE INNER TRIM CLIPS	8	\$6.50	<i>Pr</i> \$52.00
5	REAR BUMPER <i>1320</i>	1		<i>CM</i> \$1,972.60
6	REAR BUMPER CLIPS	10	<i>Pr</i> \$5.80	<i>Pr</i> \$58.00
7	REAR BUMPER LOWER LID COVER <i>685</i>	1		<i>Pr</i> \$762.00
8	REAR BUMPER SIDE BRACKET LH	1		<i>Pr</i> \$149.00
9	REAR BUMPER SIDE BRACKET RH	1		<i>R</i> \$149.00
10	REAR BUMPER UPPER BRACKET LH	1		<i>R</i> \$126.00
11	REAR BUMPER UPPER BRACKET RH	1		<i>R</i> \$126.00
12	REAR BUMPER REFLECTOR LH	1		<i>CM</i> \$192.80
13	REAR BUMPER FIXING COVER	1		<i>Pr</i> \$60.00
14	REAR BUMPER INNER CENTER RETAINER GUIDE	1		<i>Pr</i> \$246.00
15	REAR TAIL LAMP LH <i>850</i>	1		<i>CM</i> \$1,216.00
16	REAR QUARTER PANEL LINER LH	1		<i>Pr</i> \$610.50
17	REAR QUARTER PANEL LINER RH	1		<i>Pr</i> \$610.50
18	REAR END PANEL	1		REPAIR
19	REAR BUMPER REINFORCEMENT	1		REPAIR
20	REAR QUARTER PANEL LH	1		REPAIR
SUB TOTAL				\$8,902.00
LESS 20%				-\$1,780.40
PARTS TOTAL				\$7,121.60

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>Pr</i> \$60.00
2	REAR WINDSCREEN STOPPER	2	\$15.00	<i>Pr</i> \$30.00
3	REAR BUMPER REVERSE SENSOR	1		<i>Pr</i> \$350.00
S/N TOTAL				\$440.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 14.02.2020
Vehicle No: SJF657E
Model: FORD FOCUS
Chassis: WF05XXGCC5FK32680-2015
Reg.Year: 2015

Third Party Insurer: AIG
Third Party Veh No: SLG4403R
Date of Accident: 07.02.2020

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE,REPLACE,REPAIR,READJUST,REAR ACCIDENT AREA & ETC	\$600.00	500
LABOUR CHARGES TO REMOVE,REPLACE,REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE	\$150.00	120
LABOUR CHARGES TO REMOVE,REPLACE,REFIX REAR BUMPER SENSOR & ETC	\$80.00	60
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATION	\$120.00	60
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER,REAR TAILGATE,REAR END PANEL,REAR QUARTER PANEL LH & ETC.	\$800.00	720
TO CHECK WIRING & ELECTRICAL WIRING SYSTEM.	\$60.00	20
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$200.00	300
TO DIAGNOSE FAULTY CODE & RESET MEMORY.	\$150.00	X
LABOUR TOTAL		\$2,160.00 980

ONG

TOTAL

\$9,281.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 14.02.2020
 Vehicle No: SJF657E
 Model: FORD FOCUS
 Chassis: WF05XXGCC5FK32680-2015
 Reg.Year: 2015

Third Party Insurer: AIG
 Third Party Veh No: SLG4403R
 Date of Accident: 07.02.2020

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER REINFORCEMENT <i>480</i>	1		<i>121</i> \$967.40 ✓
SUB TOTAL				\$967.40
LESS 20%				-\$193.48
PARTS TOTAL				\$773.92 ✓

Finalise:

Parts: \$5984.40

Supp: \$773.92

Nett: \$240.00

Labour: \$980

Jump Sum: \$7978.32 - 20% (#1595.66) = \$6382.66

↓

\$6300.00

24/2/2020

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

