

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 54424
Date Estimated : 10/02/2020
Prepared By : Shukhaizi Bin Misbah

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Kuah Ann Thye (Ke Antai)
14 Brompton Road

Singapore 799894

- ACCOUNT - 115
United Overseas Insurance Ltd
3 Anson Road #28-01 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP6553S	WBA3A16060NS37826	30/09/2014	316iA/4	0

DESCRIPTION

To replace front bumper, front bonnet, front left fender,
front left door, front left wheelhouse, front left side /h 850
skirt and front left pillar

VALUE
4,250.00

2975

painting front bumper, front bonnet, front left fender,
front left door, front left side skirt, front left
wheelhouse and side pillar.

3811

6,123.00

To replace front left pneumatic spring strut
including reset and checks function of ride level height
control for proper function.

X ?

516.00

To replace tyre and wheel rim including balancing. (1x).

94.00

To check steering geometry and conduct wheel alignment
according to BMW specification (1X)

531.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150

177.00

sundries

150 ✓ ?

150.00

Total Labour 1: 11,841.00

DESCRIPTION

HEX NUT M10 CHROME FREE ? X NN
HEX SCREW WITH COLLAR M12X1.5X85 ? X NN
LH TENSION STRUT W/HYDRAULIC MOUNT ? ✓ BT
COLLAR NUT M12X1.5X45 ? X NN
SPHERICAL COLLAR SCREW M12X1.25X45 ? ✓ NEC
WHEEL HUB WITH BEARING FRT ? ✓ BT
FRT LH CARRIER ? ✓ BT
FRT SWING SUPPORT ? ✓ BT
HEXAGON SCREW WITH FLANGE M10X85 ? X NN
STABILIZER FRT WITH RUBBER MOUNTING ? X NN

QTY	PRIC	VALUE
1	1.11	1.11
1	8.05	8.05
1	271.15	271.15
4	7.65	30.60
4	8.05	32.20
1	484.55	484.55
1	463.45	463.45
1	99.60	99.60
1	6.75	6.75
1	390.10	390.10

VALUE
1.11
8.05
271.15
30.60
32.20
484.55
463.45
99.60
6.75
390.10

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

91165600



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 54424
Date Estimated : 10/02/2020
Prepared By : Shukhaizi Bin Misbah

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP6553S	WBA3A16060NS37826	30/09/2014	316iA/4	0

DESCRIPTION	QTY	PRIC	VALUE
FRT SPRING STRUT ? ✓ BT	1	496.65	496.65
COMBINATION NUT M14X1.5 ? ✓ NEC	1	5.80	5.80
HEX NUT WITH FLANGE ? ✓ NEC	2	2.50	5.00
HEXAGON NUT WITH COLLAR ? ✓ NEC	2	2.35	4.70
ALLOY RIM 7Jx16 V-SPOKE 390	1	781.20	781.20
225/50 R17 94W BRIDGESTONE POTENZA	1	423.30	423.30
BONNET X R	1	1,281.20	1,281.20
FRT LH DOOR	1	1,273.85	1,273.85
FRT LH SIDE PANEL	1	702.65	702.65
LH REINFORCEMENT ENTRANCE ? X NN	1	383.85	383.85
FRT LH 2 SIDE PANEL BRACKET ? X NN	1	35.10	35.10
FRT LH 3 SIDE PANEL BRACKET ? ✓ NEC	1	35.10	35.10
LH LOWER FRT DOOR HINGE ? X NN	1	56.30	56.30
FRONT SHOCK ABSORBER ? X NN	1	54.55	54.55
FRT BUMPER TOP MOUNT ? X NN	1	380.00	380.00
FRT LH LOWER DEFORMATION ELEMENT ? X NN	1	86.85	86.85
LH SUPPORT FOGLAMP X NN	1	42.05	42.05
FRT BUMPER TRIM PRIMED (SRA) X NN	1	1,037.05	1,037.05
WASHER GASKET X NN	1	4.20	4.20
REAR BUMPER CARRIER (ECE) X NN	1	470.25	470.25
FRT BUMPER LOWER MOUNT X NN	1	134.45	134.45
FRT LH WHEEL HOUSING COVER CRU	1	117.15	117.15
LH SILL TRIM PRIMED CRU	1	324.10	324.10
LH HEADLIGHT (XENON) X NN	1	2,130.35	2,130.35

17.40 5.80 2pc = 5.00

Total Parts : 12,085.46

Steve (LKK) 00 - Not Authorised (Report)

Excess - \$ 750

P/P

Ry Bel spy

12/2/20, 12.30pm

5 days 8 days ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

31,705.70



Labour 1	11,841.00
Parts	12,085.46
Labour 2	0.00
Excess	0.00
Total GST @ 7%	1,674.85

Grand Total : 25,601.31

THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **