

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 54424**
Date Estimated : **10/02/2020**
Prepared By : **Shukhaizi Bin Misbah**

- ESTIMATE REPAIR FOR -

Kuah Ann Thye (Ke Antai)
14 Brompton Road

- ACCOUNT - 115

United Overseas Insurance Ltd
3 Anson Road #28-01 Springleaf Tower

Singapore 079909

Singapore 799894

| | | | | |
|-----------------|-----------------------|-------------------|----------------|----------|
| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
| SKP6553S | WBA3A16060NS37 | 30/09/2014 | 316iA/4 | 0 |

| DESCRIPTION | ACCOUNT: ORIGINAL PRICE | DISC. % | NETT |
|---|----------------------------|---------|----------|
| To replace front left door, front left fender, left side skirting and front left wheel housing cover etc including to make good front bonnet and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job. | 2,975.00 | 0 | 2,975.00 |
| To respray front left door, front left fender, left side skirting cover and front bonnet etc. | 3,811.00 | 0 | 3,811.00 |
| To replace front left tyre and wheel rim including balancing. | 94.00 | 0 | 94.00 |
| To check steering geometry and conduct wheel alignment according to BMW specification | 531.00 | 0 | 531.00 |
| To check electrical wiring systems at the front section for proper function including adjustments of headlights. | 150.00 | 0 | 150.00 |
| sundries | 150.00 | 0 | 150.00 |
| # To tow accident vehicle to PML workshop (by owner). | 100.00 | 0 | 100.00 |
| # To replace electromechanical power steering including to programming, initializing steering column adjustment and checks for proper function. | 885.00 | 0 | 885.00 |
| # To remove and install front undercarriage for insection and replace all damaged parts. | 1,332.50 | 0 | 1,332.50 |
| # To check steering geometry and conduct wheel alignment according to BMW specification (after replacement) | 531.00 | 0 | 531.00 |
| # To supply front left tyre (70%) | 179.39 | 0 | 179.39 |

| DESCRIPTION | UNIT PRICE | QTY | DISC. % | NETT |
|-----------------|------------|-----|---------|------|
| # | | | | |
| # EXPANDING NUT | 0.95 | 1 | 0 | 0.95 |
| # EXPANDING NUT | 2.10 | 2 | 0 | 4.20 |
| # | 0.71 | 1 | 0 | 0.71 |

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X




Final Report

| | | | | |
|------------------------------------|----------|---|---|----------|
| LH TENSION STRUT W/HYDRAULIC MOUNT | 271.15 | 1 | 0 | 271.15 |
| SPHERICAL COLLAR SCREW M12X1.25X45 | 8.05 | 4 | 0 | 32.20 |
| WHEEL HUB WITH BEARING FRT | 484.55 | 1 | 0 | 484.55 |
| FRT LH CARRIER | 463.45 | 1 | 0 | 463.45 |
| # SPRING PAD WITH GUARD TUBE TOP | 17.75 | 1 | 0 | 17.75 |
| FRT SWING SUPPORT | 99.60 | 1 | 0 | 99.60 |
| # FRT GUIDE SUPPORT | 239.00 | 1 | 0 | 239.00 |
| FRT SPRING STRUT | 496.65 | 1 | 0 | 496.65 |
| # PIPE CLAMP | 12.70 | 1 | 0 | 12.70 |
| # LH TIE ROD | 296.65 | 1 | 0 | 296.65 |
| # EXCH STEERING BOX ELECTR. (TKP) | 3,648.60 | 1 | 0 | 3,648.60 |
| COMBINATION NUT M14X1.5 | 5.80 | 3 | 0 | 17.40 |
| HEX NUT WITH FLANGE | 2.50 | 1 | 0 | 2.50 |
| HEX NUT WITH FLANGE | 2.50 | 1 | 0 | 2.50 |
| HEXAGON NUT WITH COLLAR | 2.35 | 2 | 0 | 4.70 |
| ALLOY RIM 7Jx16 V-SPOKE 390 | 781.20 | 1 | 0 | 781.20 |
| FRT LH DOOR | 1,273.85 | 1 | 0 | 1,273.85 |
| FRT LH SIDE PANEL | 702.65 | 1 | 0 | 702.65 |
| FRT LH 3 SIDE PANEL BRACKET | 35.10 | 1 | 0 | 35.10 |
| # FRT DOOR WEATHERSTRIP | 141.40 | 1 | 0 | 141.40 |
| FRT LH WHEEL HOUSING COVER | 117.15 | 1 | 0 | 117.15 |
| # SUPPORTING LEDGE LH | 18.95 | 1 | 0 | 18.95 |
| LH SILL TRIM PRIMED | 324.10 | 1 | 0 | 324.10 |

SUPPLEMENTARY ITEMS

| | |
|---------------------------------|-----------|
| Total Labour : | 10,738.89 |
| Total Parts : | 9,760.10 |
| Total Labour & Parts : | 20,498.99 |
| Deduction for Excess : | 750.00 |
| Total Repair Costs less Excess: | 19,748.99 |
| GST @7%: | 1,382.43 |
| Grand Total : | 21,131.42 |



Note : LIMIT AT \$16K.



ISLAND TOWING SERVICES

59 Ubi Avenue 1 #07-08 Bizlink Centre Singapore 408938
Telephone: 6747 7400 Email: admin@islandrecovery.com.sg
Facsimile: 6844 7233 Web: www.islandrecovery.com.sg
Co. Reg. 53269210A

Cash Sales/ Work Order

NO. 66107

Date: 10-02-2020

M/S: CASH

Vehicle No: SKP 6553 S Model: BMW 3

From: 14 Brompton Rd Time Start: 06:33

To: 303 Alexandra Rd Time End: 08:07

Remarks: _____

☐ Change Tyres / Jump Start

☐ Accident

☐ Use Car Carrier

☐ Basement / Multi Carpark

☐ Crane Up / Winch Out

☐ Open Door

☒ Using King Dolly

☐ Dismantle Shaft / Brake

☐ Loaded

AMOUNT S\$ 100.00

Received By

Island Towing Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.