



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO :
ATTN : MOTOR CLAIM DEPT.

ESTIMATE REPORT 1st QUOTATION
OWNER'S PARTICULAR

NAME : LENG KIN NYUK
ADDRESS :
LICENSE NO. : SCU100Z
MAKE / MODEL : MERCEDES C180
OWNER'S INSURER : FWD INSURANCE
JOB-CODE : TP S/A : JOEY

JOB NO. : _____

CONTACT : 91146846

CHASSIS NO. : _____

ENGINE NO. : _____

ACCIDENT DATE : 10-Feb-20

CLAIM DETAIL

MATERIALS

		QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR. DISP	REV. PRICE
1	FRONT SUPPORT PANEL 650	Oil 1.00	872.00	10.00	784.80	Y	? ✓
2	FRONT GRILLEL LOGO	Sn 1.00	138.00	10.00	124.20	Y	X
3	FRONT SHOCK ABSORBER TOP MOUNTING LH	Sn 1.00	378.00	10.00	340.20	Y	X
4	FRONT SHOCK ABSORBER LH	Sn 1.00	768.00	10.00	691.20	Y	X
5	FRONT LOWER ARM LH	Sn 1.00	652.00	10.00	586.80	Y	X
6	FRONT STAY ARM LH	Sn 1.00	620.00	10.00	558.00	Y	X
7	FRONT KUNCKLE ARM LH 783.60	Bj 1.00	1151.00	10.00	1035.90	Y	✓
8	FRONT KNUCKLE ARM BEARING LH 420	Sn 1.00	685.00	10.00	616.50	Y	✓
9	FRONT KNUCKLE SUPPORT ARM LH	Sn 1.00	885.00	10.00	796.50	Y	X
10	FRONT SPORT RIM RH 1021.00	Oil/Sn 1.00	1530.00	10.00	1377.00	Y	✓
11	FRONT TYRE RH	Sn 1.00	480.00	10.00	432.00	Y	X
12	FRONT FENDER RH 1028.60	Bj 1.00	1100.00	10.00	990.00	Y	✓
13	FRONT FENDER TOP GARNISH LH	mycm 1.00	45.00	10.00	40.50	Y	✓
14	FRONT FENDER INNER FRONT SHIELD RH 184	cm 1.00	308.00	10.00	277.20	Y	✓
15	FRONT FENDER INNER REAR SHIELD RH	Sn 1.00	320.00	10.00	288.00	Y	X
16	FRONT FENDER SHIELD CLIPS 1 SET	Sn 1.00	50.00	10.00	45.00	Y	✓
17	RADIATOR GRILLE ASSY 649	mycm 1.00	1105.00	10.00	994.50	Y	2 ✓
18	HEADLAMP SIDE RUBBER RH	Sn 1.00	350.00	10.00	315.00	Y	X
19	HEADLAMP PANEL SIDE RH	R 1.00	236.00	10.00	212.40	Y	X
20	HEADLAMP ASSY LED RH 2579	cm 1.00	2988.00	10.00	2689.20	Y	✓
21	SUPPORT HEADLAMP LOWER BRACKET RH 310	Bj 1.00	580.00	10.00	522.00	Y	✓

22	LOGO MERCEDES	me	1.00	85.00	10.00	76.50	Y	✓
23	FRONT BUMPER	cm	1.00	1392.00	10.00	1252.80	Y	✓
24	FRONT BUMPER SENSOR PCS	Sen	1.00	1548.00	10.00	1393.20	Y	✓ 258
25	FRONT BUMPER CHROME MOULDING RH 210	Sen	1.00	254.00	10.00	228.60	Y	✓
26	FRONT BUMPER LOWER GRILLE	Sen	1.00	160.00	10.00	144.00	Y	X
27	FRONT BUMPER FOG LAMP LED RH	Sen	1.00	285.00	10.00	256.50	Y	X
28	FRONT BUMPER FOG LAMP COVER RH	Sen	1.00	70.00	10.00	63.00	Y	✓
29	FRONT BUMPER FOG LAMP BULB ISET	Sen	1.00	120.00	10.00	108.00	Y	X
30	FRONT BUMPER COVER 326 mtg cracked	Sen	1.00	658.00	10.00	592.20	Y	✓
31	FRONT BUMPER COVER SCREW & NUT ISET	me	1.00	180.00	10.00	162.00	Y	✓
32	FRONT BUMPER SPONGE CENTRE	Sen	1.00	178.00	10.00	160.20	Y	X
33	FRONT BUMPER SPONGE SIDE RH	Sen	1.00	104.00	10.00	93.60	Y	X
34	FRONT BUMPER REINFORCEMENT PLASTIC PROTECTION	Sen	1.00	175.00	10.00	157.50	Y	X
35	FRONT BUMPER INNER PLASTIC CENTRE	Sen	1.00	165.00	10.00	148.50	Y	X
36	FRONT BUMPER INNER PLASTIC SIDE RH	Sen	1.00	134.00	10.00	120.60	Y	X
37	FRONT BUMPER REINFORCEMENT	Sen	1.00	487.00	10.00	438.30	Y	X
38	FRONT BUMPER REINFORCEMENT BRACKET RH	Sen	1.00	262.00	10.00	235.80	Y	X
39	FRONT BUMPER SIDE BRACKET RH	Sen	1.00	98.00	10.00	88.20	Y	X
40	FRONT BUMPER SENSOR WIRE HARDNESS	Sen	1.00	334.00	10.00	300.60	Y	X
41	FRONT BUMPER SIDE RETAINER RH	Sen	1.00	36.00	10.00	32.40	Y	X
42	FRONT BUMPER SIDE RETAINER LH	Sen	1.00	36.00	10.00	32.40	Y	✓
43	RADIATOR	Sen	1.00	890.00	10.00	801.00	Y	X
44	AIRCON CONDENSOR	Sen	1.00	1150.00	10.00	1035.00	Y	X
45	AIRCON FAN WITH COWLING	Sen	1.00	468.00	10.00	421.20	Y	X
TOTAL (PARTS):				23500.00		21150.00		

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA		1.00	1200.00	0.00	1200.00	Y	650/
2	SPRAY PAINTING ON AFFECTED AREA		1.00	1200.00	0.00	1200.00	Y	750/
3	RESPRAY TUFF KOTE ON AFFECTED AREA	nn	1.00	120.00	0.00	120.00	Y	X
4	R&R FRONT SUSPENSION ASSY		1.00	480.00	0.00	480.00	Y	60/
5	R&R CONDENSOR & TOP UP GAS	nn	1.00	180.00	0.00	180.00	Y	X

REF:

AIG / 2000 6100 / Ke

6	R&R RADIATOR SYS & PRESSURE TEST	nn 1.00	120.00	0.00	120.00	Y	X
7	CHECK & REPAIR WIRING SYS	1.00	120.00	0.00	120.00	Y	20%
8	CONDUCT FULL WHEEL ALIGNMENT	1.00	120.00	0.00	120.00	Y	60%
TOTAL (LABOUR):			3540.00		3540.00		
TOTAL PARTS & LABOUR			27040.00		24690.00		

EXCESS: : \$S _____

NO. OF DAY : 05

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : \$S _____

DATE OF SURVEY : ____/____/____

SURVEY BY : _____

CONTACT N: _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: