

BW WORKSHOP SERVICES PTE. LTD.
291 KAKI BUKIT AVE 1, SHUN LI INDUSTRIAL PARK
SINGAPORE 416080
TEL: 6745 8800 FAX: 6741 4140
GST REG NO : 201504834E

Finalize Estimate

To : CHINA TAIPING INSURANCE DATE : 17/3/2020
Att : _____ VEHICLE NO : SMR 1419 X

Third Party Claims

Page 1 / 2

S/NO	ITEMS	Qty	Parts Amount	List -25%
1	REAR TAILGATE	1	\$ 1,860.00	\$ 1,395.00
2	REAR TAILGATE LOCK	1	\$ 850.00	\$ 637.50
3	REAR TAILGATE TRIM OUTER CHROME (1SET)	1	\$ 640.00	\$ 480.00
4	LOGO "ESQUIRE"	1	\$ 75.00	\$ 56.25
5	LOGO "HYBRID"	1	\$ 65.00	\$ 48.75
6	REAR BUMPER	1	\$ 1,970.00	\$ 1,477.50
7	REAR BUMPER SIDE RETAINER - LH	1	\$ 170.00	\$ 127.50
8	REAR BUMPER SIDE SUPPORT BRACKET - LH & RH @ \$175.00	2	\$ 350.00	\$ 262.50
9	REAR BUMPER TOWING CAP	1	\$ 45.00	\$ 33.75
10	REAR BUMPER REVERSE SENSOR (1SET)	1	\$ 450.00	\$ 337.50
11	SIDE BUMPER - LH	1	\$ 390.00	\$ 292.50
12	SIDE BUMPER REVERSE SENSOR - LH	1	\$ 380.00	\$ 285.00
13	REAR END PANEL	1	\$ 810.00	\$ 607.50
14	TAILLAMP PANEL - LH	1	\$ 360.00	\$ 270.00
15	REAR END PANEL INNER GARNISH	1	\$ 190.00	\$ 142.50
16	REAR CARGO COMPARTMENT BOX - CENTER	1	\$ 490.00	\$ 367.50
17	REAR SPARE TYRE BOX - CENTER	1	\$ 410.00	\$ 307.50
18	REAR TAILGATE INNER GARNISH	1	\$ 590.00	\$ 442.50
19	REAR FENDER - LH	1	\$ 1,400.00	\$ 1,050.00
20	REAR FENDER INNER GARNISH - LH	1	\$ 790.00	\$ 592.50
21	REAR FENDER SLIDE DOOR CENTER RAIL COVER - LH	1	\$ 450.00	\$ 337.50
22	REAR FENDER LAMP - LH	1	\$ 670.00	\$ 502.50
			Total :	\$ 10,053.75

BW WORKSHOP SERVICES PTE. LTD.

291 KAKI BUKIT AVE 1
SHUN LI INDUSTRIAL PARK
SINGAPORE 416080
TEL: 6745 8800 FAX: 6741 4140
GST REG NO : 201504834E

Finalize Estimate

To : CHINA TAIPING INSURANCE DATE : 17/3/2020
Att : _____ VEHICLE NO : SMR 1419 X

Third Party Claims

Page 2 / 2

S/NO	S/N ITEMS	Qty		Amount
23	REAR WINDSCREEN MOULDING	1		\$ 85.00
24	SEALANT	2		\$ 90.00
25	REAR BUMPER CLIPS @ \$5.50	10		\$ 55.00
26	RIVET @ \$1.50	10		\$ 15.00
			Total :	\$ 245.00
S/NO	LABOUR			Amount
27	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGH, REFIT AND TO RENEW AFFECTED PARTS.			\$ 1,400.00
28	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.			\$ 1,200.00
29	TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.			\$ 30.00
30	TO REMOVE AND REFIT REAR WINDSCREEN.			\$ 120.00
31	TO REMOVE AND REFIT REAR FENDER GLASS - LH.			\$ 80.00
32	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.			\$ 120.00
33	TO APPLY UNDERSEALING.			\$ 80.00
34	TO CHECK AND RELIGNMENT CHASSIS MEMBER.			\$ 120.00
35	TO TRANSFER TAILGATE'S FITTINGS.			\$ 60.00
36	TO REMOVE AND REFIT REVERSE SENSOR.			\$ 40.00
37	TO REMOVE AND REFIT PETROL TANK IN ORDER TO FACILITATE REPAIRING WORKS.			\$ 60.00
38	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY FLATBED TOWING.			\$ 120.00
39	TO RE-PROGRAM THE REVERSE SENSOR			\$ 250.00
			Total :	\$ 3,680.00
	COST OF REPAIR : \$ 10,053.75			
	S/N ITEM : \$ 245.00			
	LABOUR : \$ 3,680.00			
	\$ 13,978.75			
	Final Amount : \$13,978.75 - 20 Days (Before GST)			